Submit 3 Copies To Appropriate District Office	State of New Mexico				Form C-103 Revised March 25, 1999	
District I 1625 N. French Dr., Hobbs, NM 88240				WELL API NO.		
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION			30-025-04534 5. Indicate Type	e of Lease	
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr. Santa Fe, NM 87505			STATE	X FEE 🗌	
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil &	Gas Lease No.				
SUNDRY NOT	7. Lease Name	or Unit Agreement Name:				
(DO NOT USE THIS FORM FOR PROPO DIFFERENT RESERVOIR. USE "APPL	H. T. Orcutt (NC	<u>ንፐ ር) Com "ለ"</u>				
PROPOSALS.) 1. Type of Well:		JI-C) COIII A				
Oil Well Gas Well X Other						
2. Name of Operator Chev	8. Well No. 3					
3. Address of Operator	9. Pool name o	or Wildcat				
P. O. 4. Well Location	Eumont; Yates-7	Rivers-Queen				
Unit Letter G : 1980 fo	eet from the North line and	d 1980 feet	t from the East lin	e		
Section 6			Range 36E	NMPM	County LEA	
	10. Elevation (Show 1 3562' GR	whether Di	R, RKB, RT, GR, e	etc.)		
11. Check	Appropriate Box to Ir	ndicate N	ature of Notice	, Report or Other	r Data	
NOTICE OF INTENTION TO: SUB				BSEQUENT RE		
	PLUG AND ABANDON	1 🗌	REMEDIAL WO	RK 🗌	ALTERING CASING	
	CHANGE PLANS		COMMENCE DI	RILLING OPNS.	PLUG AND X	
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST		ABANDONMENT	
OTHER:			OTHER:			
<ol> <li>Describe proposed or complete starting any proposed work). S recompilation.</li> <li>This well is part of the New plugging and abandonmen</li> </ol>	SEE RULE 1103. For Mu v Mexico "P&A Pilot l	ltiple Com Project" (	pletions: Attach v conducted by B	vellbore diagram of enterra Corporat	proposed completion or ion to demonstrate the	
Tagged btm @ 3256'						
Bottom Plug @ 3146' – 3256' 16 cu ft ZONITE 7				Tagged		
Rustler/7 5/8" Shoe Plug @ 1001' - 1180' 24 cu ft ZONITE 1				Tagged	C C 1/1) C11 1 /	
10 ¼" Shoe/FW/Top Plug @ 7' - 353'         140 sx Class C cmt         1           ZONITE Cap to 7'         1 cu ft ZONITE         1				10 5/4 x / Circ to	surf, 5 1/2" filled w/ cmt	
Set marker. Chevron to clean locate Plugging operations began 10/24/01		'02. Wellb	ore diagram attacl	ned.		
I hereby certify that the information	above is true and comple	te to the be	est of my knowled	ge and helief		
SIGNATURE JK. Riplan	I be Para		egulatory OA	-	TE 4/30/02	
Type or print nameJ.K. Ripley(This space for State use)	/			Iele	phone No.(915)687-7148	
APPPROVED BY		TITLE			DATE JUL 1 1 200	
V	GWW					

2
Ċ
S

# **BENTENNA** Corporation

**Mid-Continent Region** 

#### Final P&A Schematic





6

OPERATOR		DATE					
Chevron U.S.A. Production Company			See Below				
LEASE & WELL NUMBER			COUNTY & STATE				
H. T. Orcutt (NCT-C) Com A #3			Lea, New Mexico				
FIELD				FORMATION			
Eumont				Queen – Penrose			
TD P	PBD	RKB	PERFS				
3862' 3	655'	5'	3353' – 3624' overall				
SURFACE IN	NTERMEDIATE	PRODUCTION	СІВР ДЕРТН				
10¾" @ 303'	75/8" @ 1118'	5½" @ 3750'	3690' w/ 35' cement cap				
OPERATOR CHARGE CODE			BENTERRA CHARGE CODE				
UWPWBA0012ABN			NWNMR-00101-010				
This well is part of the New Mexico "P&A Pilot Project" conducted by Benterra Corporation to demonstrate the plugging and abandonment process using highly compressed sodium bentonite nodules as the plugging medium. Note: Chevron fished & cleaned out tbg & rods to 3364' = 11' below top perf. Discussed w/ Buddy Hill w/ NMOCD prior to Benterra MIRU & he approved plugging from 3364'.							
10/24/01							
MIRU Benterra Unit #4. SIP = static. Remove WH & install WCV. WIH w/ 3½" FLT, tagged btm @ 3256' = 108' above Chevron reported cleanout depth. FL @ 320'. Called Buddy Hill w/ NMOCD & he approved plugging from 3256'. Poured 8 cu ft ZONITE, wait and tag @ 3207'. Poured 8 cu ft ZONITE, wait & tag @ 3146'. Bottom plug set from 3146' – 3256' (110') w/ 16 cu ft ZONITE as of 5:30 PM 10/25/01. SDON.							
10/25/01							
SIP = static. WIH w/ SB & tagged top of plug @ 3146', OK. FL @ 300'. Removed WCV, installed WH & closed well in. RD Benterra.							
10/29/01							
MIRU Benterra Unit #4. SIP = static. Remove WH. WIH w/ SB & tagged top of plug @ 3147', OK. Pushed 5½" wiper rubber to 1180'. Poured 24 cu ft ZONITE, wait & tag @ 1001'. FL @ 285'. <u>T/Salt -</u> <u>Rustler – 75/8" csg shoe plug set from 1001' – 1180' (179') w/ 24 cu ft ZONITE as of 3:30 PM 10/29/01.</u> Installed WH & SWI. RD Benterra.							
11/16/01							
MIRU Benterra Unit #4. SIP = static. Removed WH. Made trip w/ SB & tag @ 1000', OK. FL @ 260' Installed WH & RD Benterra							
12/10/01							
SIP = static.							
12/19/01							
SIP = static.							

## H. T. Orcutt (NCT-C) Com A #3

### 1/4/02

SIP = static. Removed WH. Made trip with SB & tag plug at 1000', OK. Install WH & load hole with 6 bbl freshwater, indicated FL is approximately 250' FS. SWI & RD.

#### 1/9/02

SIP = static.

#### 1/21/02

RU Key pump truck. 5<sup>1</sup>/<sub>2</sub>" csg loaded immediately - press from surface to 1000' (T/Salt - Rustler plug) to 200 psi, held ok.

#### 1/23/02

RU Key WL truck and mast. RU Key pump and vacuum trucks. WIH w/ 4" OD gun and shot 5½" csg at 353' w/ 4 - .42" JS at 120° phasing. Well stable. RD Key WL. Install WH & circ down 5 ½" csg and out 10¾" x 75/8" annulus with 50 bbl freshwater, wellbore circ clean. SWI & RD Key trucks.

#### 1/29/02

SIP = Static. MIRU Schlumberger & Key water truck. Pumped 10 bbl freshwater down  $5\frac{1}{2}$ " csg, through perfs at 353' and established circ out  $10\frac{3}{4}$ " x 75/8" annulus. Mix and pumped approximately <u>140 sx Class</u> <u>C cmt @ 14.8 ppg, circ approx 15 sx good cmt to pit from  $10\frac{3}{4}$ " x 75/8" annulus.</u> Closed in wellbore and annulus. Left  $5\frac{1}{2}$ " csg full of cmt. RD Schlumberger & Key. <u>10<sup>3</sup>{4}"</sup> Shoe / fresh water / top plug in place as of 1:05 PM 1/29/02.</u>

#### 1/31/02

MIRU Benterra #4. SIP = Static. Removed WH, tag TOC at 7' below GL. <u>Filled 51/2" csg to surface with</u> <u>ZONITE</u>. RD.

2/4/02

Monitor well - no problems.

2/14/02

Check location - no problems.

3/14/02

Check location - no problems.

3/18/02

Check location - add water to top of ZONITE cap, no bubbling. Annuli risers full of cement.

4/2/02

Key Energy Services dug out cellar and cut-off csg & WH to 4' below GL. Welded on cap with ½" brass valve and installed dry hole marker. Dug out & cut off guywire anchors to 4' below GL. Backfilled all excavations. Turned over to ChevronTexaco for location cleanup and NMOCD inspection. Final Report.