BENTERRA Corporation Mid-Continent Region

P&A PROCEDURE



WELL NAME:	H. T. Orcutt (NCT-C) Com A #3
API NUMBER	30-025-04534
COORDINATES:	1980' FNL & 1980' FEL Unit G
SEC/TWN/RNG:	6 - 21S - 36E
COUNTY/STATE	Lea, NM
DRILLED	1936

OPERATOR:	Chevron
FIELD:	Eumont
DATE:	7/31/01
BY:	DCD

Provide 24 hr Notification to NMOCD of Pending Operations

- 1. Hold pre-job safety mtg and spot equipment. Check 51/2" csg and all annuli for pressure.
- 2. ND WH equip and install well control equip.
- 3. Make trip w/ GR on slickline and check PBD @ 3655'. Record FL. Displace wellbore fluids with freshwater.
- 4. Insert 51/2" wiper plug (cored to allow fluid bypass) into csg and push to 3300' w/ slickline.
- 5. Surface pour 14 cu ft of ZONITE to set 100' btm plug from approx 3200 3300'. Set plug in stages, check w/ SL to assure bridges are not occurring and required plug height is achieved. Pour at rate that minimizes potential to bridge. After setting plug, add water as necessary to assure hydration of plug.
- 6. Push cored 51/2" wiper plug to 1200' w/ slickline. Set 132' (17 cu ft) ZONITE plug from 1068' 1200' across top of salt and extending 50' above 75/8" shoe. Use precautions as in Step 5, add water if necessary to hydrate plug.
- 7. Push cored 51/2" wiper plug to 353' w/ slickline. Set 100' (14 cu ft) ZONITE plug from 253 353' across 103/4" shoe. Add water if necessary to hydrate plug.
- 8. Push cored 51/2" wiper plug to 30' w/ slickline. Fill csg w/ ZONITE to 3' below GL (4 cu ft).
- 9. Remove well control equip, secure WH and RD equip.
- 10. Allow 48 hours for ZONITE to hydrate, remove WH, cut off casings 3' below GL and cap wellbore.
- 11. Install dry hole marker stamped w/ required well identification, 4" OD x 4' above the GL.
- 12. Remove all equip and cut deadmen below GL.
- 13. Turn over to Chevron for any surface remediation work.

WELL PLANNING SHEET Existing Configuration



WELL PLANNING SHEET Proposed P&A

