Form 3160-3

(December 1990)

SUBMIT IN TRIPLICATE

BUREAU OF LAND MANA CONS. NM 88240

FORM APPROVED

Budget Bureau No. 1004-0136

Expires: December 31, 1991

APPLICATION FOR PERMIT TO DRILL OR DEEPEN	6. If Indian, Alottee or Tribe Name	
a. Type of Work DRILL DEEPEN V	 6. If Indian, Alottee or Tribe Name 7. If Unit or CA, Agreement Designation 8. Well Name and Number EUNICE MONUMENT SOUTH UNIT 	
b. Type of Well		
IL GAS FELL OTHER MULTIPLE ZONE MULTIPLE ZONE		
Name of Operator CHEVRON USA INC	284	
Address and Telephone No. 15 SMITH ROAD, MIDLAND, TX 79705 915-687-737	9. API Well No. 30-025-04561	
Location of Well (Report location clearly and in accordance with any State requirements.*) t Surface nit Letter C : 660' Feet From The NORTH Line and 1980' Feet From The WEST Line t proposed prod. zone	10. Field and Pool, Exploaratory Area EUNICE MONUMENT GRAYBURG S/A 11. SEC., T., R., M., or BLK. and Survey or Area	
SAME	Sec. 8, Township 21-S, Range 36-I	
Distance In Miles and Direction from Nearest Town or Post Office*	12. County or Parish 13. State LEA NM	
b. Cistance From Proposed* Location to Nearest Property or 16. No. of Acres in Lease ease Line, Ft. (also to nearest drig, unit line, if any) 16. No. of Acres in Lease	17. No. of Acres Assigned To This Well	
B. Distance fFrom Proposed Location* to Nearest Well, Drilling, 19. Proposed Depth ompleted or Applied For, On This Lease, Ft. 4050'	20. Rotary or Cable Tocis ROTARY	
Elevations (Show whether DF RT, GR, etc.)	22. Approx. Date Work Will Start*	
	3/1/2003	
D CHANGE		

CHEVRON U.S.A. INTENDS TO DEEPEN, UNDER REAM, AND ACIDIZE THE SUBJECT PRODUCING WELL. THE INTENDED PROCEDURE AND WELL BORE DIAGRAM IS ATTACHED FOR YOUR APPROVAL.



DeSolo/Nichois 12-93 ver 1.0

M

In Above Space Describe Proposed Program: If proposal is to deepen, give data on present productive zone and proposed new productive zone. If proposal is to drill or deepen directionally, give pertinent data on subsurface locations and measured true verticle depths. Give blowout preventer program, if any.

24 Thereby certify that the foldspoing is the	sel rake		Regulatory Specialist	DATE	2/17/2003
TYPE OR PRINT NAME	Denise Leake	e			
(This space for Federal or State office use)				
PERMIT NO	DRIGINAL SIGN	ED BY	APPROVAL DATE		
Application approval does not warr	ant or certify that Are appleant for	ega or equitable	title to those rights in the subject lease which would	d entitle the applicant to conduct oper	ations thereon.
APPROVED	PETROLEUM EN				
CONDITIONS OF APPROVAL, IF ANY:					
Title 18 U.S.C. Section 1001, make representations as to any matter w	es it a crime for any person knowing	y and wilfully to ma	ake to any department or agency of the United Stat	— — — · · · · · · · · · · · · · · · · ·	

EMSU #284 660' FNL & 1980' FWL, 8-21S-36E Lea County, New Mexico 30-025-04561 FA5702

Deepen, under ream, and acidize producing well

- 1. Verify anchors have been set & tested. Test flowline as per below procedure.
- 2. Rig up pulling unit. ND wellhead. NU BOP.
- 3. TOH with rods and pump. Visually inspect for scale, paraffin, and wear. Scanalog production tubing out of hole.
- 4. TIH with 4-1/2" casing scraper on 2-7/8" workstring. Make scraper run to the casing shoe at 3890'. TOH with scraper.
- 5. Rig up Weatherford reverse unit. TIH with 3-3/4" bit with 6 3-1/8" drill collars on 2-7/8" workstring. Clean well out to TD at 3984. Drill new formation to 4050". TOH with bit and collars.
- 6. TIH with 3-5.'8'' X 6'' under-reamer with 6 3-1/8'' drill collars on 2-7/8'' workstring. Underream Grayburg 3-3/4'' open hole section to 6'' from 3890' – 4050' (160' total), changing reamers as required. Rig down Weatherford.
- 7. TIH with 4-1/2" treating packer on 2-7/8" workstring. Run packer at 3750°. Rig up DS. Pickle tubing with 200 gals 15% HCL. Circ clean and set packer. Acidize perfs and open hole with 5000 gals 15% 50% foamed acid in three stages with 2% KCL water between stages as per DS procedure. Swab back load monitor fluid level, rate, and cut. Trip out with packer.
- 8. TIH with production tubing with tubing anchor. Set tubing anchor at +/- 3740'. Set seating nipple below casing shoe, in open hole, at 4000'. Run pump and rods.
- 9. ND BOP. NU wellhead. Return well to production. Rig down pulling unit.

Displace flowline with fresh water. Have field specialist close valve at header. Pressure line according to the type of line. AGU, EMSU, and EMSUB buried fiberglass lines will be tested with 300 PSI. All polypipe (SDR7 and SDR11) will be tested w/100 PSI. All steel lines will be tested w/500 PSI. If a leak is found, contact Larry Williams for repair/replacement. If test is good, bleed off pressure and **open valve** at header. Document this process in the morning report.

Kevin Hickey 915-687-7260





WELL DATA SHEET

