

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 37501

Form C-103
Revised 10-1-77

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐	GAS WELL ☐	OTHER ☐	5a. Indicate Type of Lease State ☐ Fee ☒
Name of Operator AMOCO PRODUCTION COMPANY			5. State Oil & Gas Lease No.
Address of Operator P. O. Box 68, Hobbs, NM 88240			7. Unit Agreement Name
Location of Well UNIT LETTER <u>A</u> <u>660</u> FEET FROM THE <u>Merch South</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>11</u> TOWNSHIP <u>21-S</u> RANGE <u>36-E</u> NMPM.			8. Farm or Lease Name McQuatters
			9. Well No. 1
			10. Field and Pool, or wildcat Eumont Queen
11. Elevation (Show whether DF, RT, GR, etc.) 3541' GL			12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☒ Cmt squeeze Eumont and turn wellbore over to Chevron.

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MI and RUSU 1-20-87. Kill well with 35 BLW. POH with production equipment. RIH with Howco 7" cement retainer and set at 3262. Squeeze with 100 sx class C, 3/10% of Halad 4 and 100 sx 4# sx Tuff plug and 56 sx class C. Max squeeze pressure 1000#. Reverse out 65 sx. Pull tubing and RIH 6-1/4" bit, 8-1/4" drill collars. Tag cement at 3258. Drill out cement and cement retainer to 3430. Circ. clean. Pressure test to 550#. and OK. Pull out to 3500 and circulate clean. Drill out to 3550. Fell out of cement and lower bit to 3630. Circ clean and test to 700#. Drill out cement from 3634 to 3634. Drill out CIBP to 3643. Circulate to 3832. Tag fill and fill to 3848. Drill out new hole to 3852 and circulate clean. RD and MOSU. Turn wellbore over to Chevron.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

S. Brownlee

TITLE Administrative Analyst

DATE 2-11-87

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

COPIES OF APPROVAL, IF ANY:

TITLE

DATE

2-11-87