Submit 3 Copies To Appropriate District Office District I	State of E zv. Minerals		exico aral Resources		Form C- Revised March 25,	
1625 N. French Dr., Hobbs, NM 88240	LL API NO.		1999			
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERV	ATION	DIVISION	30-025-04741		
District III 1000 Rio Brazos Rd., Aztec, NM 87410	5. Indicate Type STATE	of Lease				
District IV		Gas Lease No.				
1220 S. St. Francis Dr., Santa Fe, NM 87505						
(DO NOT USE THIS FORM FOR PROPO DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.) 1. Type of Well:	CES AND REPORTS OF SALS TO DRILL OR TO DEED CATION FOR PERMIT" (FOR ther	PEN OR PL	UG BACK TO A	7. Lease Name o Arnott Ramsay (1	or Unit Agreement Na NCT-C)	me:
2. Name of Operator				8. Well No. 8		
Chevr	on U.S.A. Inc			o, wenno, o		
3. Address of Operator	Box 1150 Midland TV	70702		9. Pool name of Eumont; Yates-7F		
4. Well Location	P. O. Box 1150, Midland, TX 79702 4. Well Location					
Unit Letter O: 660 feet f	rom the South line and 19	80 feet fr	om the Fast line			
Section 21			Range 36E		O	
	10. Elevation (Show w		R, RKB, RT, GR. etc.	NMPM	County LEA	
11 Ch. 1 A	3585' GR			í l		
NOTICE OF IN	ppropriate Box to Ind	dicate N				
	PLUG AND ABANDON	П	SUBS REMEDIAL WORK		PORT OF: ALTERING CASING	· 🗖
	CHANGE PLANS				ALI LINING CASING	' []
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AN CEMENT JOB	D 🗌	ABANDONMENT	
OTHER:			OTHER:			
 12. Describe proposed or completed starting any proposed work). SE recompilation. This well is part of the New plugging and abandonment 	Mexico "P&A Pilot P	iple Comp	onducted by Ren	lbore diagram of p	roposed completion of	or Ale
Tagged CIBP @ 3692'						
Zonite Plugs: Bottom Plug 3588' - 36 B/Salt Plug 2781' - 28 Rustler Plug 1346' - 15 Shoe (Zonite Section) 290' - 3	4 cu ft. Zonite30 cu ft. Zonite	ר ז	Fagged Fagged Fagged Fagged			
Cavity Shot @ 266' - 276'						
Cement Plug: Surf/ Shoe Plug 8' – 266'	245 sx Class C cer	ment (Circulated			
Surface topped with 1 cu ft Zonit		-				
Set marker. Chevron to clean loc Plugging operations began 9/7/01	ation. and were completed on 3	3/27/02. V	Vellbore diagram att	ached		
I hereby certify that the information a						
SIGNATURE I.K. Ripley	1 1 1		gulatory OA		4/22/02	
Type or print name J.K. Ripley	Shoafb				none No.(915)687-71	48
(This space for State use)			\sim 1			
APPPROVED BY Conditions of approval, if any:	the TI	TLE 🟒	ld kep	1	DATE <u>7-30-</u>	<u>o</u> z_
GWW						

Final P&A Schematic





Chevron U.S.A. Production Company See Below LEASE & WELL NUMBER COUNTY & STATE Arnott Ramsay C #8 Lea, New Mexico FIELD FORMATION Eumont Queen TD 9BD RKB 3880' 3635' 6.5' OH 3777-3880 TD SurrAce INTERMEDIATE PRODUCTION CIBP DEPTH 10 3/4*@276' 7 5/8*@1525' 51/2* @ 3777' 3700' DPERATOR CHARGE CODE BENTERRA CHARGE CODE WBS No. UWPWBA1004ABN NWNR-00101-001 This well is part of the New Mexico "P&A Pilot Project" conducted by Benterra Corporation to demonstrate the plugging medium. 9/7/84* MI Benterra Unit #4. Held pre-job safety meeting. Casing valve had been left open and there was no pressure on well. Removed WH equip and installed well control valve. Wel standing full w' water. WIH w' 3 ½* sinker bar, stopped at 265' and worked to 280'. Bar had signs of paraffin. POH and ran 2* sinker bar, and made aware of problem. (Note: discussed problem with Nathan Mouser w/ Chevron and he said he would probably try to cut parafin with a swab unit.) Chevron cleaned out wellbore (circ out polymer squeeze material from previous workover) & circ w/ freshwater. 16/3/201 MIRU Benterra Unit #4. No press on well. Remove WH & WIH w/ SB & tagged bim @ 3692'. Started in hole w/ 5 ½* wiper rubber - reviewed	OPERATOR				DATE	
LEASE & WELL NUMBER COUNTY & STATE Arnott Ramsay C #8 Lea, New Mexico FIELD FORMATION Eumont Queen TD PBD RKB PERFS 0H 3777-3880 TD OH 3777-3880 TD SURFACE INTERMEDIATE PRODUCTION CIBP DEPTH 10.3/4"@276' 7 5/8"@1525' 51/2" @ 3777' 3700' OPERATOR CHARGE CODE BENTERRA CHARGE CODE WWMR-00101-001 This well Is part of the New Mexico "P&A Pilot Project" conducted by Benterra Corporation to demonstrate the plugging and abandonment process using highly compressed sodium bentonite nodules as the plugging medium. 9/7/04 WI Benterra Unit #4. Held pre-job safety meeting. Casing valve had been left open and there was no pressure on well. Removed WH equip and installed well control valve. Well standing full will water. WIH w/ 3 ½" sinker bar, stopped at 260' and worked to 280'. Bar had signs of parafin. POH and ran 2" sinker bar, unable to work past 280''. POH will W, removed well control valve and installed WH equip. Left well SI. Took Unit #4 to yard for reloading ZONITE and SD for weekend. EL_GONZEW will WHOD Water. Will W 3 3/4" sinker bar, stopped at 260' and worked to 280''. Bar had signs of parafin. POH and ran 2" sinker bar. 103/01 Took Unit #4. No press on well. Remove WH & WIH w/ SB & tagged btm @ 3692''. Started in hole wf 5 ½" wiper rubber - reviewed well files w/ Chevron & determined that CIBP was probably never capped w/ cement - decided to push WR						
Arnott Ramsay C #8 Leâ, New Mexico FIELD FORMATION Eumont Queen TD PBD RKB PERFS 01347@276' 7 5/8*@1525' 6.5' OH 3777-3880 TD SURFACE INTERMEDIATE PRODUCTION CIBP DEPTH 10.3/4*@276' 7 5/8*@1525' 51/2*@ 3777' 3700' OPERATOR CHARGE CODE WBS No. UWPWBA1004ABN NVMR-00101-001 This well is part of the New Mexico "P&A Pilot Project" conducted by Benterra Corporation to demonstrate the plugging and abandonment process using highly compressed sodium bentonite nodules as the plugging medium. 9/7/01 9/7/01 MI Benterra Unit #4. Held pre-job safety meeting. Casing valve had been left open and there was no pressure on well. Removed WH equip and installed well control valve. Well standing full will water. WIH w/ 3 ½' sinker bar, stopped at 265' and worked to 280'. Bar had signs of parafin. POH and ran 2* sinker bar, unable to work past 280'. POH will WL, removed well control valve. Mell Standing full. Not UWPW MA10017E and SD for weekend. Or well. Removed WH equip and installed well control valve. Well standing full. Or well. Removed WH equip and installed well control valve. Well standing full.						
FIELD FORMATION Eumont Queen TD PBD RKB PERFS 3880' 3635' 6.5' OH 3777-3880 TD SURFACE INTERMEDIATE PRODUCTION CIBP DEPTH 10 3/4"@276' 7.5/8"@1525' 51/2" @ 377' 3700' OPERATOR CHARGE CODE BENTERRA CHARGE CODE WWNMR-00101-001 WBS No. UWPWBA1004ABN NWNMR-00101-001 This well is part of the New Mexico "P&A Pilot Project" conducted by Benterra Corporation to demonstrate the plugging and abandonment process using highly compressed sodium bentonite nodules as the plugging medium. 9///04 MI Benterra Unit #4. Held pre-job safety meeting. Casing valve had been left open and there was no pressure on well. Removed WH equip and installed well control valve. Well standing full w/ water. WIH w/ 3 ½" sinker bar, stopped at 265' and worked to 280. Bar had signs of paraffin. POH and ran 2" sinker bar, unable to work past 280'. POH w/ WL, removed well control valve and installed WH equip and installed WH equip and installed Well worke and installed WH equip and installed WH equip and installed WH equip and installed WH equip and installed Well worke and installed WH equip and installed WH equ						
Euronit Queen TD PBD RKB PERFS 3880' 3635' 6.5' OH 3777-3880 TD SURFACE INTERMEDIATE PRODUCTION CIBP DEPTH 10 3/4"@276' 7.5/8"@1525' 51/2" @ 3777' 3700' OPERATOR CHARGE CODE BENTERRA CHARGE CODE WWNMR-00101-001 This well is part of the New Mexico "P&A Pilot Project" conducted by Benterra Corporation to demonstrate the plugging and abandonment process using highly compressed sodium bentonite nodules as the plugging medium. 9/7/04* MI Benterra Unit #4. Held pre-job safety meeting. Casing valve had been left open and there was no pressure on well. Removed WH equip and installed well control valve. Well standing full w/ water. WHH w/ 3 ½" sinker bar, stopped at 265' and worked to 280'. Bar had signs of paraffin. POH and ran 2" sinker bar, unable to work past 280'. POH w/ WL, removed well control valve and installed WH equip SI had signs of paraffin. POH and ran 2" sinker bar, unable to work past 280'. POH w/ WL, removed well control valve and installed WH equip SI had signs of paraffin. POH and ran 2" sinker bar, unable to work past 280'. POH w/ WL, removed well control valve and installed WH equip SI had signs of paraffin. POH and ran 2" sinker bar, unable to work past 280'. POH w/ WL, removed well control valve and installed WH equip SI had signs of parafin. Chevron and he said he would probably try to cut parafin with a swab unit.) Chevron cleaned out wellbore (circ out polymer squeeze material from previous workover) & circ w/ freshwater. NIMCDD			<u></u>			
TD PBD RKB PERFS 3880' 3635' 6.5' OH 3777-3880 TD SURFACE INTERMEDIATE PRODUCTION CIBP DEPTH 10 3/4"@276' 7 5/8"@1525' 51/2"@ 3777' 3700' OPERATOR CHARGE CODE BENTERRA CHARGE CODE WWNMR-00101-001 This well is part of the New Mexico "P&A Pilot Project" conducted by Benterra Corporation to demonstrate the plugging and abandonment process using highly compressed sodium bentonite nodules as the plugging medium. 9/7/04 9/7/04 9/7/04 0 </td <td></td> <td></td> <td></td> <td></td> <td></td>						
3880' 3635' 6.5' OH 3777-3880 TD SURFACE INTERMEDIATE PRODUCTION CIBP DEPTH 10 3/4"@276' 7 5/8"@1525' 51/2"@ 3777' 3700' OPERATOR CHARGE CODE BENTERRA CHARGE CODE WWNMR-00101-001 This well is part of the New Mexico "P&A Pilot Project" conducted by Benterra Corporation to demonstrate the plugging and abandonment process using highly compressed sodium bentonite nodules as the plugging medium. 9/7/04 9/7/04 MI Benterra Unit #4. Held pre-job safety meeting. Casing valve had been left open and there was no pressure on well. Removed WH equip and installed well control valve. Well standing full wwater. WIH w/ 3 ½" sinker bar, stopped at 265' and worked to 280'. Bar had signs of paraffin. POH and ran 2" sinker bar, unable to work past 280'. POH wi WL, removed well control valve and installed WH equip. Left well SI. Took Unit #4 to yard for reloading ZONITE and SD for weekend. E.L. Gonzalez w/ NMOCD was contacted and made aware of problem. (Note: discussed problem with Nathan Mouser w/ Chevron and he said he would probably try to cut parafin with a swab unit.) Chevron cleaned out wellbore (circ out polymer squeeze material from previous workover) & circ w/ respect w/ SW wiper rubber – reviewed well files w/ Chevron & determined that CIBP was probably never capped wi cernent – decided to push WR to CIBP & cap w/ 100' of ZONITE. Notified E.L. Gonzalez w/ MOCD of procedure change. Finish pushing WR to 3692', FL @ +/- 167'. Place 14 cu ft ZONITE & 10/3/61 MIRU Benterra Unit #4. No press on well. Remove WH & WIH w/ SB a tagged btm @ 3692'. Started in		PRD	DVD	DEDEO		
SURFACE INTERMEDIATE PRODUCTION CIBP DEPTH 10 3/4*@276* 7 5/8*@1525* 51/2*@3777* 3700* OPERATOR CHARGE CODE BENTERRA CHARGE CODE WNMR-00101-001 This well is part of the New Mexico "P&A Pilot Project" conducted by Benterra Corporation to demonstrate the plugging and abandonment process using highly compressed sodium bentonite nodules as the plugging medium. 9/7/64 3/7/64 MI Benterra Unit #4. Held pre-job safety meeting. Casing valve had been left open and there was no pressure on well. Removed WH equip and installed well control valve. Well standing full w/ water. WIH w/ 3% sinker bar, stopped at 265* and worked to 280*. Bar had signs of paraffin. POH and ran 2* sinker bar, unable to work past 280*. POH w/ UL, removed well control valve and installed WH equip. Left well S1. Took Unit #4 to yard for reloading ZONITE and SD for weekend. E.L. Gonzalez w/ NMOCD was contacted and made aware of problem. (Note: discussed problem with Nathan Mouser w/ Chevron and he said he would probably try to cut parafin with a swab unit.) Chevron cleaned out wellbore (circ out polymer squeeze material from previous workover) & circ w/ freshwater. 10/3/01 MIRU Benterra Unit #4. No press on well. Remove WH & WIH w/ SB & tagged btm @ 3692'. Started in hole w/ 5 ½" wiper rubber – reviewed well files w/ Chevron & determined that CIBP was probably never capped w/ cement – decided to push WR to CIBP & cap wi 100' of ZONITE. Notified E.L. Gonzalez w/ MOCD of procedure change. Finish pushing WR to 3692', FL @ +/-167'. Place 14 cu ft ZONITE & tagged @ 3588'. Btm plug set from 3588' – 369						
10 3/4"@276' 7 5/8"@1525' 51/2" @ 3777' 3700' OPERATOR CHARGE CODE WBS No. UWPWBA1004ABN BENTERRA CHARGE CODE WBS No. UWPWBA1004ABN NWNMR-00101-001 This well is part of the New Mexico "P&A Pilot Project" conducted by Benterra Corporation to demonstrate the plugging and abandonment process using highly compressed sodium bentonite nodules as the plugging medium. 9/7/01 9/7/01 MI Benterra Unit #4. Held pre-job safety meeting. Casing valve had been left open and there was no pressure on well. Removed WH equip and installed well control valve. Well standing full w/ water. WH w/ 3%" sinker bar, stopped at 265' and worked to 280'. Bar had signs of paraffin. POH and ran 2" sinker bar, unable to work past 280'. POH w/ WL, removed well control valve and installed WH equip. Left well \$31 Took Unit #4 to yard for reloading ZONITE and SD for weekend. EL. Gonzalez w/ NMOCD was contacted and made aware of problem. (Note: discussed problem with Nathan Mouser w/ Chevron and he said he would probably try to cut parafin with a swab unit.) Chevron cleaned out wellbore (circ out polymer squeeze material from previous workover) & circ w/ freshwater. 10/3/04 MIRU Benterra Unit #4. No press on well. Remove WH & WIH w/ SB & tagged btm @ 3692'. Started in hole w/ 5 %" wiper rubber - reviewed well files w/ Chevron & determined that CIBP was probably never capped w/ cement - decided to push WR to CIBP & cap w/ 100' of ZONITE. Notified EL. Gonzalez w/ NMOCD of procedure change. Finish pushing WR to 3692', FL @ +/ 167'. Place 14 cu ft ZONITE & tagged @ 3588'. Btm plug set from						
OPERATOR CHARGE CODE BENTERRA CHARGE CODE WBS No. UWPWBA1004ABN NWNMR-00101-001 This well is part of the New Mexico "P&A Pilot Project" conducted by Benterra Corporation to demonstrate the plugging and abandonment process using highly compressed sodium bentonite nodules as the plugging medium. 9/7/04 MI Benterra Unit #4. Held pre-job safety meeting. Casing valve had been left open and there was no pressure on well. Removed WH equip and installed well control valve. Well standing full w/ water. WIH w/ 3 ½" sinker bar, stopped at 265' and worked to 280'. Bar had signs of paraffin. POH and ran 2" sinker bar, unable to work past 280'. POH w/ WL, removed well control valve and installed WH equip. Left well SI. Took Unit #4 to yard for reloading ZONITE and SD for weekend. E.L. Gonzalez w/ NMOCD was contacted and made aware of problem. (Note: discussed problem with Nathan Mouser w/ Chevron and he said he would probably try to cut parafin with a swab unit.) Chevron cleaned out wellbore (circ out polymer squeeze material from previous workover) & circ w/ freshwater. 10/3/01 MIRU Benterra Unit #4. No press on well. Remove WH & WIH w/ SB & tagged btm @ 3692'. Started in hole w/ 5 ½" wiper rubber - reviewed well files w/ Chevron & determined that CIBP was probably never capped w/ cement - decided to push WR to CIBP & cap w/ 100' of ZONITE. Notified E.L. Gonzalez w/ MMOCD of procedure change. Finish pushing WR to 3692', FL @ +/- 167'. Place 14 cu ft ZONITE & tagged @ 3588'. Btm plug set from 3588' - 3692' = 104'. Pushed 5 ½" wiper rubber to 2890' for B/salt plug. Close well in & SDON. 10/4/01 SIP = static. Poured 9 cu ft. ZONITE, wait & tag @ 2821'. Poured 5 cu ft ZONITE wait & tag @ 2781'. Pushed 5 ½" w						
WBS No. UWPWBA1004ABN NWNMR-00101-001 This well is part of the New Mexico "P&A Pilot Project" conducted by Benterra Corporation to demonstrate the plugging and abandonment process using highly compressed sodium bentonite nodules as the plugging medium. 9/7/04 MI Benterra Unit #4. Held pre-job safety meeting. Casing valve had been left open and there was no pressure on well. Removed WH equip and installed well control valve. Well standing full w/ water. WIH w/ 3 ½" sinker bar, stopped at 265' and worked to 280'. Bar had signs of paraffin. POH and ran 2" sinker bar, unable to work past 280'. POH w/ WL, removed well control valve and installed WH equip. Left well SI. Took Unit #4 to yard for reloading ZONITE and SD for weekend. EL. Gonzalez w/ NMOCD was contacted and made aware of problem. (Note: discussed problem with Nathan Mouser w/ Chevron and he said he would probably try to cut parafin with a swab unit.) Chevron cleaned out wellbore (circ out polymer squeeze material from previous workover) & circ w/ freshwater. 10/3/01 MIRU Benterra Unit #4. No press on well. Remove WH & WIH w/ SB & tagged btm @ 3692'. Started in hole w/ 5's" wiper rubber – reviewed well files w/ Chevron & determined that CIBP was probably never capped w/ cement – decided to push WR to CIBP & cap w/ 100' of ZONITE. Notified EL. Gonzalez w/ NMOCD of procedure change. Finish pushing WR to 3692', FL @ +/- 167'. Place 14 cu ft ZONITE & tagged @ 3588'. Bim plug set from 3588' – 3692' = 104'. Poured 5 cu ft ZONITE wait & tag @ 2781'. Bigg = static. Poured 9 cu ft. ZONITE, wait & tag @ 2821'. Poured 5 cu ft ZONITE wait & tag @ 2781'. Bigg = static. Poured 9 cu ft. ZONITE, wait & tag @ 2821'. Poured 5 cu ft ZONITE wait & tag @ 2781'. <td></td> <td></td> <td>31/2 @ 31/1</td> <td colspan="3"></td>			31/2 @ 31/1			
This well is part of the New Mexico "P&A Pilot Project" conducted by Benterra Corporation to demonstrate the plugging and abandonment process using highly compressed sodium bentonite nodules as the plugging medium. 9/7/04 MI Benterra Unit #4. Held pre-job safety meeting. Casing valve had been left open and there was no pressure on well. Removed WH equip and installed well control valve. Well standing full w/ water. WIH w/ 3 's' sinker bar, stopped at 265' and worked to 280'. Bar had signs of paraffin. POH and ran 2" sinker bar, unable to work past 280'. POH w/ WL, removed well control valve and installed WH equip. Left well SI. Took Unit #4 to yard for reloading ZONITE and SD for weekend. <u>E.L. Gonzalez w/ NMOCD was contacted and made aware of problem.</u> (Note: discussed problem with Nathan Mouser w/ Chevron and he said he would probably try to cut parafin with a swab unit.) Chevron cleaned out wellbore (circ out polymer squeeze material from previous workover) & circ w/ freshwater. 10/3/01 MIRU Benterra Unit #4. No press on well. Remove WH & WIH w/ SB & tagged btm @ 3692'. Started in hole w/ 5 ½" wiper rubber – reviewed well files w/ Chevron & determined that CIBP was probably never capped w/ cement – decided to push WR to CIBP & cap w/ 100' of ZONITE. Notified E.L. Gonzalez w/ NMOCD of procedure change. Finish pushing WR to 3692', FL @ +/- 167'. Place 14 cu ft ZONITE & tagged @ 3588'. Btm plug set from 3588' – 3692' = 104'. Pushed 5 ½" wiper rubber to 2890' for B/salt plug. Close well in & SDON. 10/4/01 SIP = static. Poured 9 cu ft. ZONITE, wait & tag @ 2821'. Poured 5 cu ft ZONITE wait & tag @ 2781'. B/salt plug set 2781' – 2890' w/ 14 cu ft ZONITE as of 9:45 a.m. 10/4/01. Pushed 5 ½" wiper rubber to 1575'. Poured 3 cu ft ZONITE, wait & tag @ 2090'. Well prepped for Cavity Shot from 266'. – 276' PD				1		
 977/04: MI Benterra Unit #4. Held pre-job safety meeting. Casing valve had been left open and there was no pressure on well. Removed WH equip and installed well control valve. Well standing full w/ water. WIH w/ 3 ½" sinker bar, stopped at 265' and worked to 280'. Bar had signs of paraffin. POH and ran 2" sinker bar, unable to work past 280'. POH w/ WL, removed well control valve and installed WH equip. Left well SI. Took Unit #4 to yard for reloading ZONITE and SD for weekend. <u>E.L. Gonzalez w/ NMOCD was contacted and made aware of problem.</u> (Note: discussed problem with Nathan Mouser w/ Chevron and he said he would probably try to cut parafin with a swab unit.) Chevron cleaned out wellbore (circ out polymer squeeze material from previous workover) & circ w/ freshwater. 10/3/01 MIRU Benterra Unit #4. No press on well. Remove WH & WIH w/ SB & tagged btm @ 3692'. Started in hole w/ 5 ½" wiper rubber – reviewed well files w/ Chevron & determined that CIBP was probably never capped w/ cement – decided to push WR to CIBP & cap w/ 100' of ZONITE. Notified E.L. Gonzalez w/ NMOCD of procedure change. Finish pushing WR to 3692', FL @ +/- 167'. Place 14 cu ft ZONITE & tagged @ 3588'. Btm plug set from 3588' – 3692' = 104'. Pushed 5 ½" wiper rubber to 2890' for B/salt plug. Close well in & SDON. SIP = static. Poured 9 cu ft. ZONITE, wait & tag @ 2821'. Poured 5 cu ft ZONITE wait & tag @ 2781'. B/salt plug set 2781' – 2890' w/ 14 cu ft ZONITE as of 9:45 a.m. 10/4/01. Pushed 5 ½" wiper rubber to 1575'. Poured 22 cu ft ZONITE, wait & tag @ 1409'. Pour 8 cu ft ZONITE, wit & tag @ 1460'. T/Salt – Rustler plug set 1346' – 1575' wi 30 cu ft ZONITE as of 11:50 a.m. 10/4/01. Pushed 5 ½" wiper plug to 316'. Poured 3 cu ft ZONITE, wait & tag @ 290'. Well prepped for Cavity Shot from 266' – 276'. PD 	····					
9/7/04 MI Benterra Unit #4. Held pre-job safety meeting. Casing valve had been left open and there was no pressure on well. Removed WH equip and installed well control valve. Well standing full w/ water. WIH w/ 3 ½" sinker bar, stopped at 265' and worked to 280'. Bar had signs of paraffin. POH and ran 2" sinker bar, unable to work past 280'. POH w/ WL, removed well control valve and installed WH equip. Left well SI. Took Unit #4 to yard for reloading ZONITE and SD for weekend. <u>E.L. Gonzalez w/ NMOCD was contacted</u> and made aware of problem. (Note: discussed problem with Nathan Mouser w/ Chevron and he said he would probably try to cut parafin with a swab unit.) Chevron cleaned out wellbore (circ out polymer squeeze material from previous workover) & circ w/ freshwater. 10/3/01 MIRU Benterra Unit #4. No press on well. Remove WH & WIH w/ SB & tagged btm @ 3692'. Started in hole w/ 5 ½" wiper rubber – reviewed well files w/ Chevron & determined that CIBP was probably never capped w/ cement – decided to push WR to CIBP & cap w/ 100' of ZONITE. Notified E.L. Gonzalez w/ NMOCD of procedure change. Finish pushing WR to 3692', FL @ +/- 167'. Place 14 cu ft ZONITE & tagged @ 3588'. Btm plug set from 3588' – 3692' = 104'. Pushed 5 ½" wiper rubber to 2890' for B/salt plug. Close well in & SDON. 10/4/01 SIP = static. Poured 9 cu ft. ZONITE, wait & tag @ 2821'. Poured 5 cu ft ZONITE wait & tag @ 2781'. B/salt plug set 2781' – 2890' w/ 14 cu ft ZONITE as of 9:45 a.m. 10/4/01. Pushed 5 ½" wiper rubber to 1575'. Poured 22 cu ft ZONITE, wait & tag @ 1409'. Pour 8 cu ft ZONITE, wait & tag @ 1346'. T/Sait – Rustler plug set 1346' – 1575' w/ 30 cu ft ZONITE as of 11:50 a.m. 10/4/01. Pushed 5 ½" wiper plug to 316'. Poured 3 cu ft ZONITE, wait & tag @ 290'. Well prepped for Cavity Shot from 266' _ 276'. PD	This well is part plugging and aba	of the New Mexic Indonment process	o "P&A Pilot Proje using highly comp	ect" conducted pressed sodium	by Benterra Corporation to demonstrate the bentonite nodules as the plugging medium.	
 pressure off well. Removed WH equip and installed well control valve. Well standing full w/ water. WIH w/ 3 ½" sinker bar, stopped at 265' and worked to 280'. Bar had signs of paraffin. POH and ran 2" sinker bar, unable to work past 280'. POH w/ WL, removed well control valve and installed WH equip. Left well SI. Took Unit #4 to yard for reloading ZONITE and SD for weekend. <u>E.L. Gonzalez w/ NMOCD was contacted</u> and made aware of problem. (Note: discussed problem with Nathan Mouser w/ Chevron and he said he would probably try to cut parafin with a swab unit.) Chevron cleaned out wellbore (circ out polymer squeeze material from previous workover) & circ w/ freshwater. 10/3/01 MIRU Benterra Unit #4. No press on well. Remove WH & WIH w/ SB & tagged btm @ 3692'. Started in hole w/ 5 ½" wiper rubber – reviewed well files w/ Chevron & determined that CIBP was probably never capped w/ cement – decided to push WR to CIBP & cap w/ 100' of ZONITE. Notified E.L. Gonzalez w/ NMOCD of procedure change. Finish pushing WR to 3692', FL @ +/- 167'. Place 14 cu ft ZONITE & tagged @ 3588'. Btm plug set from 3588' – 3692' = 104'. Pushed 5 ½" wiper rubber to 2890' for B/salt plug. Close well in & SDON. 10/4/01 SIP = static. Poured 9 cu ft. ZONITE, wait & tag @ 2821'. Poured 5 cu ft ZONITE wait & tag @ 2781'. B/salt plug set 2781' – 2890' w/ 14 cu ft ZONITE as of 9:45 a.m. 10/4/01. Pushed 5 ½" wiper rubber to 1575'. Poured 22 cu ft ZONITE, wait & tag @ 1409'. Pour 8 cu ft ZONITE, wait & tag @ 1346'. T/Salt – Ruster plug set 1346' – 1575' w/ 30 cu ft ZONITE as of 11:50 a.m. 10/4/01. Pushed 5 ½" wiper plug to 316'. Poured 3 cu ft ZONITE, wait & tag @ 290'. Well prepped for Cavity Shot from 266' – 276'. PD 						
	Took Unit #4 to and made aware would probably to Chevron cleaned freshwater. 10/3/01 MIRU Benterra U hole w/ 5 ½" wip capped w/ ceme NMOCD of proce tagged @ 3588'. plug. Close well 10/4/01 SIP = static. Pou B/salt plug set 27 1575'. Poured 22 Rustler plug set 27	yard for reloading <u>e of problem.</u> (No try to cut parafin v d out wellbore (cir Unit #4. No press er rubber – reviev ent – decided to pu edure change. Fii Btm plug set from in & SDON. ured 9 cu ft. ZONI 781' – 2890' w/ 14 2 cu ft ZONITE, w 1346' – 1575' w/ 3	7 WL, removed w ZONITE and SD te: discussed pro vith a swab unit.) c out polymer squ on well. Remove ved well files w/ C ush WR to CIBP & nish pushing WR m 3588' – 3692' = TE, wait & tag @ cu ft ZONITE as vait & tag @ 1409 80 cu ft ZONITE a	ell control valv for weekend. oblem with Na ueeze materia e WH & WIH v chevron & dete cap w/ 100' of to 3692', FL (e = 104'. Pushe 2821'. Poure of 9:45 a.m. '. Pour 8 cu fi	 ve and installed WH equip. Left well SI. <u>E.L. Gonzalez w/ NMOCD was contacted</u> than Mouser w/ Chevron and he said he al from previous workover) & circ w/ w/ SB & tagged btm @ 3692'. Started in ermined that CIBP was probably never of ZONITE. Notified E.L. Gonzalez w/ @ +/- 167'. Place 14 cu ft ZONITE & d 5 ½" wiper rubber to 2890' for B/salt ed 5 cu ft ZONITE wait & tag @ 2781'. 10/4/01. Pushed 5 ½" wiper rubber to the to the to the to the to the to to the t	

Arnott Ramsay C #8 Page 2
11/19/01
MIRU Key Energy WL, including mast. Hole full of water. RU well control equip. & cavity shot consisting of 24 – 2" x 4 ½" cast boosters w/ prima-cord threaded through all boosters. No stovepipe used on this charge – duct taped together. Charge run on 27' of nylon cord w/ conductor wire connected to 5/16" WL. WIH w/ CS & positioned opposite 266 – 276' (6.5' RKB). Key vac truck connected to 5 ½" csg outlet. Fired shot – "mini sonic boom", slight ground shake, strong blow of water sprayed (+/- 40') out 10 ¾" x 7 5/8" riser, 30-45 seconds, some indication of slight flow out 7 5/8" x 5 ½" riser. Performed 'gun & run' when shot fired. POH & rec all of WL & nylon rope. RD Key WL. RU Key PT to 5 ½' tbg head. Pumped 4 bbl freshwater & loaded. Had circ out both annulus risers – better flow out 10 ¾" x 7 5/8" annulus. Closed in 7 5/8" x 5 ½" annulus & connected vac truck to 10 ¾" x 7 5/8" annulus. Pump 25 bbl FW, twice capacity. Closed in 7 5/8" x 5 ½" annulus & hooked VT to 7 5/8" x 5 ½" annulus. Pumped 25 bbl FW via 5 ½" csg. All water pumped @ circ press. Closed wellbore in & RD Key trucks.
MIRU Key Energy Unit #99. WIH w/ 15' mule-shoe tbg jt on 2 3/8' tbg & tag @ 264', unable to work deeper. RU DHV International & Key pump & vac trucks. Pumped down 2 3/8" tbg & video taped cavity shot area. Pipe was clearly damaged @ 264' – could probably get ZONITE beyond 5 ½" csg wall but would not be able to determine effective length of any such plug since camera stopped @ 264'. Review of area above 264' found csg to be parted and 'egged' @ +/- 258'. 5 ½" csg appeared to be in good condition @ 252' (as shallow as we could pull camera w/ out laying jt of tbg down) although a split is visible @ +/- 255'. Rotated tbg & fell +/- 3'. Reviewed area w/ camera, appeared to be in formation. Overall, camera provided inconclusive evaluation of cavity shot. However, ability to circ out both 10 ¾" x 7 5/8" x 7 5/8" & 5 ½" annuli suggests that cementing may be most appropriate plug. Will discuss w/ NMOCD. RD DHV & SDON.
POH & LD tbg. RD & release PU.
12/07/01 Discussed operations w/ Chris Williams & Paul Kautz w/ NMOCD in Hobbs, NM during an update meeting regarding the P&A pilot progress. Informed them of the communication from both 10 ¾" x 7 5/8" & 7 5/8" x 5 ½" annuli. Requested & received permission to cement both annuli and leave 5 ½" csg filled with cement, approved by Chris Williams.
12/8/01
MIRU Key Energy bulk truck, cmt pump truck & vac truck w/ 130 bbl freshwater. Pumped into 5 ½" csg, loaded w/ 8 bbl FW & established circ out both 10 ¾" x 7 5/8" & 7 5/8" x 5 ½" annuli. Pumped add'l 10 BW & began cementing. Mixed & pumped +/- 245 sx Class C neat @ 14.8 ppg. Had cmt returns after +/- 80 sx but not quality cement. Mix & pump +/-165 sx (total of 245 sx pumped). Circ 13.8 – 14.2 ppg cement out both annuli, closed-in annuli. Pump 1 bbl FW to clear lines, pump & 5 ½" wellhead, max press 250 psi. Closed-in 5 ½" csg w/ 200 psi. Cement in place @ 1:30 p.m. 12/8/01. RD & R all Key equip
12/10/01
SIP = static. TOC inside 5 1/2" csg = 8'. Will fill with ZONITE.
12/11/01
MIRU Benterra #4. Filled csg with ZONITE (+/- 1 ft ³). Install WH. RD Benterra.
12/19/01
SIP = static. Fluid, ZONITE @ surface. No pressure on annuli risers.
1/9/02
SIP = static

Arnott Ramsay C #8

Page 3

1/28/02

SIP = static. Removed WH, water at surface, no bubbling.

2/20/02

Check location; no problems.

3/14/02

Check location; no problems.

3/18/02

Add water to top of ZONITE cap, no bubbling. Surface & intermediate risers are cemented.

3/27/02

Dug out around wellhead with backhoe and cut off casings and wellhead at 4' below GL. Installed WH cap with 1/2" brass monitoring valve and dry hole marker with location identification. Back-filled cellar, cut-off guy wire anchors below GL. Well P&A'd 3-27-02. Notified ChevronTexaco that location was ready for cleanup. FINAL REPORT.