	Plug Set:	1. Spot following plug to cover across top of salt section	10. Pull up in casing above top of plug and reverse circulate to clear ' [\] ing. TOH laying down tubing to 1600 ft.	Cement: Volume of Cement <u>30</u> (sacks) Cement Class* <u>APICLSC</u> API CLASS C Type of Job* <u>P&A</u> P&A	3275 3725 CEMENT NO	Plug Set: Depth Top' Bottom' Type Plug* (yes∕no)	9. Spot following plug on top of CIBP	8. Circulate and fill wellbore with 9.5 ppg mud.	7. After setting CIBP, close pipe-rams and pressure test plug and casing to 500 psi to ensure wellbore integrity.	<u>3765 3767 CIBP(TBG SET) NO</u>	lug Set: Depth Top' Bottom' Type Plug* (yes/no)	TIH w∕tubing conveyed CIBP and set at 3765 ft.	5. TIH w/casing scraper and clean out casing to below 3,725 ft.	4. Install and test Class III BOPs as per guidelines in Division Workover Manual. TOH standing back tubing.	3. MIRU WSU. Ensure that well is dead. TOH laying down rods and pump.	2. Pull test rig anchors prior to rigging up. Send results and charts to Rosemarie Whitlock in Midland Office. Replace anchors as necessary.	NOTE: All plugs to be class C cement. Plugs are to be mixed using 6.3 gals./sack mix water for a 14.8 ppg slurry with a 1.32 cubic ft./sack yield. A 9.5 ppg mud laden fluid to be placed in wellbore between the plugs, with a fresh water spacer to be pumped ahead of and behind each plug.	 Notify New Mexico Oil Conservation Division 24 hrs. prior to commencing plugging operations. (505) 393-6161 	.job\$ 60003423 NEW MEXICO STATE "G" - 0010 10/16/90 Procedure by JLG	
--	-----------	--	--	--	---------------------	--	---------------------------------------	--	--	-----------------------------------	---	--	---	--	---	--	--	---	--	--

Lea County, Date plugged 17. RDMD.	16. Weld onto to Weld the followj Exxon Corp. N.M. "G" St. ¢10 1980' FSL, ¢60' Sec. 26, T21S, R	15. Nipple	Cement	0	0	Plug S T	14. Shut 4 1∕2″ b plug to	Perfor	13. MIRU	12. Pull tubing.	Cement:	L .		- (t
unty, N lugged Mn	Veld onto the follo "G" St. 4 "FSL, 660 26, T21S,					Set: De Top'		e t	RU WLSU	1 up TOH		1150	D Top'	((((
	ng on p FWL	down BOPs and	Volume of Cement Type o	380	380	Depth Bottom'	blind-rams and pump do / 8 5/8" annulus. After ill casing and annulus	.e: Phasing <u>20</u> top of Bottom Interval Interva <u>380 381</u>	U to perforate	in casing above laying down tub:	Volume of Cement Type	1600	Depth	t t
	sing a 1/4" steel late.	remove wellheads	Cement <u>100</u> (Class* <u>APICLS</u> f Job* <u>P&A</u>	IN 4 1/2" ANNULUS	CEMENT	Type Plug*	wn cas estab from	ing <u>90</u> Bottom of Interval Spacing <u>381 1</u>	ite.	top of plug ing.	Cement <u>30</u> Class* <u>APICL</u> of Job* <u>P&A</u>	CEMENT	Type Plug*	Procedure by
	plate containing	·	sacks) <u>(C</u> API CLASS C P&A	<u>.us</u>	NO	Tagged (yes∕no)	ing to establish cir lishing circulation, surface to 380 ft.	Shots per ft		and reverse cj	(sacks) <u>SC</u> API CLASS C P&A	NO	Tagged (yes∕no)	א זרפ ר י יייי
	ing a weep hole.						circulation up the lon, pump following	Total		circulate to clear			2	TA, 19, 10

18. Clean location