

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-70

5a. Indicate Type of Lease
State ☒ For ☐
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Chevron U.S.A. Inc.	8. Farm or Lease Name W. A. Ramsay NCT-A
3. Address of Operator P.O. Box 670, Hobbs, NM 88240	9. Well No. 40
4. Location of well UNIT LETTER <u>A</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>27</u> TOWNSHIP <u>21S</u> RANGE <u>36E</u> NMPM.	10. Field and Pool, or Wildcat Eumont Y-SR-Q
15. Elevation (Show whether DF, RT, GR, etc.) 3559'	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Work performed 5-12-88 thru 5-16-88 TD: 3920 PB: 3915'

POOH w/ pumping equipment. Chemical squeeze perms f/3738' to 3910' w/1050 gallons petrosol X-25. Shut in f/36 hrs for chemical to work. Acidize perms w/3000 gallons 15% NEFE HCL, swab well. Cleanout 5' fill f/3910 to 3915'. Run 2 7/8" prod. tbg to 3915'. Run pump. equip. Space out pmp, test to 500spi, ok. RD MO PU. Turn over to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED M. E. Abin TITLE Staff Drilling Engr. DATE June 20, 1988

ORIGINAL FILED IN DIVISION

APPROVED BY DEPT. OF ENERGY TITLE DATE

CONDITIONS OF APPROVAL, IF ANY: