and the second			•·· •· •·	
District Office	State of New Mexico Energy, Minerals and Natural Resources Department OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, New Mexico 87504-2088		Form C-103 Revised 1-1-89	
DISTRICT I P.O. Box 1980, Hobbs, NM 88240 OIL CC			WELL API NO. 30-025-04863	
DISTRICT II Sant P.O. Drawer DD, Artesia, NM 88210			5. Indicate Type of Lease STATE XX FEE	
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No. B1481	
SUNDRY NOTICES AND F	REPORTS ON WELLS	<u></u>		
( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name		
1. Type of Well: OEL GAS WELL WELL X	OTHER		008651	
2. Name of Operator OXY USA Inc.		16696	8. Well No. 1	
3. Address of Operator P.O. Box 50250	Midland, TX 79	9710	9. Pool name or Wildcat 076480 Eumont Yates 7 Rvrs Queen (PG)	
4. Well Location	- Nouth	109	RO East Error The East Line	
Unit LetterB:660 Feet From	n The <u>North</u>	Line and70		
Section 32 Township	p 21S Range D. Elevation (Show whether DF,	36E <b>RKB, RT, GR, etc.</b> )	NMPM Lea County	
	3615'			
11. Check Appropria NOTICE OF INTENTION	te Box to Indicate Nat	ture of Notice, F	BSEQUENT REPORT OF:	
		REMEDIAL WORK		
PULL OR ALTER CASING		OTHER:		
12. Describe Proposed or Completed Operations (Clearty		ive pertinent dates, inc	luding estimated date of starting any proposed	
work) SEE RULE 1103.				
TD - 3890' Perfs - 3803'-3890'				
•				
	SEE OTHER SIDE	7		
	SEE OTHER SIDE	_		
		<u> </u>		
I hereby certify that the information above is true and complete		Regulatory	Analyst DATE 12/13/95	
SKONATURE	mu		DATE	

- TITLE -

DEC 1 8 1995

\_ DATE -

PE OR PRINT NAME	D <b>avi</b> d	Stewart
IFE OK FRENT NAME		

4

(This space for State Use) ORIGINAL S'GNED BY JERRY SEXTON DILLY. TI I MAN SAVILOR

CONDITIONS OF APPROVAL, IF ANY:

APTROVED BY -

- 1.) MIRU pulling unit. TOOH w/ rods and pump. ND WH, NU BOP. TOOH w/ tbg .
- 2.) TIH w/ 6 1/8" RB, and 7" csg scraper on tbg and CO csg to 3830'. TOOH
  w/ RB, csg scraper, and tbg.
- 3.) RU wireline and run GR/Neutron log from 3830' to 3000'. Perforate Yates and Seven Rivers formation as per Geologist's recommendation on location. RIH w/ CIBP and set @ <u>+</u>3790'.
- 4.) TIH w/ Baker Lok-set pkr w/ on-off tool and 1.87" profile nipple on 3 1/2" tbg and set pkr @ ± 3150'. Swab test well.
- 5.) RU acid company, pressure backside to 500#. Acidize perfs w/ 4500 gals 7 1/2% Ne Fe HCl and 7/8" RCNBS. Flush w/ 2% KCl wtr. Swab test.
- 6.) RU Frac Co., Pressure backside to 2000#. Frac perfs w/ 78,500 gals 50 quality gelled 2% KCl wtr/CO2 and 180,000# 12/20 sand and 60,000# Resin coated 12/20 sand at 45 BPM down 3 1/2" tbg as follows:

a.) Pump 35,000 gals 50 quality foam pad.

- b.) Pump 4,000 gals 50 quality foam with 2 ppg 12/20 sand.
- c.) Pump 4,500 gals 50 quality foam with 3 ppg 12/20 sand.
- d.) Pump 5,000 gals 50 quality foam with 4 ppg 12/20 sand.
- e.) Pump 6,000 gals 50 quality foam with 5 ppg 12/20 sand.
- f.) Pump 7,000 gals 50 quality foam with 6 ppg 12/20 sand.
- g.) Pump 9,500 gals 50 quality foam with 7 ppg 12/20 sand.
- h.) Pump 7,500 gals 50 quality foam with 8 ppg 12/20 resin coated sand.
- i.) Flush w/ base frac fluid.

ľ

- 7.) Open well on 14/64" choke and flow back load and CO2. Test well.
- 8.) TIH w/ sinker and tag PBTD. RU coil tbg unit if necessary and CO well to PBTD. RD coil tbg.
- 9.) RU slick line and TIH w/ plug and set in profile nipple. TOOH w/ 3 1/2" tbg. TIH w/ 2 3/8" production tbg and latch onto on off tool. pressure test tbg. Pull plug and test well.

د. این استوریسی در ما<sup>رد</sup> این استوریسی در مارد

10.) Run four point test and put well on production.