

W.A. Ramsay (NCT) A # 032
API # 30-025-04905
Section 34, T21S, R36E, UL. J

WBS # UWPWB-A10___-ABN
1980' FSL & 1980' FEL
Lea County, New Mexico

Recommended P&A Procedure

Notify OCD 24 hrs prior to operations.

1. This procedure will P&A the W.A. Ramsay NCT A # 032.
2. MIRU PU. Conduct Safety Meeting. Contact OCD. ND WH. NU BOP.
3. RIH w/WS. RU Sierra.
4. Cap existing CIBP set @ 3670' w/35 sx CI 'C' cement Plug, tag cement. Well previously TA'd, 1-20-95.
5. Spot 100' CI 'C' balanced cement plug from 2910' to 2810', 50' above & below, B/Salt. Tag cement.
6. Spot 100' CI 'C' balanced cement plug from 1668' to 1568', 50' above & below T/Salt. Tag cement.
7. Perf & Sqz @ 8/5/8" csg shoe, & spot 100' balanced cmt plug from 450' to 350'. Tag cement.
8. Spot 10 sx CI 'C' cement from 70' to surface.
9. ND BOP. RD PU. ND wellhead. Cut off casing 4' below GL & cap.
10. Install 4" P&A marker 4' above GL w/the following stamped on it:
Chevron U.S.A. Inc.
W.A. Ramsay NCT-A # 32
1980' FSL & 1980' FEL
T21S, R-36E, Sec. 34, UL J
Lea County, NM
11. Remove all equip, deadman, and junk from location.
12. Fill any pits and level location.
Class C Cement:
1% CaCl (Cement Accelerator)
0.5 BA-10 (Fluid Loss Additive)
0.3 CD-32 (Cement Dispersant)
905# Brine w/25# of gel per BBL

Casing	Depth
Surf Csg	8-5/8" @ 422'
Prod Csg	5-1/2" @ 3870'
Formation Tops	Depth
Anhy	1520'
T/Salt	1618'
B/Salt	2860'
T/Yates	3040'
T/7Rvns	3290'
T/Queen	3670'

CJ Affeld
Petroleum Engineer
CTN 687-7271
Home - 915-694-3884