

DISTRICT I

1625 N. French Dr., Hobbs, NM 88240

DISTRICT II

811 South First, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

DISTRICT IV

2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

**OIL CONSERVATION DIVISION**

2040 South Pacheco  
Santa Fe, NM 87505

FORM C-103  
Revised March 25, 1999

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. <b>30-025-06600</b>
1. Type of Well: <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		5. Indicate Type of Lease <input type="checkbox"/> STATE <input checked="" type="checkbox"/> FEE
2. Name of Operator <b>Apache Corporation</b>		6. State Oil & Gas Lease No.
3. Address of Operator <b>2000 Post Oak Blvd., Ste. 100, Houston, Texas 77056-4400</b>		7. Lease Name or Unit Agreement Name <b>Northeast Drinkard Unit</b>
4. Well Location Unit Letter <b>P</b> : <b>990</b> Feet From The <b>South</b> Line and <b>990</b> Feet From The <b>East</b> Line Section <b>15</b> Township <b>21S</b> Range <b>37E</b> NMPM <b>Lea</b> County		8. Well No. <b>710</b>
10. Elevation (Show whether DP, RKB, RT, GR, etc.) <b>3411' GR</b>		9. Pool name or Wildcat <b>Eunice N., Blinebry-Tubb-Drinkard</b>

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

**SUBSEQUENT REPORT OF:**

- |  |   |
|--|---|
| <input type="checkbox"/> Perform Remedial Work | <input type="checkbox"/> Plug and Abandon |
| <input type="checkbox"/> Temporarily Abandon   | <input type="checkbox"/> Change Plans     |
| <input type="checkbox"/> Pull or Alter Casing  |   |
| <input type="checkbox"/> Other                 |   |

- |   |   |
|---|---|
| <input type="checkbox"/> Remedial Work                | <input type="checkbox"/> Altering Casing      |
| <input type="checkbox"/> Commence Drilling Operations | <input type="checkbox"/> Plug and Abandonment |
| <input type="checkbox"/> Casing Test and Cement Job   |   |
| <input checked="" type="checkbox"/> Other             | Add Blinebry Perforations                     |

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 8/29/00    Run in hole w/ RBP & set @ 5491'. Test casing to 500# - OK.
- 8/30/00    Run in hole w/ 2-3/8" tubing. Catch RBP & reset @ 5680'. Drop sand on plug. Perforate Blinebry 5523 - 5528, 5532 - 5536, 5540 - 5546, 5554 - 5574, 5588 - 5602, 5606 - 5636. Acidize Blinebry 5523' - 5636' w/ 4000 gals 15% HCL.
- 8/31/00    Frac Blinebry 5523' - 5636' w/ 18400 gals gel & 80160# 16/30 sand
- 9/1/00    Run in hole w/ retrieving head. Rig up foam air unit. Tag sand @ 5280'. Clean out sand to RBP @ 5680'. Circulate well clean. Pull out of hole w/ RBP.
- 9/5/00    Run in hole w/ production equipment. Nipple up wellhead & flow line. Return to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

*Debra L. Anderson*  
Debra L. Anderson

TITLE

Sr. Engineering Technician

DATE

9/25/00

TYPE OR PRINT NAME

TELEPHONE NO.

713-296-6338

(This space for State Use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

5