State of New Mexico Energy, Minerals and Natural Resources Department

Form C-	103
Revised	1-1-89

DISTRICT I	OIL CONSERVAT	ION DIVISION			
P.O. Box 1980, Hobbs, NM 88240	310 Old Santa Fe Tr		WELL API NO.		
	Santa Fe, New M	exico 87503		5-06613	
			5. Indicate Type of Lease FED STATE	X FEE	
			6. State Oil & Gas Lease No.	B-9188	
	S AND REPORTS ON WELL		7 Losso Nomo or Linit Amore	ant Nama	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"		7. Lease Name or Unit Agreement Name			
(FORM C-101 FOR SUCH PROPOSALS.) 1. Type of Well:		NORTHEAST DRINKARI	O UNIT		
	Gas Well Other INJEC	CTOR			
2. Name of Operator	· · · · · · · · · · · · · · · · · · ·		8. Well No. 605		
SHELL WESTERN E&P INC. 3. Address of Operator			9. Pool name or Wildcat		
P. O. BOX 1950, HOBBS, NEW ME	EXICO 88240		N. EUNICE BLINEBRY-T	UBB-DRINKARD	
4. Well Location					
Unit Letter <u>C</u> : 760 Fe	et From The <u>NORTH</u> Line	e and <u>1980</u> Fee	t From The SOUTH	Line	
Section 15	Township 21S	Range 37E	NMPM	LEA County	
	b. Elevation (Show whether DF, RKB, 159DF	RT GR, etc.)			
	propriate Box to Indicate Nati	are of Notice, Report,	or Other Data		
NOTICE OF INTENTI			SEQUENT REPORT OF:		
		MEDIAL WORK	ALTERING	CASING	
		COMMENCE DRILLING OPNS.			
PULL OR ALTER CASING		ASING TEST AND CEMEN	VT JOB		
OTHER: PROFILE CORRECTION		THER:			
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.					
1. Pull out of hole with injection equipment.					
2. Tag PBTD with bit and scraper and pull of 2. Establish an injustion rate into parts betw		als at 6222			
 Establish an injection rate into perfs between 5974 & 6101 and a casing leak at 6232. Cement squeeze the perfs and casing leak. Wait on cement. Drill out and test squeeze. 					
5. Acid treat the Drinkard perfs (6502 to 6696) with 2436 gal 20% HCl, and Blinebry (5760 to 5938) with 3318 gal 20% HCl					
 6. Set hydraulic isolation packer at 5740 and Guiberson Uni VI packer at 5560(isolating a casing leak at 5617 and perfs (5698to 5719) 7. Load casing annulus with inhibited water and record a pressure chart at 500psig for 30 minutes. 					
8. Return well to injection and report stabilized rates and pressures on the morning wire.					
			<u> </u>		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
SIGNATURE C. Man	<u>~~</u> 1	TTLE PRODUCTION		05/09/95	
TYPE OR PRINT NAME C. L. MANN			TELEPHONE NO.	505/393-0209	
	D BY JERRY SEXTON		M	Y 12 1995	
	SUPERVISOR TITLE		DATE DATE		
CONDITIONS OF APPROVAL IF ANY:					