State of New Mexicol Revised 1-1-89 State of New Mexicol Operation Revised 1-1-89 District Office OIL CONSER VATION DIVISION DISTRICT II OIL CONSER VATION DIVISION DISTRICT II OIL CONSER VATION DIVISION DISTRICT II OIL CONSER VATION DIVISION P.O. Drawer DD, Anesia, NM \$8210 WELL API NO. DISTRICT III 1000 Rio Brazos Rd, Azec, NM \$7410 Santa Fe, New Mexico \$7503 S. ladicate Type of Lesse SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TOA B-85 OTHER (DO NOT USE THIS FORM FOR PROPOSALS) State DA (DO NOT USE THIS FORM FOR PROPOSALS) State DA (DO NOT USE THIS FORM FOR PROPOSALS) State DA (1) Type of Well: ON 011 CAS OTHER 021 CAS OTHER 11 Type of Well: State DA 021 CAS OTHER 12 Name of Operator State DA	and the second	Constant Marico	Form C-103
MSTRICT I OIL CONSERVATION DIVISION 310 OIA Santa Fe Trail, Room 206 Santa Fe, New Mexico 87503 WELL AFI NO. 30-023-06618 DISTRICT II OD. Driver DD, Arceix, NM 8210 Santa Fe, New Mexico 87503 S. Indicate Type of Lase STATE(X) FEE DISTRICT II ODD THE FILS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TOA DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS) F. Lesse Name or Unit Agreement Name 1. Type of Wdl: Out and operator Collins & Ware, Inc. OTHER 8. Well No. 3 2. Name of Operator Collins & Ware, Inc. OTHER 8. Well No. 3 3. Addres of Operator Collins & Ware, Inc. 9. Pool parme or Wildex Blinebry 508 W. Walt, Suite 1200, Midland, Tx 79701 Blinebry 508 W. Walt, Suite 1200, Midland, Tx 79701 Blinebry 10. Elevation (Show wetwee DF, RAE, RT, GR, etc.) 34591 GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 12. Berefore M REMEDIAL WORK PLUG AND ABANDON 13. PLOG ALTER CASING OTHER: 14. Check Appropriate Box to Indicate Nature of Notice, Report, or Othe	Appropriate		Revised 1-1-89
SINTACT II Santa Fe, New Mexico 87503 S. Indicate Type of Lesse FEE CD. Derwer DD, Artesia, NM 88210 S. Indicate Type of Lesse State DI & Gas Less Na. B-85 COD NO DISTRICT II S. UNDRY NOTICES AND REPORTS ON WELLS 6. State OI & Gas Lesse Na. B-85 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPENOR PLUG BACK TOA DIFFERENT RESERVOR. USE 'APLICATION FOR PROPOSALS.) 7. Lesse Name or Unit Agreement Name 1. Type of Well: OTHER State DI State DA Vell. OTHER OTHER State DA Vell. OTHER OTHER State DA Vell. OTHER State DA State DA Vell. OTHER State DA State DA Vell. OTHER OTHER State DA State DA Vell. State DA State DA State DA State DA		310 Old Santa Ec. Irall, Room 200	WELL API NO. 30-023-06618
GOO No Britor Rd, Attee, NM E7410 Image: Constraint of the second se	INTRICT II	Santa Fe, New Mexico 87503	5. Indicate Type of Lease STATE STATE FEE
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPENON F DOUBLON FOR THE SERVOIR USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.) Image: State DA	DISTRICT III 000 Rio Brazos Rd., Aztec, NM 87410		6. State Oil & Gas Lease No. B-85
(DONOT USE THIS FORM THE OFFICE TRESERVOR USE "APPLICATION FOR PERMIT" State DA DIFFERENT RESERVOR USE "APPLICATION FOR PERMIT" State DA OIL @AS OTHER VEL @AS State DA VEL @AS OTHER 2. Name of Operator 8. Well Na 3. Collins & Ware, Inc. 9. Pool game or Wildeat Blinebry State DA 508 W. Walt, Suite 1200, Midland, Tx 79701 Blinebry 4. "Well Location J:: 1980 Feet From The South Line and 1980 Unit Letter J:: 1980 Feet From The South Line and 1980 Feet From The East Section 16 Township 21S Range 37E NMPM Lea Cou Mill Letter J:: 1980 Feet From The South Line and 1980 Feet From The East Cou 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3459 ¹ GR GR Cou SUBSEQUENT REPORT OF: PERFORM REMEDIAL WO	SUNDRY NO	TICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
I. Type of Well: OTHER WELL OTHER 2. Name of Operator 8. Well No. 2. Name of Operator 9. Pool same or Wildcat 3. Address of Operator 9. Pool same or Wildcat 3. Address of Operator 9. Pool same or Wildcat 3. Address of Operator 9. Pool same or Wildcat 3. Value Statistic 1980 Ymail Location 1980 Unit Letter 1980 16 Township 21S Range 3459! \rightarrow GR 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3459! \rightarrow GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON PULLOR ALTER CASING Commerce DRILLING OPNS. PULUG AND ABANDON CASING TEST AND CEMENT JOB PULLOR ALTER CASING OTHER: 12. Describe Proposed of Completed Operatious (Clearly state all periment details, and gi	- DIECEUENT M-SI	HOUR USE AFFLOATION ON THE	
Image: Control of Deparation	I. Type of Well:		
X Address of Operator Blinebry 508 W. Wall, Suite 1200, Midland, Tx 79701 Blinebry 4. Well Location 1980 Feet From The South Line and 1980 Feet From The East Maint Letter	Name of Operator		8. Well No. 3
508 W. Wall, Suite 1200, Midland, 1x 19701 4. Well Location Unit Letter J 1980 Feet From The South Line and 1980 Feet From The East Section 16 Township 21S Range 37E NMPM Lea Court 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 11. 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 12. NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK Alterning casing PULL OR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENC OTHER:			9. Pool name or Wildcat
Section 10 Iowinsup 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3459'* GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: DERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING DERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS. PLUG AND ABANDONMENCE DERFORM REMEDIAL WORK CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENCE DEFENDORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENCE OTHER:	Unit Letter _J : _19	780 Feet From The Ine and	NMPM Lea Count
NOTICE OF INTENTION TO: SUBSEQUENT HILL OFFICE PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMEN PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOB PLUG AND ABANDONMEN OTHER: OTHER: OTHER: PLUGG AND ABANDONMEN 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed		10. Elevation (Show whether DF, RKB, RT, GR, etc. 3459' GR	
DERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMEN PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOB CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: PLUG and ABANDONMEN 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed			
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING CASING TEST AND CEMENT JOB CASING TEST AND CEMENT JOB OTHER: OTHER: PLUGG AND ABANDONMENT OTHER: PLUGG AND ABANDONMENT 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed		PLUGANDADADON	
OTHER:			
OTHER:	PULL OR ALTER CASING		prementions in the second seco
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.	other:		
n•, -=-	12. Describe Proposed or Completed O	perations (Clearly state all pertinent details, and give pertinent date	is, including estimated date of summing any proposed

(2	
I bereby certify that the information above is true and complete to the best of my knowledge and belief.	Production Supervisor DATE
TYPE OR PRINT NAME Dianne Sumrall	TELEPHONE NO. (915) 687-3435
(This space for Statistic) :	DATE AUG 15 7890 ,
CONDITIONS OF AFFROVAL, IF ANY:	2A Tubb (Gas) & Drinka

ATTACHMENT TO C-103 STATE DA #3

- 8/2/96 Install BOP and POOH with tubing. RU Wedge Wireline. Run gauge ring to 6450'. Set CIBP at 6366', dump 35' cement on top. Set CIBP at 6160', dump 35' cement on top. Secure well and SDFN.
- 8/3/96 TIH with tubing testing to 5000 psi. Ran tubing open-ended to 6000'. Circulate hole. Pressure test casing to 1000 psi. Pickle tubing with 250 gals acid. Spot 500 gals 15% HCL 5500' 6000'. POH with tubing. RU Wedge Wireline. RIH with GR-CCL. Tag cement at 6118'. Ran GR-CCL from 6118'-5500'. POH. RIH with 4" select fire casing gun and shot 1 SPF from 5565' 5886' (49 shots). Selector was wet. Wait to shoot the final 11 holes tomorrow AM. Secure well and SDFN.
- 8/4/96 Bled off pressure. PU casing gun, RIH and perf 1 SPF from 5890' 5975' (11 shots). FL at 1600' before and after perf. RD Wedge Wireline. RU 3½' tubing tools. Changed out BOP rams. Made up 5½' RTTS, SN, and cross-over on tubing. PU and run 24 joints and well started flowing. Well flowed 18 bbls of fluid to test tank in 1½ hours. Pump a total of 135 bbls 10# brine. Secured well and SDFN.
- 8/5/96 12 hour SITP=160, SICP = 180. Bled off gas cap and well died. RU HOWCO on tubing. Pumped 13 bbls 10# brine. RD from tubing and RU on casing. Set RTTS packer at 762'. Loaded annulus with 6 bbls brine, pressured annulus to 500 PSIG to test packer. Released packer. Continued PU 3½" tubing and RIH to 5458'. Set packer at 5458'. Loaded annulus with 6 bbls brine and pressured to 500 PSIG. RU on tubing and tested lines to 6000 PSIG. Opened well and acidized with 4000 gals 15% Ferchek acid and 120 1" ball sealers evenly spaced in acid. Achieved complete ball out after pumping 12 bbls flush. Broke HOWCO off tubing. Well was on slight vacuum. Dropped 2 7/8" SV and let fall. Tied HOWCO back on tubing. Loaded tubing with 3 bbls. Tested tubing to 6000 PSIG for 2 minutes. Bled off pressure and PU sandline. Fished SV. PU 17 joints of 3½" tubing and RIH to clear ball sealers. Pulled and LD 17 joints. Reset packer at 5458'. Loaded annulus with 13 bbls brine, pressured casing to 500 PSIG to check packer. RD and released HOWCO and transport. RU swab. Swabbed and flowed back 32 BLW in 3 hours.
- 8/6/96 RU Halliburton. Test lines to 7000 psi. Pressure annulus to 500 psi. Fracture treated perfs 5565'-5975' with 61,500 gals of x-linked gel with 175,000# sand. Total load 1657 bbls. Well on vacuum in 3 hours. Unseat RTTS and POOH with 3¹/₂" tubing. RIH with Baker Lok-set on 2 3/8" tubing. Set packer at 5466', SN at 5563'. ND BOP. NU wellhead. RU swab valves and choke. Secure well and SDFN.
- 8/7/96 SITP 820 psi. RU flowlines to separator and test tank. Start blowing well down through adjustable choke. Pressure stabilized at 350 psi on 26/64" choke. Well not making any fluid. Started getting sand at bleeder. Choke well back to 16/64" choke. FTP increased to 620 psi. Left well flowing to test tank on 16/64" choke for 2 hours. SWI to install positive choke. Choke full of sand and ball sealers. Cleaned out choke and flowline. Install 12/64" positive choke. Opened well to test tank. FTP 730 psi. Flowed well for 1 hour. Removed choke. Ceramic choke nipple indicated some minor abrasion due to sand. Re-install 12/64" choke and open well to test tank. FTP 730 psi. Flowed well for 2½ hours and SWI for night.
- 8/8/96 SITP 720 psi. Open well to test tank on 12/64" choke. Flowed well to test tank 6 hours. Well made 1 bbls of fluid in 6 hours. Switched well to test separator for 2 hours. Gas rate 518 MCFPD, no fluid. SWI.

8/10/96 Install steel line to separator and SDFN.

- 8/11/96. SITP 705 psi. Installed additional master valve on wellhead. Finish tie-in lines to sales line. Open well on 12/64" choke. Well flowing with FTP 675 psi. Gas rate GPM totalizer 380 MCFPD. No fluid in 10 hours.
- 8/12/96 Change choke to 14/64". Gas rate test meter 650 MCFPD, GPM total flow 535 MCFPD. Flow well on 14/64" choke for 6 hours, no fluid. Change choke to 16/64". Flow well 45 minutes on 16/64" choke and got sand to surface. Change choke back to 14/64". Flowed well 1 hour. Gas rate test meter 643 MCFPD, GPM total flow 538 MCFPD. Changed choke to 12/64" for overnight.