

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name W. W. Weatherly	
9. Well No. 2	
10. Field and Pool, or Wildcat Drinkard	
12. County Lea	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Sun Oil Company	3. Address of Operator P. O. Box 1861 Midland, Texas 79701	4. Location of Well UNIT LETTER <u>J</u> 1980 FEET FROM THE <u>South</u> LINE AND 1980 FEET FROM THE <u>East</u> LINE, SECTION <u>17</u> TOWNSHIP <u>21S</u> RANGE <u>37E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3471 GR			16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <u>Dual complete</u> <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Attempt dual completion by perforating in the Penrose Skelly Grayburg. Work to begin 3/31/71 per attached procedure :

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>RW Hughes</u>	TITLE <u>Proration Clerk</u>	DATE <u>April 1, 1971</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>SUPERVISOR DISTRICT</u>	DATE <u>APR 5 1971</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

APR 21 1971

OIL CONSERVATION COMM.  
HOBBBS, N. M.

W. W. WEATHERLY No. 2

Penrose Skelly (Graybury) Pool  
Lea County, New Mexico

PROGRAM PROCEDURE

1. MI - RU well service unit.
2. Kill Drinkard zone with 9.0#/gallon brine water.
3. Install BOP
4. Unlatch tubing anchor @ 6503' and POOH.
5. RU - Western and run gauge ring to 6560 (Drift ID 4.767" for 5 1/2" OD 17# casing) Run casing scraper if gauge ring will not run below 6560'.
6. Perforate with one hole at each of the following depths:  
3694, 96, 98, 3700, 02, 04, 20, 22, 24, 26, 28, 30, 32, 42, 44, 47,  
55, 57, 59, 61, 63 & 65. (Total 22 holes) Use Western M-1 select fire  
4" OD gun, (.49" hole)
7. Run Baker full-bore packer & model "C" retrievable bridge plug on 2 3/8" OD tubing. Set bridge plug at 3900'. Set packer at approximately 3800' and pressure test BP to 3500 psi.
8. Pull up and spot 200 gallons Western DS-30 (15% HCL) acid across perfs.
9. Pull up and set packer @ 3600'. Test casing to 3500' psi. Let acid soak 30 minutes to 1 hour.
10. Acidize perforations w/2,000 gallons DS-30 (15% HCL) acid. Treat in multiple stages using ball seals to assure that all of the holes are open and treated. Use Western Company for treatment.
11. Swab tubing down and conduct short swab test to check fluid entry.
12. Unseat packer and lower past perforations to assure that all ball seals are free. Circulate hole with gelled brine water mixed as described in step 15 (volume to 3700' is 90 bbls.)
13. Pull tubing and packer.
14. R-U Western Company to frac:  
Frac w/30,000 gallons gelled brine and 49,000# 20/40 sand. Gelled brine



W. W. Weatherly No. 2  
Program Procedure

- B) Pump 1000 gal. gelled water containing 500# 20/40 sand.
  - C) Pump 1000 gal. gelled water containing 1000# 20/40 sand.
  - D) Pump 1000 gal. gelled water containing 1500# 20/40 sand.
  - E) Pump 6000 gal. gelled water containing 12,000# 20/40 sand, drop 6 RCN ball sealers.
  - F) Pump 9000 gal. gelled water containing 16,000# 20/40 sand, drop 6 RCN ball sealers.
  - G) Pump 9000 gal. gelled water containing 18,000# 20/40 sand.
  - H) Flush with 100 barrels slick water.
15. Shut in for 2-3 hours or until pressure drops to zero.
  16. Run Baker FB packer and retrieving head.
  17. Set packer and swab test perforations 4 - 6 hours to clean up and stabilize frac sand.
  18. Kill well, unseat packer and reverse circulate sand off BP @ 3900'.
  19. Unseat BP and POOH.
  20. Run Baker Model "N" Mechanical Set Retainer Packer (Remove flapper valve before running) w/Model "D" Anchor Type Roto-Set Seal Assembly (two 14" seal assemblies containing 20 seals), seating nipple above seal assembly, 2860' of 2 1/16 OD tubing, Baker Model "D" parallel anchor and = 3690' of 2 1/16 OD tubing.
  21. Set Baker Model "N" Packer @ 6550.
  22. Unlatch Model "D" anchor seal assembly and circulate 60 barrels water followed by 70 barrels 9.5# brine water treated with 15 gallons Tretolite KW-12 followed by 19 barrels fresh water.
  23. Seat back into Model "N" Packer and set tubing in tension, 6000# over the weight of the tubing.
  24. Run the 2 1/16" OD short string w/J-latch and seating nipple and seat into Model "D" paralleled string anchor, set in tension, 6000# over the weight of the tubing.
  25. Install surface equipment.
  26. Swab both zones in for evaluation.

1

2

3