Submit 3 Copies To Appropriate District	State of New Mexico Energy, Minerals and Natural Resources OIL CONSERVATION DIVISION 2040 South Pacheco Santa Fe, NM 87505					Form C-103 Revised March 25, 1999						
1625 N. French Dr., Hobbs, NM 87240 District II 811 South First, Artesia, NM 87210 District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV 2040 South Pacheco, Santa Fe, NM 87505					5. I	WELL API NO. <u>30-025-20088</u> 5. Indicate Type of Lease STATE x FEE 6. State Oil & Gas Lease No.						
SUNDRY NOTIO (DO NOT USE THIS FORM FOR PROPO DIFFERENT RESERVOIR. USE: "APPLIC PROPOSALS.) 1. Type of Well:	ES AND REPORTS ON DSALS TO DRILL OR TO DEI CATION FOR PERM T [*] (FOR	PFN (BACK TO A JCH	7. I	Lease Na	me or U	Jnit Agr	eement Nam	ne:		
Oil Well 🗌 Gas Well 🕱	Other					EINICE COM						
2. Name of Operator					8. V	Vell No.						
Chevron U.S.A. Inc.					2	2						
3. Address of Operator					9. F	9. Pool name or Wildcat						
P.O. Box 1150 Midland, TX 79702 4. Well Location					EUM	EUMONT; YATES-7 RVRS-QUEEN (PRO GAS)						
	1980 feet from the	sot	TH	line and	560	fe	eet from	the	WEST	line		
Section 19	Township 21		Range	37E	NM	IPM		Count	V LEA			
	10. Elevation (Show wh											
11. Check A	ppropriate Box to Ind	icate	Nature	of Notice	, Rep	ort, or (Other I	Data				
NOTICE OF INTENTION TO: SUB						SEQUENT REPORT OF:						
	PLUG AND ABANDON		REMED	IAL WORK					RING CASIN	G 🗌		
	CHANGE PLANS		СОММЕ		ING O							
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING CEMEN	TEST AND)			ABANDONMENT				
OTHER:			OTHER:									
										LJ		

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

CHEVRON PROPOSES TO TA PER ATTACHED PROCEDURE

WELL WILL BE RETURNED TO PRODUCTION OR P&A'D WITHIN 90 DAYS

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE	TITLE REGULATORY O.A.	DATE _	10/16/01
Type or print name J. K. RIPLEY (This space for State use)		Telephone No.	(915)687-7148
APPROVED BY Conditions of approval, if any:	TITLE	DATE	

Eunice Com # 2 Eumont Field T21S, R37E, Section 19 Job: <u>Temporary Abandon Well</u>

Procedure:

<u>Note</u>: There is no remaining potential in the Eumont Gas (Yates - 7 Rivers - Queen) Pool. Therefore it is proposed to plug and abandon that zone and remove the wellbore from the Eunice Gas Com Unit. The wellbore will not be completely plugged at this time since it is being considered for recompletion deeper in the Blinebry. That completion would not be part of the unitized Eumont Gas interval and the well name would be Graham State I # 2 (100% Chevron).

- 1. MI & RU pulling unit. Bleed pressure from well, if any. Pump down tbg with 8.7 PPG cut brine water, if necessary to kill well. Remove WH. Install BOP's and test to 1000 psi.
- 2. Release 9 5/8" Guiberson Uni-VI pkr at 3294'. POH with 2 3/8" tbg string, on-off tool, and pkr. LD tbg string, on-off tool, and pkr while POH.
- 3. PU 8 ¾" MT bit and GIH on 2 7/8" work string to PBTD at 3599'. POH with 2 7/8" work string and bit. LD bit.
- 4. PU and GIH with 9 5/8" pkr on 2 7/8" work string to 3200'. Set pkr at 3200'. Pressure test csg and pkr to 500 psi. Establish pump-in rate into perfs 3374-3582' using cut brine water. Hold 500 psi on tbg/csg annulus during sqz job.
- 5. RU BJ Services cementing equipment. Cement squeeze perfs 3374-3582' using Class C cement mixed to 14.8 PPG w/ 1.32 CFY. Attempt to achieve at least 1500 psi squeeze pressure. Release pkr. Reverse out excess cement. PUH to approximately 3000'. Reset pkr at 3000' and pressure tbg and csg to 500 psi. RD and release BJ Services cementing equipment. Shut well in and WOC overnight.
- 6. Open well. Bleed off pressure. POH with 2 7/8" work string and sqz packer. LD pkr.
- PU and GIH with 8 ¾" MT bit on 2 7/8" work string to top of cement in csg at 3200'. Drill out cement to 3599'. Reverse circulate well clean from 3599' using 8.7 PPG cut brine. Pressure test casing and sqzd perfs to 500 psi. If perfs leak, repeat cmt sqz procedure.

- 8. Establish reverse circulation and displace cut brine from wellbore from 3599' using corrosion inhibited fresh water. POH with 2 7/8" work string and bit. LD work string and bit. Conduct MIT on csg and provide pressure test chart to NMOCD. <u>Note</u>: Provide 24 hrs. notice of MIT to NMOCD to provide opportunity to witness.
- 9. GIH with security pipe. Remove BOP's and install WH. RD & release pulling unit.

AMH 9/20/2001



By: A. M. Howell

Liner: 7' OD 23# J-55 Set: © 6673' w/ top @ 3601' Hole Size: 8 3/4" Circ: Yes TOC: 3601' (Top of liner) TOC By: Circulated

TD: 6700'

Updated: 9/20/2001

