

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. A-1375
7. Lease Name or Unit Agreement Name Wallace State
8. Well No. 7
9. Pool name or Wildcat Oil Center Blinbry
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3532 GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator Me-Tex Supply Company
3. Address of Operator P.O. Box 2070, Hobbs, NM 88240	4. Well Location Unit Letter E : 5610 Feet From The south Line and 330 Feet From The west Line Section 3 Township 21S Range 36E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3532 GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12/7 - POH w/tbg & rods. Tag PBDT @ 5920' RIH w/ bulldog bailer to 5921'. POH Unable to clean to btm. rig up reverse unit. SDFN
12/8 - Drill out to 5922'. Junk in hole. POH, RIH w/wash pipe. SDFN
12/9 - Drill w/wash pipe to 5923'. POH. Recover junk.
12/10- RIH w/3 3/8" bit, drill to 5940'. POH. Schlumberger perforate: 2JSPF - 5920, 22, 24, 26, 28, 30, 33 (14 holes) SDFN.
12/11- Acidize 5920-33. Communicate w/ old perfs 5882-5906. Acidize both perfs w/1800 gal. 15% NEFE acid.
12/12- Frac dwr. 4 1/2" csg w/30,000 gal. gel w/ 36,500# 20/40 sand @ 3200# 25 BPM.
12/13- Unable to reverse sand. RIH w/ drill bit. SDFN.
12/14- Drill sand to 5940'. SDFN.
12/15- RIH w/rods & pump set @ 5849'. Start pumping load water.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mark Veteto TITLE Vice-President DATE 12/28/89
TYPE OR PRINT NAME Mark Veteto TELEPHONE NO. 397-7750

ORIGINAL SIGNED BY JERRY SEXTON
(This space for State Use) DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

JAN 02 1990

RECEIVED

DEC 29 1981

OCD
HOBBS OFFICE