

WELL NO.	DATE	APP NO.	DISTRICT
Alved "A" 2	9-21-76	33-6046	Midland
Penrose Skelly (Grayburg)	Grayburg		TOTAL DEPTH

CONCESSION	SW/4, SW/4, Sec. 8, T-21-S, R-37-E, Lea County, New Mexico
DEPTH	
PRESENT	PREVIOUS
PLA	
PROCEDURE	REMARKS

- 1) Notify WMOCC 24 hours in advance.
- 2) Bleed tubing pressure down. It should not be necessary to kill well. It would swab down during test with pressure building up over-night.
- 3) Release packer and circulate hole with 9.5#/gal. or heavier mud.
- 4) Pull packer and tubing.
- 5) Set wireline CIBP at 3800'± and dump 35'+ of cement on top.
- 6) Cut 5-1/2" casing at free point and pull. A 100' cement plug is to be placed 50' in and 50' out of the 5-1/2" casing that remains in the hole.
- 7) Place a 100' cement plug from 1186' to 1286'.
 Note: The base of the salt is about 2650'. The WMOCC will require an additional cement plug to be placed across the base of the salt from 2600' to 2700' if casing is pulled from below that depth.
- 8) Place 10 sack cement at surface.
- 9) Weld steel plate on 8-5/8".
- 10) Place marker on well.