## Submit 3 copies

## State of New Mexico Minerals and Natural Resources Department

Form C-103

District Office	Energy, Minerals and No	atural Resources Department		Revised 1-1-8
<u>DISTRICT I</u>	OIL CONSERV	<b>ATION DIVISION</b>	IVVELL API NO.	
P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088			30-025-24	067
Santa Fe, New Mexico 87504-2088			5. Indicate Type of Lease	
P.O. Box Drawer DD, Artesia, NM	88210		STA	ATE 🗹 FEE 🗌
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 8	7410		6. State Oil / Gas Lease No.	
	Y NOTICES AND REPORTS O	N WELLS		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI (FORM C-101) FOR SUCH PROPOSALS.			7. Lease Name or Unit Agree W. A. RAMSEY (NCT-B)	ment Name
1. Type of Well: OIL WELL	GAS WELL OTHER			
Name of Operator     CHEVRON USA INC			8. Well No.	
Address of Operator			9. Pool Name or Wildcat TUBB & DR	INKARD
4. Well Location			· · · · · · · · · · · · · · · · · · ·	
Unit Letter <u>H</u>	:2310' Feet From The	NORTH Line and 430'	Feet From The EAST	Line
Section 25	Township 21-S	Range 36-E N	JPMLE	A COUNTY
	10. Elevation (Show whether	DF, RKB, RT,GR, etc.) 3531'		
11. Che	ck Appropriate Box to Indica	ate Nature of Notice, Report	, or Other Data	
NOTICE OF INTENTION TO:			JBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK			ALTERING CA	ASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OP	ERATION PLUG AND A	BANDONMENT
PULL OR ALTER CASING		CASING TEST AND CEME	AT JOB	
	SQZ BLINEBRY ZONE	✓ OTHER:		
Describe Proposed or Complet proposed work) SEE RULE 110 CHEVRON U.S.A. INTENDS TO GAS PRODUCTION FROM THE V	03. CEMENT SQUEEZE THE BLINEBI	RY PERFS IN ORDER TO SHUT		
				<b>,</b>
			4	<u>.</u> •
				r . ,
$\mathcal{L}$	$\mathcal{L}_{\mathcal{A}}$			
I hereby certify that the information above is true and of SIGNATURE	considere to be best of my knowledge and belief.  TITLE	Regulatory Specialist	DATE	10/1/2002

(This space for State Use)

TYPE OR PRINT NAME

APPROVED CONDITIONS OF APPROVAL, IF ANY:

ORIGINAL SIGNED BY TUTLEY W. WINK OC FIELD REPRESENTATIVE II/STAFF MANAGER

Denise Leake

DATE

915-687-7375

Telephone No.

W. A. Ramsey (NCT-B) # 6
Blinebry Field
T21S, R36E, Section 25
Job: Cement Sqz Blinebry Perfs To Shut Off Water

## Procedure:

- 1. Displace flowline with fresh water. Have field specialist close valve at header. Pressure line according to the type of line. AGU, EMSU, and EMSUB buried fiberglass lines will be tested with 300 psi. All polypipe(SDR7 and SDR11) will be tested w/100 psi. All steel lines will be tested w/500 psi. If a leak is found, contact Larry Williams for repair/replacement. If test is good, bleed off pressure and open valve at header. Document this process in the morning report.
- 2. MI & RU pulling unit. Bleed pressure from well, if any. Pump down csg with 2% KCl water, if necessary to kill well. POH with rods and pump. Remove WH. Install BOP's and test to 1000 psi. POH with 2 3/8" tbg string.
- 3. PU 3 ¼" blade bit and GIH on 2 3/8" tbg string to PBTD at 6776'. Reverse circulate well clean from 6776' using 2% KCl water. POH with 2 3/8" work string and bit. LD bit.
- 4. PU & GIH with 5 ½" sqz pkr and RBP on 2 7/8" work string to 5800'. Set pkr at 5800' with RBP swinging. Swab Tubb & Drinkard intervals together. Report recovered fluid volumes, pressures, and/or swabbing fluid levels. Release pkr. Set RBP at 5800' and pressure test to 2000 psi. PUH and set sqz pkr at 5200'. Pressure test pkr and csg to 500 psi. Leave pressure on casing while swabbing and cmt squeezing. GIH and swab Blinebry perfs. Report recovered fluid volumes, pressures, and/or swabbing fluid levels.
- 5. Pour 3 sks 20/40 sand down tbg and let fall to top of RBP at 5800'. Wait 1 hour for sand to fall. Establish injection rate into perfs 5513-5693'. Monitor csg pressure for communication.
- 6. RU DS Services cementing equipment. Cement squeeze perfs 5513-5693' using Class C cement mixed to 14.8 PPG w/ 1.35 CFY. Attempt to achieve at least 2000 psi squeeze pressure. Release pkr. Reverse out excess cement. PUH to approximately 5000'. Reset pkr at 5000' and pressure tbg and csg to 500 psi. RD and release DS Services cementing equipment. Shut well in and WOC overnight.
- 7. Open well. Bleed off pressure. POH with 2 7/8" work string and sqz packer. LD pkr.
- 8. PU and GIH with 4 ¾" MT bit on 2 7/8" tbg string to top of cement in csg at 5250'. LD and drill out cement to 5750'. Reverse circulate well clean from 5750' using 2% KCl water. Pressure test casing and sqzd perfs to 500 psi. If perfs leak, repeat cmt sqz procedure. LD and cleanout 5 ½" csg to top of sand on RBP at 5800'. Reverse circulate well clean from 5800' using 2% KCl water. POH with 2 7/8" work string and bit. LD bit.

- 9. PU retrieving head and GIH on 2 7/8" tbg string to top of RBP at 5800'. Reverse circulate sand from top of RBP. Engage and release RBP at 5800'. POH with 2 7/8" tbg string and RBP. LD 2 7/8" work string, RBP, and retrieving head.
- 10. PU and GIH w/ BP mud anchor jt of 2 3/8" tbg, 2 3/8" x 4' perforated sub, SN, 40 jts 2 3/8" EUE 8R J-55 tbg, TAC, and 177 jts 2 3/8" EUE 8R J-55 tbg, testing to 5000 psi. Set TAC at 5500' with EOT suspended at 6750' and SN at 6715'. Note: All tbg below 5800' must have special clearance couplings due to the 4" liner.
- 11. Remove BOP's and install WH. GIH with rods, weight bars, and pump per ALS recommended design. RD & release pulling unit.
- 12. Turn well over to production. Report producing rates and fluid levels.

AMH 9/26/2002

By: K. M. Jackson

Field: Blinebry, Tubb,

linebry, Tubb, &

Reserv.

Well: W. A. Ramsey

JT-B) #6

Updated: 3/20/01

By: K. M. Jackson

Updated: 9/25/02