

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2038
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name Eunice Monument S.
Name of Operator Chevron U.S.A. Inc.	8. Farm or Lease Name Unit
Address of Operator P.O. Box 670, Hobbs, NM 88240	9. Well No. 194
Location of Well UNIT LETTER G 2254 FEET FROM THE North LINE AND 2080 FEET FROM THE East LINE, SECTION 6 TOWNSHIP 21S RANGE 36E N.M.P.M.	10. Fluid and Pool, or Wildcat Eunice Monument SA/G/
11. Elevation (Show whether DF, RT, G.L., etc.)	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

REFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
IMPROVING ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
ILL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	
		OTHER add perfs, acdz, rtn to prod. ☐	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD: 4200 PB: 4054

POH w/pump and rods, ND WH, NU BOP, POH w/ prod. tbg, Tagged CIBP at 3928', Drill on CIBP to 4148. Perf 4084-4096 (zone 5), 3851-3864 & 3828-3844 (zone 2) 3817-3823, 3799-3810, 3774-3787 (zone 1) 1 SPF, 180° phase, 4" guns, total 71 holes. TIH w/ pkr to 4096, set pkr at 4055. Acdz w/1150 gallons 15% NEFE HCL. Swab. Rlse pkr, TOH, PU 5 1/2" cmt ret on 2 7/8 WS to 4054. Pmp thru cmt ret, squeeze perfs 4084-96 w/100sx Cl C. Displaced w/ FW. Sting out of ret. WOC 22 hrs. TIH, tagged cmt at 3520'. Drlg-soft cmt 3520-3650, drlg firm cmt 3650-4054, circ hole clean. Test csg to 400psi, for 20 min. Displace hole w/ CKF. Perf zone 4 3992-94, 4002-04, 4009-11, 4018-20 (8 holes) 1 JHPF 4" guns, 18-° phase, TIH w/ pkr and set same at 3980', load BS to 400psi. Tst tbg to 3000psi, ok. Acidize w/ 600 gal 15% NEFE HCL, swab. Perforate zones 1-3, 3774-87, 3799-3810, 3817-23, 3828-44, 3851-64, 3891-93, 3900-02, 3911-13, 3938-40, 3944-46, 3952-54, 3960-62, 3968-70, 1 SPF, 180° phase, 75 holes. TIH w/ pkr and RBP, set RBP at 3984. Acdz w/ 5600 gallons 15% NEFE HCL zones 1-3, perfs 3774-3970, Tailed w/ CKF. Swab. Run 2 3/8" J-55 EUE, to 3936'. ND BOP, NU WH, and pmp tee. Run pmp equip., RU Pmp Unit and tst pmp to 50opsi, ok. RD MO PU. Work performed 1-13-88 through 1-21-88.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signature: Jerry Sexton TITLE: Staff Drilling Engineer DATE: Jan. 29, 1988
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT SUPERVISOR
COPIES BY: _____ TITLE: _____ DATE: FEB 2 - 1988
ADDITIONS OF APPROVAL, IF ANY:

RECEIVED
FEB 1 1988
OCD
HOBBS OFFICE