Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

CONDITIONS OF APPROVAL, IF ANY:

OIL CONSERVATION DIVISION P.O. Box 2088

WELL API NO. 30-025-30098

		Danie 1	Fe, New Mexico				
P.O. Drawer DD	D, Artesia, NM 88210			0750 7 2000	5. Indicate Type of	1 1 :	[
DISTRICT III 1000 Rio Brazo	Rd., Aziec, NM 17410				6. State Oil & Ga	STATE	FEE X
	SE THIS FORM FOR PR DIFFERENT RESE (FORM C	OPOSALS TO DR	PLICATION FOR PE	OR PLUG BACK TO A	7. Lease Name or	r Unit Agreement Name	
1. Type of We of We well X	ii: Gai: Weil		OTHER		J. A. A	kons	
2. Name of Op		 			8. Well No.	ikeris	
Oryx Er 3. Address of (nergy Company					5	
	Box 1861, Midla	ınd, Texas	79702		9. Pool name or V	wildcat Ibb-Drinkard	
4. Well Location	00.						
Unit L	etter R : 23]	. C Feet From Th	e South	Line and1650	O Feet From	n The East	Line
Section	a 3	Township	21-S R	nge 36-E	NMPM Le	va.	6
			evation (Show whether	DF, RKB, RT, GR, etc.)	INITIAL CC		County
		/////	3543.3' GR				
11.	Check	Appropriate E	Box to Indicate I	Nature of Notice, R			
	NOTICE OF IN	IENTION IC):	SUB	SEQUENT R	REPORT OF:	
EDECIDIA DEL	MEDIAL WORK	PILIC AND	ABANDON	REMEDIAL WORK	X	ALTERING CASING	
ENFORM NEW		r LOG AND					
		CHANGE P	LANS		G OPNS	PILIC AND ARANDO	NIMENT
TEMPORARILY	ABANDON		PLANS	COMMENCE DRILLING		PLUG AND ABANDO	NMENT
TEMPORARILY	ABANDON		PLANS	COMMENCE DRILLING		PLUG AND ABANDO	NMENT [
PULL OR ALTER	ABANDON	CHANGE P		COMMENCE DRILLING CASING TEST AND CE OTHER:	EMENT JOB		NMENT
PULL OR ALTER OTHER:	ABANDON	CHANGE P		COMMENCE DRILLING	EMENT JOB		NMENT .
PULL OR ALTER DTHER:	ABANDON	CHANGE P		COMMENCE DRILLING CASING TEST AND CE OTHER:	EMENT JOB		NMENT
PULL OR ALTER DTHER: 12 Describe Pro work) SEE I	ABANDON	CHANGE P	all pertinent details, an	COMMENCE DRILLING CASING TEST AND CE OTHER: d give pertinent dates, inclu	EMENT JOB	f starting any proposed	
PULL OR ALTER DTHER:	ABANDON	CHANGE P	all pertinent details, an	COMMENCE DRILLING CASING TEST AND CE OTHER:	EMENT JOB	f starting any proposed	
PULL OR ALTER DTHER:	ABANDON Proceed or Completed Opera RULE 1103. Press test the out paraffin.	tions (Clearly state of the 4000 pt to 4000 pt to 5000	all pertinent details, and osi OK, POH were on 2-7/8"	COMMENCE DRILLING CASING TEST AND CE OTHER: d give pertinent dates, inclu	eding estimated date of	f starting any proposed S off top to	steam
PULL OR ALTER DTHER: 12 Describe Prowork) SEE I Stim 11/28/90 11/29/90	ABANDON PRICASING Proceed or Completed OperaRULE 1103. Press test the out paraffin. RIH w/4-3/4" 2% KCL wtr. FIH w/5-1/2" Acdz perfs 64	g to 4000 p bit, scrape Wouldn't ci Model R Pkr 74'-6880' w	all persinent details, and persinent details,	COMMENCE DRILLING CASING TEST AND CE OTHER: d give pertinent dates, included 1/2-7/8" prod the	ement Job ding estimated date of the control o	s off top to). Pump 250	steam
PULL OR ALTER DTHER:	ABANDON R CASING Prosed or Completed Opera RULE 1103. nulate perfs. Press test the out paraffin. RIH w/4-3/4" 2% KCL wtr. FIH w/5-1/2" Acdz perfs 64 mixture in 3 T PBTD @ 68 5-1/2" TAC on	g to 4000 p bit, scrape Wouldn't ci Model R Pkr 74'-6880' w stages. Fl 90'. POH w/	all persinent details, and persinent details,	COMMENCE DRILLING CASING TEST AND CE OTHER: d give pertinent dates, include 1/2-7/8" prod the tba. Tag fill 5'. RU HOWCO, NEFEHCL & 6000 CL w/additives. tbg. & Pkr, TIH	ement Job ding estimated date of the control o	s off top to). Dump 250 g to 1000 psi acid/xylene	steam bbl.
EMPORARILY PULL OR ALTEI DTHER: 12 Describe Pro work) SEE I Stim 11/28/90 11/29/90 11/30/90 12/1/90	ABANDON R CASING Prosed or Completed Opera RULE 1103. nulate perfs. Press test the out paraffin. RIH w/4-3/4" 2% KCL wtr. FIH w/5-1/2" Acdz perfs 64 mixture in 3 T PBTD @ 68 5-1/2" TAC on	g to 4000 p bit, scrape Wouldn't ci Model R Pkr 74'-6880' w stages. Fl 90'. POH w/ 2-7/8" pro	all perinent details, and perinent details, and perinent details, and per on 2-7/8" frc. Set @ 641 15% ushed w/2% K 22-7/8" product bg TS 675 pump on 76 ro	commence drilling casing test and ce other: d give pertinent dates, included the comment dates, included the comm	ement Job ding estimated date of the control o	s off top to). Dump 250 g to 1000 psi acid/xylene	steam bbl.
PULL OR ALTER DTHER:	ABANDON R CASING Proced or Completed Opera RULE 1103. Pulate perfs. Press test the out paraffin. RIH w/4-3/4" 2% KCL wtr. FIH w/5-1/2" Acdz perfs 64 mixture in 3 T PBTD @ 68 5-1/2" TAC on w/2-1/2" x 1-	change P stions (Clearly state of g to 4000 p bit, scrape Wouldn't ci Model R Pkr 74'-6880' w stages. Fl 90'. POH w/ 2-7/8" pro 1/2 x 16' p 6 BW 84 MC	all periment details, and periment details,	commence drilling casing test and ce other: d give pertinent dates, included the comment dates, included the comm	ement Job ding estimated date of the control o	s off top to). Dump 250 g to 1000 psi acid/xylene	steam bbl.
PULL OR ALTER DTHER:	ABANDON PR CASING Proceed or Completed Opera RULE 1103. Pulate perfs. Press test the out paraffin. RIH w/4-3/4" 2% KCL wtr. FIH w/5-1/2" Acdz perfs 64 mixture in 3 T PBTD @ 68 5-1/2" TAC on w/2-1/2" x 1-24P 46 BO 11	change P stions (Clearly state of g to 4000 p bit, scrape Wouldn't ci Model R Pkr 74'-6880' w stages. Fl 90'. POH w/ 2-7/8" pro 1/2 x 16' p 6 BW 84 MC	all periment details, and periment details,	COMMENCE DRILLING CASING TEST AND CE OTHER: d give pertinent dates, include 1/2-7/8" prod the tba. Tag fill 5'. RU HOWCO, NEFEHCL & 6000 CL w/additives. tbg. & Pkr, TIH O', MA 6717', S d string. well	ement Job	s off top to). Pump 250 g to 1000 psi acid/xylene set-up & Bake C @ 6452'. TII test @ 6 PM 1	steam bbl. r H 1/30/90.
PULL OR ALTER THER: 12 Describe Prowork) SEE I Stim 11/28/90 11/29/90 12/1/90 12/6/90 I hereby certify the	ABANDON R CASING Proced or Completed Opera RULE 1103. Pulate perfs. Press test the out paraffin. RIH w/4-3/4" 2% KCL wtr. FIH w/5-1/2" Acdz perfs 64 mixture in 3 T PBTD @ 68 5-1/2" TAC on w/2-1/2" x 1- 24P 46 BO 11 at the information above is true	g to 4000 p bit, scrape Wouldn't ci Model R Pkr 74'-6880' w stages. Fl 90'. POH w/ 2-7/8" pro 1/2 x 16' p 6 BW 84 MC	all persinent details, and persinent details, and persinent details, and persinent details, and person 2-7/8" arc. The Set @ 641 w/340 gal 15% ushed w/2% K w/2-7/8" product bg TS 675 pump on 76 roump on 76 rou	COMMENCE DRILLING CASING TEST AND CE OTHER: d give pertinent dates, include 1/2-7/8" prod the tba. Tag fill 5'. RU HOWCO, NEFEHCL & 6000 CL w/additives. tbg. & Pkr, TIH O', MA 6717', S d string. well	ement Job	s off top to). Dump 250 g to 1000 psi acid/xylene	steam bbl. r H 1/30/90.