

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-34538

5. Indicate Type of Lease

STATE ☒

FEE

6. State Oil & Gas Lease No

7. Lease Name or Unit Agreement Name

Range 28 State Com.

8. Well No.

1

9. Pool name or Wildcat

Grama Ridge Morrow East

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☐

GAS
WELL ☐

OTHER Dry Hole

2. Name of Operator

Nearburg Producing Company

3. Address of Operator

PO Box 823085, Dallas Texas 75382-3085

4. Well Location

Unit Letter G : 1980 Feet From The North Line and 165C Feet From The East Line

Section 28

Township 21S

Range 35E

NMPM

Lea

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3591 Gr.

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Load hole with brine based mud. Spot 25 sx. cement plug on BP set at 10,500'.
Set CIBP @ 10,150' cap with 35' cement. (Dump bailer)
Set CIBP @ 7734', cap with 35' cement (Dump bailer)
Cut and pull 7", casing at 6700' (TOC 6767' by Temp survey)
Set 100' cement plug at stub, 50' in and 50' out. WOC TAG PLUG.
Set 100' cement plug @ base of 9 5/8" (5570') 50' in and 50' out.
Set 100' cement plug @ base of salt 3,500' to 3,600'.
Set 100' cement plug @ base of 13 3/8" (1350) 50' in and 50' out.
Set 10 sack surface plug, set dry hole marker.
Remove deadmen, back fill working pit and clean location.

THIS CONVICTION MUST BE NOTIFIED 24
HOURS BEFORE THE BEGINNING OF
PLUG & OPERATIONS FOR THE C-103
TO BE APPROVED

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Eddie J. Beland

TITLE Operations coordinator

DATE 3-29-99

TYPE OR PRINT NAME

TELEPHONE NO

(This space for State Use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

JP

CP