Submit 3 copies to Appropriate Energy, Minerals and Natural Resource District Office	es Department Form C-103 Revised 1-1-89			
DISTRICT OIL CONSERVATION	DIVISION WELL API NO.			
P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088	30-025-35453			
DISTRICT II Santa Fe, New Mexico 875				
P.O. BOX Drawer DD, Artesia, INMI 60210	STATE FEE V			
DISTRICT III	6. State Oil / Gas Lease No.			
1000 Rio Brazos Rd., Aztec, NM 87410				
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR I				
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI	1. Lease Manie of Onic Agreement Mane			
(FORM C-101) FOR SUCH PROPOSALS.	EUNICE MONUMENT SOUTH UNIT			
1. Type of Well: OIL GAS WELL OTHER				
2. Name of Operator CHEVRON USA INC	8. Well No. 614			
3. Address of Operator 15 SMITH ROAD, MIDLAND, TX 79705	9. Pool Name or Wildcat EUNICE MONUMENT GRAYBURG S/A			
4. Well Location				
Unit Letter :3655Feet From TheNORTH	e and <u>85'</u> Feet From The <u>EAST</u> Line			
Section 6 Township 21-S Range	36-ENMPMLEA_ COUNTY			
10. Elevation (Show whether DF, RKB, RT,GR, etc.)				
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data				
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:			
	DIAL WORK ALTERING CASING			
	G TEST AND CEMENT JOB			
OTHER: PERF, ACIDIZE, & CLEAN OUT				

^{12.} Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

CHEVRON U.S.A. INTENDS TO PERFORATE, ACIDIZE & CLEAN OUT THE SUBJECT WELL.

THE INTENDED PROCEDURE AND WELL BORE DIAGRAM IS ATTACHED FOR YOUR APPROVAL.

i hereby certify that the information above is true and co SIGNATURE		DATE	
TYPE OR PRINT NAME	Denise Leake	Telephone N	lo. 915-687-7375
(This space for State Use) APPROVED CONDITIONS OF APPROVAL, IF ANY:	ORIGINAL SIGNED BY GARY W. WINK OC FIELD REPRESENTATIVE ILISTAFE MANIACEP	DATE	2 4 2003

ر دور درو EMSU # 614 API # 30-025-35453 3655' FNL & 85' FEL S6, T21S, R36E, & Unit I Eunice Monument South Unit Lea County, New Mexico

PROCEDURE TO CLEAN OUT, PERF, AND ACIDIZE

- 1. Verify anchors have been set & tested. Test flowline as per below procedure
- 2. MIRU PU. ND WH. NU BOP.
- 3. TOH w/ rods, pump and 2-7/8" tubing .
- 4. TIH with 6-1/8" bit and casing scraper to TD at 4020'. Drill out to 4040'. Circ clean and POOH.
- 5. Rig up wireline Co. Perf as follows with 3 jspf using a 4" HSCG w/120 deg phasing. (perfs picked from Schlumberger Compensated Neutron Density Log dated 5/9/2001)

ensated required	Densit
4014-34	20'
3980-86	6`
3966-72	6`
3820-36	16`
3810-16	6`

- 6. TIH with 7" packer and set packer at 4000'.
- 7. Rig up DS. Acidize perfs 4014-34' as follows:
 - 1000 gals 15% acid with 90 ball sealers stage as per attached DS recommendation
- 8. Swab back spent acid. Monitor fluid level and cut. If not productive set CIBP at 4000'.
- 9. Release packer and set at 3750'.
- 10. Rig up DS. Acidize perfs 3810-4034' as follows:
 10000 gals 15% 50 quality foamed HCl acid with 75 ball sealers in four stages as per attached DS recommendation
- 11. Swab back spent acid. Monitor fluid level and cut.
- 12. TIH with production tubing and pumping equipment.
- 13. ND BOP. NU WH. RD PU.
- 14. Place well back on production.

Note:

If scale is found samples are to be sent to Baker Petrolite and DS for analysis prior to stimulation. A scale squeeze may be performed if necessary.

DS to obtain oil sample from well to determine sludging tendency.

Displace flowline with fresh water. Have field specialist close valve at header. Pressure line according to the type of line. AGU, EMSU, and EMSUB buried fiberglass lines will be tested with 300 psi. All polypipe (SDR7 and SDR11) will be tested w/100 psi. All steel lines will be tested w/500 psi. If a leak is found, contact Larry Williams for repair/replacement. If test is good, bleed off pressure and **open valve** at header. Document this process in the morning report.

Kevin Hickey 915-687-7260

File MAR

