

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other Instructions on reverse side)

Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

LC-063228

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Fields Federal

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Triste Draw Delaware

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 25, T-23-S, R-32-E NMMPM

12. COUNTY OR PARISH

LEA

13. STATE

NM

1. OIL WELL ☐ GAS WELL ☐ OTHER SWD Well

2. NAME OF OPERATOR

Estacado, Inc.

3. ADDRESS OF OPERATOR

P. O. Box 5587, Hobbs, New Mexico 88241

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface

990' FSL & 330' FWL
UNIT LETTER "M"

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GK, etc.)

3713 DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

REVISED

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☒

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

PROCEDURES

1. Move in and rig up plugging equipment. Dig work pit. Install BOP
2. Pick up workstring. RIH & tag CICR at 5000' & spot a 35' cmt plug.
3. PUH to 4900' \pm mix 10# mud & circulate the hole.
4. PUH to 4765' \pm (Base of Salt) & spot a 100' cmt plug, POOH w/tubing
5. Rig up wireline. Perf casing at 1175' \pm (T/Rustler 1208')
6. Establish circulation down through 4 1/2" casing & up 4 1/2" / 7 5/8" annulus
7. Fill casing with cmt. inside and out from perfs to the surface.
8. Cut off wellhead 3' below ground level and install dry hole marker.

RECEIVED
DEC 19 2 25 PM '88

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE President

DATE 12/15/88

(This space for Federal or State office use)

ORIG. SEC. BUREAU
APPROVED BY
CONDITIONS OF APPROVAL, IF ANY

TITLE

DATE

1-6-89

Subject to
Like Approval
by State

*See Instructions on Reverse Side