

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name Seven Rivers Queen Unit	
2. Name of Operator Atlantic Richfield Company		8. Farm or Lease Name Seven Rivers Queen Unit	
3. Address of Operator P. O. Box 1710, Hobbs, New Mexico 88240		9. Well No. 10	
4. Location of Well UNIT LETTER <u>J</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>27</u> TOWNSHIP <u>22S</u> RANGE <u>36E</u> NMPM.		10. Field and Pool, or Wildcat Eunice 7Rivers Queen So.	
15. Elevation (Show whether DF, RT, GR, etc.) 3505' GR		12. County Lea	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 3815', PBD 3812'. Present perfs 3722-3756'. Propose to add perfs, acidize & frac in the following manner:

1. POH w/completion assy.
2. CO to PBD w/sd pump.
3. Run bit & scraper to PBD.
4. Perforate w/l JSPPF 3782-86' & 3788-98'.
5. Run trtg pkr on 2-7/8" tbg.
6. Spot 1000 gals 15% HCL-LSTNE acid across perfs 3782-3798'.
7. Set pkr @ 3600'.
8. Frac perfs 3722-3798' w/40,000# 20/40 sd in 40,000 gal slick 9# brine in 4 stages using rock salt & benzoic acid to divert.
9. POH w/pkr, clean out to PBD. Run completion assy & return to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED _____ Dist. Brlg. Supv.

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: