

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL ☐ GAS ☐ OTHER- WIW		7. Unit Agreement Name Seven Rivers Queen Unit
2. Name of Operator ARCO Oil and Gas Company Division of Atlantic Richfield Company		8. Farm or Lease Name Seven Rivers Queen Unit
3. Address of Operator P. O. Box 1710, Hobbs, New Mexico 88240		9. Well No. 3
4. Location of Well UNIT LETTER C 660 FEET FROM THE North LINE AND 2080 FEET FROM THE West LINE, SECTION 27 TOWNSHIP 22 RANGE 36 NMPM.		10. Field and Pool, or Wildcat Eunice 7R On So.
15. Elevation (Show whether DF, RT, GR, etc.) 3502.1' GR		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☒	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

- RU, install BOP & POH w/injection assy.
- RIH w/RBP & pkr. Set BP @ top of liner approx 3400'. Spot 2 sx sd on top. Set pkr & locate holes in csg.
- Set cmt retr above holes in csg & cmt squeeze w/C1 H Neat cmt. WOC 24 hrs.
- RIH w/bit & DO cmt retr & cmt. Press test squeeze job. Circ sd off RBP. Rec BP. PB w/sd to 3725'. Rem BOP & install well head.
- Pump 8000 gals K-Trol treatment & displ to 3600' w/2% KCL, all cont'g additives. SIW for 5 days for polymerization.
- Remove wellhead, install BOP & POH w/tbg & pkr. CO K-trol & sd to 3782' PBD.
- Spot 15% NEFE acid 3730-3782'. RIH w/pkr & set @ approx 3725'; if communication occurs move pkr to 3714'. Spot 15% NEFE acid 3782-3730' & displ w/5 bbls of inj water thru coiled tbg. Pull coiled tbg to 3730' & acidize w/2000 gals 15% NEFE. POH w/coiled tbg. Swab back load.
- RIH w/pkr & tbg, load tbg/csg annulus w/trtd FW, set pkr above perms & return to injection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Eddie W. Seay TITLE Drlg. Engr. DATE 10/24/84
APPROVED BY Oil & Gas Inspector TITLE _____ DATE OCT 29 1984
CONDITIONS OF APPROVAL, IF ANY: