

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE  
(Other instructions on reverse side)

Budget Bureau No. 1004-1  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL

LC-030133B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Cenoco Inc.

3. ADDRESS OF OPERATOR

P.O. Box 460 - Hobbs, NM 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface

Unit M 660/S + W

14. PERMIT NO.

30-025-09127

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Meyer B-33

9. WELL NO.

#1

10. FIELD AND POOL OR WILDCAT

Jalmat Yates Gas

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

33 T22S R36E

12. COUNTY OR PARISH 13. STATE

Oke NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

See Attached Wellplan

18. I hereby certify that the foregoing is true and correct.

SIGNED

*W.W. Baker*

TITLE

Adm. Supervisor

DATE

10/10/89

(This space for Federal or State office use)

Orig. Signed by Adam Salameh

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

PETROLEUM ENGINEER

DATE

11-6-89

\*See Instructions on Reverse Side

2. Marker must be capped and inscribed with the following well information:

Meyer B-33 No. 1  
Unit M, Sec. 33, T-22S, R-36E  
Lea County, NM  
Date

- Note: 1/4" metal plate can be welded to marker and then to the casing after the marker is set in cement.  
E. Cut off dead-man anchors below ground level and remove markers.  
F. Fill in cellar and workover pit.  
G. Remove all equipment, concrete bases, and pipe not in use.  
Clean and restore location to its natural state. Reseed according to BLM requirements.

5. Send a copy of the well service report to Kandy Lawson in the Hobbs Office so the proper forms can be filed.

Approved:

Tom C. Edwards  
Engineering Technician

9-18-85  
Date

Joe V. Allen  
Engineer

9-18-85  
Date

Chad A. O'Neil  
Supervising Production Engineer

9-29-85  
Date

William L. Muehlen  
Division Engineering Manager


9-29-85  
Date

Alvin B.  
Production/Supervisor

10/2/85  
Date

TCA:mjm  
MEY33-L-PRO

MEYER B-33 No. 1



MEYER B-33 NO. 1  
PLUG AND ABANDON

Location: 660' FSL & 660' FWL, Sec. 33, T-22S, R-36E  
Lea County, NM

Elevation: 3469' DF (6' AGL)

Completion: Jalmat Yates  
TD: 3548' PBTD: 3200'  
Perfs: 3056'-91', 3102'-10', 3120'-34', 3144'-57',  
3170'-80' w/3 JSPF

Baker Model "D" permanent packer set at 2895'.

Casing/Tubing Specifications:

| O.D.<br>(in) | Weight<br>(lbs/ft) | Grade | Depth<br>(ft) | Drift<br>(in) | Collapse<br>(psi) | Burst<br>(psi) | Capacity<br>(bbl/ft) | Capacity<br>(ft/ft) |
|--------------|--------------------|-------|---------------|---------------|-------------------|----------------|----------------------|---------------------|
| 10-3/4"      | 40.5               | H-40  | 303           | 9.894         | 1,420             | 2,280          | .0981                | .5508               |
| 5-1/2"       | 17.0               | J-55  | 3508          | 4.767         | 4,910             | 5,320          | .0232                | .1305               |
| 2-7/8"       | 6.5                | N-80  | 2,347         | 11,160        | 10,570            |                | .00579               | .03250              |

10-3/4" casing set @ 303' with 200 sx cement circulated to surface.  
5-1/2" casing set @ 3508' with 500 sx cement. TOC @ 2285' by  
temperature survey.  
Use safety factor of 70% for collapse and burst pressures.  
Assume 2-7/8" workstring will be used.

Notes: 1. All cement slurry used in this procedure shall be Class "C"  
neat mixed @ 14.8 ppg.  
2. All mud shall be 10 ppg with 25 lbs gel/bbl brine.  
3. Notify BLM prior to commencing any work.

Recommended Procedure:

1. Prepare well for P&A:
  - A. MIRU. Bleed well pressure down. Kill well with 10 ppg brine if needed.
  - B. ND wellhead and NU BOP.
  - C. Sting out of Baker Model "D" packer at 2895'. If this fails, RU wireline services and cut production tubing off at packer.
  - D. TOOH and LD 2-7/8" production tubing.
  - E. PU and TIH w/4-3/4" bit, 5-1/2" casing scraper, and 2-7/8" workstring to 2895'. POOH.
2. Pump bottom cement plugs:
  - A. MIRU cement services.

MEYER B-33 NO. 1  
PLUG AND ABANDON  
PAGE 2

B. GIH w/5-1/2" cement retainer, setting tool, and WS. Set cement retainer @ 2860'.

1. Test tubing to 1000 psi.
2. Sting out of retainer and circulate hole with 65 bbls mud. Test casing to 500 psi.
3. Sting back into retainer.

C. Pump 65 sx cement to fill up 5-1/2" casing from 3200' to 2860'; Pump 10 bbls water to establish rate, cement, and displace with 11 bbls mud.

D. Sting out of retainer and spot remaining 25 sx of cement on top (TOC @ 2607').

E. POOH laying down WS to 1535'.

F. Pump 10 sx cement and displace with 8 bbls mud to spot plug across top of salt from 1535' to 1434'.

G. POOH laying down WS.

3. Circulate cement up surface casing and set surface plug:

A. MIRU wireline services.

B. RIH with a 4" casing gun loaded 4 JSPF (120" phase, .4" EHD, centralized) and CCL.

C. Perforate 5-1/2" production casing @ 353'. POOH.

D. GIH w/1 joint 2-7/8" tubing. Close BOP. Pump 35 bbls mud to load hole and establish circulation up 10-3/4" x 5-1/2" annulus.

E. Pump 150 sx cement (22 sx excess) to fill up 10-3/4" x 5-1/2" annulus and set surface plug in 5-1/2" casing.

Note: If cement does not circulate to surface, pump 25 sx down 10-3/4" x 5-1/2" annulus.

F. POOH with tubing.

G. RD wireline and cement services.

4. Prepare surface location for abandonment:

A. ND BOP and cut off all casing strings at the base of the cellar or 3' below the final restored ground level (whichever is deeper). RMO pulling unit.

B. Fill the casing strings (if necessary) from the cement plug to surface with cement.

C. Cover the wellbore with a metal plate at least 1/4" thick, welded in place, or a cement cap extending radially at least 12" beyond the 10-3/4" casing and at least 4" thick.

D. Erect an abandonment marker according to the following specifications:

1. Marker must be at least 4" diameter pipe, 10' long with 4' above restored ground level, and embedded in cement.