

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name Seven Rivers Queen Unit
2. Name of Operator Atlantic Richfield Company		8. Farm or Lease Name Seven Rivers Queen Unit
3. Address of Operator P. O. Box 1710, Hobbs, New Mexico 88240		9. Well No. 30
4. Location of Well UNIT LETTER <u>L</u> <u>2310</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>35</u> TOWNSHIP <u>22S</u> RANGE <u>36E</u> NMPM.		10. Field and Pool, or Wildcat Eunice 7Rivers Queen So.
15. Elevation (Show whether DF, RT, GR, etc.) 3493' GR		12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 4010', PBD 4000'. Present perms 3686-3702, 3712-18 & 3758-72'. Propose to add perms in same formation, acidize & frac in the following manner:

1. POH w/completion assy.
2. Run bit & scraper to PBD or 3700'.
3. Run 500' of GR Corr log. Perf w/l JSPF 3648-56' & 3659-65'.
4. Run ret BP & pkr, set BP @ 3675'.
5. Spot acid across perms 3648-65' & acidize w/1000 gals 15% HCL-LSTNE acid & ball sealers.
6. Pull ret BP & pkr.
7. Run trtg pkr on 2-7/8" tbg & set @ 3550'.
8. Frac perms 3648-3772' w/40,000# 20/40 sd in 40,000 gals slick 9# brine in 4 stages, using rock salt & benzoic acid to divert.
9. Swab back load. POH w/pkr & CO to PBD.
10. Run completion assy & return to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>[Signature]</u>	TITLE <u>Dist. Dir. SDA.</u>	DATE <u>11/18/71</u>
APPROVED BY <u>[Signature]</u>	TITLE <u></u>	DATE <u></u>
CONDITIONS OF APPROVAL, IF ANY:		