

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-229	
7. Unit Agreement Name	
8. Farm or Lease Name	
Seven Rivers Queen Unit	
9. Well No.	
53	
10. Field and Pool, or Wildcat	
Langlie Mattix 7R Qn	
12. County	
Lea	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- WIW
2. Name of Operator ARCO Oil and Gas Company Division of Atlantic Richfield Company
3. Address of Operator P. O. Box 1710, Hobbs, New Mexico 88240
4. Location of Well UNIT LETTER E 1980 FEET FROM THE North LINE AND 660 FEET FROM THE West LINE, SECTION 2 TOWNSHIP 23S RANGE 36E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3470' GR

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The casing on this WIW has corroded beyond repair. Propose to plug and abandon in the following manner:

1. RU, bleed csg pressure down, install BOP & POH w/inj assy.
2. Set cmt retr @ 3551' & pump 2000 gals injectrol G followed by 5 bbls fresh water spacer & cmt squeeze w/100 to 200 sx Cl H cmt. PO of retr & spot 35' cmt on top of retr.
3. Displ hole w/9.5# brine cont'g 25# (100#) sx of salt gel per 100 bbls.
4. Spot cmt plug 3000'-2900'. Spot cmt plug 1325-500'. Spot 10 sx cmt @ surf.
5. Cut off wellhead below GL, weld on plate & install regulation dry hole marker.

Above procedures approved by Mr. Jerry Sexton, NMOCD on January 4, 1984 @ 8:45 AM.

TO BE COMPLETED BY THE OPERATOR  
PLUG AND ABANDONMENT  
TO BE COMPLETED BY THE OPERATOR

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Jerry Sexton</u>	TITLE <u>DRLG. ENG.</u>	DATE <u>2/27/84</u>
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR		MAR 5 1984