

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

3. DEPARTMENT OF THE INTERIOR
(Other instruction on reverse side)

Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Salt water disposal temp. shut-in	7. UNIT AGREEMENT NAME NMFU
2. NAME OF OPERATOR CONOCO INC.	8. FARM OR LEASE NAME Farney A-5
3. ADDRESS OF OPERATOR P. O. Box 460, Hobbs, N.M. 88240	9. WELL NO. 5
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit G	10. FIELD AND POOL, OR WILDCAT Jalmat Yates 7 Rurs
14. PERMIT NO. 1980' FNL & 1980' FEL 30-025-09266	11. SEC., T., R., M., OR S.E.K. AND SURVEY OR AREA Sec. 5 - T23S - R36E
15. ELEVATIONS (Show whether OF, RT, GR, etc.)	12. COUNTY OR PARISH Lea
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other) ☒ Plug & abandon	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

MIRU on 9/3/85. Set CIBP @ 3611'. Tested csq but didn't hold. Isolated leak from 233'-376'. Pumped 150 sxs class "C" w/ 2% CaCl₂. Flush w/ 3 1/2 bbls fresh wtr. Circ. 15 sxs to surface. Tag cmt @ 100'. Drill 60' green cmt. WOC. Drill 60' cmt w/ large pieces of csq in returns. Attempt to test csq, wouldn't hold. Pumped 150 sxs class "C" cmt w/ 2% CaCl₂. Flushed w/ 5 bbls fresh wtr. Tag cmt @ 150' from surface. DO 190' cmt. Fell out @ 340'. Test csq, but didn't hold. Pumped 500 sxs class "C" cmt w/ 3% CaCl₂. Displaced w/ 5 bbls wtr. Tag cmt @ 175'. Drill 40' green cmt. WOC. Drill out hard cmt from 210'-385'. Fell out @ 385'. Tested sqz to 500 psi & held OK. Spot 5 sxs cmt @ 3611'-3564'. Spot 11 sxs @ 1600'-900'. Spot 11 sxs from 350'-250'. Rig down. Dug out well head, cut off csq. Filled w/ cmt. Installed marker & cleaned location on 4/17/86. Attached is a copy of the P&A sketch.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Administrative Supervisor DATE 9-25-85

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

RECEIVED
OCT - 3 1985
O.C.D.
HOBB'S OFFICE