

COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>B-934</b>
7. Unit Agreement Name
8. Farm or Lease Name <b>N.M. "S" STATE</b>
9. Well No. <b>13</b>
10. Field and Pool, or Wildcat <b>DRINKARD</b>
12. County <b>LEA</b>

**SUNDY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator  
**EXXON CORPORATION**

3. Address of Operator  
**P.O. BOX 1600, MIDLAND, TEXAS 79701**

4. Location of Well  
UNIT LETTER **B**, **660** FEET FROM THE **NORTH** LINE AND **1980** FEET FROM  
THE **EAST** LINE, SECTION **2** TOWNSHIP **22-S** RANGE **37-E** NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)  
**3362 GR**

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	OTHER <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
OTHER <b>PERF &amp; FRAC ALL OF DRINKARD</b> <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**SEE ATTACHED SHEETS FOR RECOMMENDED WORKOVER PROCEDURE.**

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED **Marvin Ochs** TITLE **UNIT HEAD** DATE **12-2-75**

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

RECOMMENDED WORKOVER PROCEDURE

1. Kill the Tubb zone and load casing with brine.
2. Pull production equipment. Brown packer has been in well since 1954. Recommend having BOT tool man on well when pulling packer.
3. Run a GR/N log and collar locator from PBD to 3800'.
4. Run a retrievable bridge plug and treating packer on 2-7/8" workstring. Pressure test workstring to 5500 psi if necessary.
5. Set BP @ 6510' and packer at 6200'.
6. Perforate the Drinkard. Perfs will be picked from GR/N log. Perforate through tubing using McCullough's 1-9/16" Omega Jet tubing gun or equivalent with 1 jspf and 0° phasing. Decentralize gun in casing and use lubricator when perforating.
7. Reset packer 10' below bottom perf of upper Drinkard zone (approximately 6340').
8. Pressure test surface equipment to 5500 psi.
9. Acid frac the lower zone with 15,000 gals. Polymulsion pad, 17,000 gals. 20% HCl and 3,000 gals. flush as follows:
  - a. Pump 1,000 gals. acid.
  - b. Pump 5,000 gals. K-1 pad.
  - c. Pump 5,000 gals. HCl.
  - d. Pump a 600# slug of a 50-50 mixture of benzoic acid flakes and rock salt in 30 bbls. gelled brine.
  - e. Pump 1,000 gals. acid.
  - f. Pump 10,000 gals. K-1 pad.
  - g. Pump 10,000 gals. HCl.
  - h. Pump 3,000 gals. brine containing 3 gals. Corexit 7652.
  - i. Shut-in well approximately 1 hour.
  - j. Flow well to tanks until all load is recovered or well dies.

Frac down 2-7/8" tubing at maximum rate not exceeding 5000 psi surface pressure. The 20% HCl should contain 50# gum karaya and 4 gals. Corexit 8504 per 1,000 gals. acid. Hold pressure on tubing-casing annulus if possible. If perfs communicate during frac, IMMEDIATELY shut down pumps and notify production engineer.

Mixing directions for 15,000 gals. brine-external K-1 Polymulsion:\*

- a. Add 50 gals. Exxon 8596 (emulsifier) to 5,000 gals. clean brine.
- b. Circulate brine while adding 240# gum karaya and 300# Adomite Aqua. Circulate until gel strength develops.
- c. Circulate gelled brine while adding 10,000 gals. lease crude.

\*Insure that no alkaline contaminants, such as cement or lime residue are present in the storage, mixing, or pumping equipment.

10. Kill Drinkard if necessary.
11. Reset BP 10' above top perf of lower zone (approximately 6370'). Reset packer at 6190'.
12. Acid frac the upper zone with 7,500 gals. K-1 pad, 9,000 gals. 20% HCl and 3,000 gals. flush volume as follows:
  - a. Pump 1,500 gals acid.
  - b. Pump 7,500 gals. K-1 pad.
  - c. Pump 7,500 gals. HCl.
  - d. Pump 3,000 gals. flush containing 3 gals. Corexit 7652.
  - e. Shut-in well approximately 1 hour.
  - f. Flow well to tanks until all load is recovered or well dies.


Frac down 2-7/8" tubing at maximum rate not exceeding 5000 psi surface pressure. The 20% HCl should contain 50# gum karaya and 4 gals. Corexit 8504 per 1,000 gals. acid. Hold pressure on tubing-casing annulus if possible. If perfs communicate during frac, IMMEDIATELY shut down pumps and notify production engineer.

Mixing directions for 7,500 gals. brine-external K-1 Polymulsion:\*

- a. Add 25 gals. Exxon 8596 (emulsifier) to 2,500 gals. clean brine.
- b. Circulate brine while adding 120# gum karaya and 150# Adomite Aqua. Circulate until gel strength develops.
- c. Circulate gelled brine while adding 5,000 gals. lease crude.

\*Insure that no alkaline contaminants, such as cement or lime residue are present in the storage, mixing, or pumping equipment.

13. Kill Drinkard if necessary.
14. Pull bridge plug and packer.
15. Run 2-3/8" production tubing with production packer, profile nipple, and on/off tool on bottom (recommend using Guiberson or Baker production equipment).
16. Set packer @ 6200'±.
17. Set plug in profile nipple and release on/off tool. Swab in Tubb.
18. Close tubing valve and produce Tubb on tubing-casing annulus.
19. Latch into on/off tool and retrieve plug.
20. Swab in Drinkard and place well on production.

  
S. E. Barker

11-26-75