

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

C CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fed <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG JACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Exxon Corporation	8. Farm or Lease Name Paddock Unit
3. Address of Operator P. O. Box 1600, Midland, TX 79702	9. Well No. 40
4. Location of Well UNIT LETTER <u>P</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>3</u> TOWNSHIP <u>22-S</u> RANGE <u>37-E</u> N.M.P.M.	10. Field and Pool, or Wildcat Paddock
15. Elevation (Show whether DF, RT, GR, etc.) 3390' DF	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Pull rods and tubing.
2. Spot (100' 20 sx) class "C" cmt plug from 5050 to 4950'.
3. Spot 20 sx plug at 3800'. 20 sx plug at 3300'.
4. Cut and pull 5½" csg. Spot 30 sx plug across 5½" cut.
5. Spot 35 sx plug at 2850'.
6. Cut and pull 8 5/8" csg. Spot 55 sx plug across cut.
7. Spot 150 sx plug at 1200'.
8. Spot 70 sx plug across csg seat of surface csg.
9. Spot 10 sx plug at surface.
10. Install dry hole marker as required by NMOCC.

THIS COPY OF THE REPORT IS TO BE FILED IN THE OFFICE OF THE COMMISSIONER OF ENERGY AND MINERALS, STATE OF NEW MEXICO, ALBANY, NEW MEXICO.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED C. J. Jackson TITLE Unit Head DATE 9-19-79

APPROVED BY Jerry Sexton TITLE DATE SEP 24 1979

CONDITIONS OF APPROVAL Expires 3/24/80