SUNDRY NOTICES AND REPORTS ON WELLS TO NOT THE TRANSPORT OF THE PROPERTY OF T	COPIES RECEIVED			Form C-103 Supersedes Old
SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES AND REPORTS ON WELLS STORY OF CONTROL STORY OF CON		NEW MEXICO OIL CONSE	EVATION COMMISSION	
Supply Notices and Reports On WELLS State Oil & Gas Lange No. Supply Notices and Reports On WELLS State Oil & Gas Lange No. Supply Notices and Reports On WELLS To not use this contract of the contract		NEW MEXICO OF STATE	,	
SUNDRY NOTICES AND REPORTS ON WELLS **********************************				
SUNDRY NOTICES AND REPORTS ON WELLS	LAND OFFICE			
Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand operation St	OPERATOR			0.0000000000000000000000000000000000000
Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand of Operation Stand operation St		DEPORTS ON W	751 J. C	
On the second state of the second state of the second state of my knowledge and bellef. Solid control of the second state of my knowledge and bellef. Solid control of the second state of my knowledge and bellef. Solid control of the second state of my knowledge and bellef. Solid control of the second state of the second state of my knowledge and bellef. Solid control of the second state of the second state of my knowledge and bellef. Solid control of the second state of the second state of my knowledge and bellef. Solid control of the second state of the second sta	SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL ON TO DESPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OF THE PROPOSALS.)			
S. Form or Lease Name South South	1.	N PERMIT		7. Unit Agreement Name
Donn H. Hendrix John H		OTHER-		9 Form or Legge Name
John H. Hendrix 7, Address of Operation The East Link, section The East Link, section The East Link, section Township 15, Elevation (Show whether DF, RT, CR, etc.) The East Link, section Township 15, Elevation (Show whether DF, RT, CR, etc.) The East Link, section Township 15, Elevation (Show whether DF, RT, CR, etc.) Lea NOTICE OF INTENTION TO: Subsequent Report of Other Data Subsequent Report of: Temporative Annual Work Temporative France Casing Te				
525 Midland Tower, Midland, Texas 79701 1. Location of Well UNIT LITTER 0	John H. Hendrix			
1. Location of Well				5
The East time, section 3 Township 22-5 Name: 37-E NAME: 37-E NAME: 33-E NOTICE OF INTENTION TO: 12. County Lea NOTICE OF INTENTION TO: Subsequent Report of Other Data Subsequent Report of: NOTICE OF INTENTION TO: NOTICE OF	525 Midland lower, Midland, Texas 79701			
The complete of comple	4. Location of Well South 2086			Drinkard
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of:	UNIT CELLULA			
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of:	Fact 3 22-S 37-E N			
Check Appropriate Box To Indicate Nature of Notice, Report of Other Data Subsequent Report of: **Perform Remedial work** **Plus and Abandon** **Plus an	THE LINE, SECTION			- Amministry
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of: NOTICE OF INTENTION TO: PLUC AND ABANDON REMEDIAL WORK COMMENCE ORIGINAL TEST AND CEMENT JOB OTHER 17. DESCRIPTION OF THE PLUCA AND ABANDONMENT COMMENCE ORIGINAL WORK COMMENCE ORICLING ORIGINAL WORK COMMENCE ORICLING ORIGINAL WORK COMMENCE ORICLING ORIGINAL WORK COMMENCE ORIGINAL WORK COMMENCE ORIGINAL				
NOTICE OF INTENTION TO: PLUG AND ABANDON PLUG AND ABANDON REMEDIAL WORK X ALTERING CASING TEMPORATIVE ASANDON PLUG AND ABANDON PULL OR ALTER CASING PLUG AND ABANDONMENT COMMENCE DRILLING OFFIE. CASING TEST AND CEMENT JOB PLUG AND ABANDONMENT COMMENCE DRILLING OFFIE. CASING TEST AND CEMENT JOB PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB PLUG AND ABANDONMENT JOB PLUG		11111		
NOTICE OF INTENTION TO: PLUG AND ABANDON PLUG AND ABANDON REMEDIAL WORK X ALTERING CASING TEMPORATIVE ASANDON PLUG AND ABANDON PULL OR ALTER CASING PLUG AND ABANDONMENT COMMENCE DRILLING OFFIE. CASING TEST AND CEMENT JOB PLUG AND ABANDONMENT COMMENCE DRILLING OFFIE. CASING TEST AND CEMENT JOB PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB PLUG AND ABANDONMENT JOB PLUG	16. Check A	ppropriate Box To Indicate Na	ture of Notice, Report or	Other Data
TEMPORARILY ARANGON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting ony propounts) see null 170. 1. Pull dual strings of 2-1/16" tubing and packers. 2. Set RTBP at 6410'. 3. Perforated Drinkard zone at 6249, 6258, 6265, 6277, 6289, 6294, 6301, 6312, 6322, 6330, 6337, 6346, 6356, 6366, 6372, 6381, 6387. 4. Acidized perfs W/6000 gallons 15% LSTNE acid. 5. Fraced down 2-1/2" tubing using 60,000 gallons brine water, 54,000# 20-40 sand, and 11,000# 10-20 sand. 6. AIR 18 BPM at 3500#. ISIP 2200#, 15 minutes at 1200#. 7. Return to production.			SUBSEQUE	ENT REPORT OF:
TEMPORARILY ARANGON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting ony propounts) see null 170. 1. Pull dual strings of 2-1/16" tubing and packers. 2. Set RTBP at 6410'. 3. Perforated Drinkard zone at 6249, 6258, 6265, 6277, 6289, 6294, 6301, 6312, 6322, 6330, 6337, 6346, 6356, 6366, 6372, 6381, 6387. 4. Acidized perfs W/6000 gallons 15% LSTNE acid. 5. Fraced down 2-1/2" tubing using 60,000 gallons brine water, 54,000# 20-40 sand, and 11,000# 10-20 sand. 6. AIR 18 BPM at 3500#. ISIP 2200#, 15 minutes at 1200#. 7. Return to production.			X	ALTERING CASING
Temperature Casing Other Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proportions) SEE RULE 1103. 1. Pull dual strings of 2-1/16" tubing and packers. 2. Set RTBP at 6410'. 3. Perforated Drinkard zone at 6249, 6258, 6265, 6277, 6289, 6294, 6301, 6312, 6322, 6330, 6337, 6346, 6356, 6366, 6372, 6381, 6387. 4. Acidized perfs W/6000 gallons 15% LSTNE acid. 5. Fraced down 2-1/2" tubing using 60,000 gallons brine water, 54,000# 20-40 sand, and 11,000# 10-20 sand. 6. AIR 18 BPM at 3500#. ISIP 2200#, 15 minutes at 1200#. 7. Return to production.	PERFORM REMEDIAL WORK	PLUG AND ABANDON	777	PLUG AND ABANDONMENT
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed or Complete 1103. 1. Pull dual strings of 2-1/16" tubing and packers. 2. Set RTBP at 6410'. 3. Perforated Drinkard zone at 6249, 6258, 6265, 6277, 6289, 6294, 6301, 6312, 6322, 6330, 6337, 6346, 6356, 6366, 6372, 6381, 6387. 4. Acidized perfs W/6000 gallons 15% LSTNE acid. 5. Fraced down 2-1/2" tubing using 60,000 gallons brine water, 54,000# 20-40 sand, and 11,000# 10-20 sand. 6. AIR 18 BPM at 3500#. ISIP 2200#, 15 minutes at 1200#. 7. Return to production.		CHANGE BLANS		_
 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed or Complete Yoro. Pull dual strings of 2-1/16" tubing and packers. Set RTBP at 6410'. Perforated Drinkard zone at 6249, 6258, 6265, 6277, 6289, 6294, 6301, 6312, 6322, 6330, 6337, 6346, 6356, 6366, 6372, 6381, 6387. Acidized perfs W/6000 gallons 15% LSTNE acid. Fraced down 2-1/2" tubing using 60,000 gallons brine water, 54,000# 20-40 sand, and 11,000# 10-20 sand. AIR 18 BPM at 3500#. ISIP 2200#, 15 minutes at 1200#. Return to production. 	PULL OR ALTER CASING	CHARGE FEATS		
 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed or Complete Yoro. Pull dual strings of 2-1/16" tubing and packers. Set RTBP at 6410'. Perforated Drinkard zone at 6249, 6258, 6265, 6277, 6289, 6294, 6301, 6312, 6322, 6330, 6337, 6346, 6356, 6366, 6372, 6381, 6387. Acidized perfs W/6000 gallons 15% LSTNE acid. Fraced down 2-1/2" tubing using 60,000 gallons brine water, 54,000# 20-40 sand, and 11,000# 10-20 sand. AIR 18 BPM at 3500#. ISIP 2200#, 15 minutes at 1200#. Return to production. 				
 Pull dual strings of 2-1/16" tubing and packers. Set RTBP at 6410'. Perforated Drinkard zone at 6249, 6258, 6265, 6277, 6289, 6294, 6301, 6312, 6322, 6330, 6337, 6346, 6356, 6366, 6372, 6381, 6387. Acidized perfs W/6000 gallons 15% LSTNE acid. Fraced down 2-1/2" tubing using 60,000 gallons brine water, 54,000# 20-40 sand, and 11,000# 10-20 sand. AIR 18 BPM at 3500#. ISIP 2200#, 15 minutes at 1200#. Return to production. 			le and give pertinent dates, inclu	ding estimated date of starting any propos
 Pull dual strings of 2-1/16" tubing and packers. Set RTBP at 6410'. Perforated Drinkard zone at 6249, 6258, 6265, 6277, 6289, 6294, 6301, 6312, 6322, 6330, 6337, 6346, 6356, 6366, 6372, 6381, 6387. Acidized perfs W/6000 gallons 15% LSTNE acid. Fraced down 2-1/2" tubing using 60,000 gallons brine water, 54,000# 20-40 sand, and 11,000# 10-20 sand. AIR 18 BPM at 3500#. ISIP 2200#, 15 minutes at 1200#. Return to production. 	17. Describe Proposed or Completed Op-	erations (Clearly state all pertinent detail	is, usa give periode a large since	·
 Set RTBP at 6410'. Perforated Drinkard zone at 6249, 6258, 6265, 6277, 6289, 6294, 6301, 6312, 6322, 6330, 6337, 6346, 6356, 6366, 6372, 6381, 6387. Acidized perfs W/6000 gallons 15% LSTNE acid. Fraced down 2-1/2" tubing using 60,000 gallons brine water, 54,000# 20-40 sand, and 11,000# 10-20 sand. AIR 18 BPM at 3500#. ISIP 2200#, 15 minutes at 1200#. Return to production. 		s 0 1/160 tubing and nac	kars	
 Perforated Drinkard zone at 6249, 6258, 6265, 6277, 6289, 6294, 6301, 6312, 6322, 6330, 6337, 6346, 6356, 6366, 6372, 6381, 6387. Acidized perfs W/6000 gallons 15% LSTNE acid. Fraced down 2-1/2" tubing using 60,000 gallons brine water, 54,000# 20-40 sand, and 11,000# 10-20 sand. AIR 18 BPM at 3500#. ISIP 2200#, 15 minutes at 1200#. Return to production. 	1. Pull dual strings o	T 2-1/16 tubing and pac	KEI 3.	
 Perforated Drinkard zone at 6249, 6258, 6265, 6277, 6289, 6294, 6301, 6312, 6322, 6330, 6337, 6346, 6356, 6366, 6372, 6381, 6387. Acidized perfs W/6000 gallons 15% LSTNE acid. Fraced down 2-1/2" tubing using 60,000 gallons brine water, 54,000# 20-40 sand, and 11,000# 10-20 sand. AIR 18 BPM at 3500#. ISIP 2200#, 15 minutes at 1200#. Return to production. 	2 Cat DIDD at 6/10'			
 6337, 6346, 6356, 6366, 6372, 6381, 6387. 4. Acidized perfs W/6000 gallons 15% LSTNE acid. 5. Fraced down 2-1/2" tubing using 60,000 gallons brine water, 54,000# 20-40 sand, and 11,000# 10-20 sand. 6. AIR 18 BPM at 3500#. ISIP 2200#, 15 minutes at 1200#. 7. Return to production. 18.1 hereby certify that the information above is true and complete to the best of my knowledge and belief. 				
 Fraced down 2-1/2" tubing using 60,000 gallons brine water, 54,000# 20-40 sand, and 11,000# 10-20 sand. AIR 18 BPM at 3500#. ISIP 2200#, 15 minutes at 1200#. Return to production. 	3. Perforated Drinkard 6337, 6346, 6356, 6	zone at 6249, 6258, 626 366, 6372, 6381, 6387.	5, 6277, 6289, 6294,	6301, 6312, 6322, 6330,
11,000# 10-20 sand. 6. AIR 18 BPM at 3500#. ISIP 2200#, 15 minutes at 1200#. 7. Return to production. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
7. Return to production. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	5. Fraced down 2-1/2" 11,000# 10-20 sand.	tubing using 60,000 gall	ons brine water, 54,	000# 20-40 sand, and
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	6. AIR 18 BPM at 3500#	f. ISIP 2200#, 15 minute	s at 1200#.	
	7. Return to production	on.		
	·		f my knowledge and heliaf	
f = f = f = f = f = f = f = f = f = f =	18. I hereby certify that the information	above is true and complete to the best of	I my whomsenke and better	
	1 1	distribution of	advation Clark	DATE 4/13/76

Orig. Signed M.
Jerry Sexton.

Diet 1, Supv.

DATE 3 1976

REDEN'ED

CIL COHSERVATION COMM.
HOBBS, N. M.