Submit 3 Copies to Appropriate District Office	State of New M Energy inerals and Natural R		Form C-103 Revised 1-1-89		
DISTRICT I P.O. Box 1980, Hobbs, NM 88240 DISTRICT II P.O. Drawer DD, Artesia, NM 88210 DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410	OIL CONSERVATIO 2040 Pacheco Santa Fe, N	DN DIVISION St. M 87505	WELL API NO. 30-025-10015 5. Indicate Type of Lease STATE FEE X 6. State Oil & Gas Lease No. FEE		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name		
1. Type of Well: OL GAS WELL AS WELL	OTHER		Corrigan, H.		
 Name of Operator Collins & Ware, Inc. Address of Operator 508 West Wall, Suite 1200, Midland, Texas 79701 			8. Well No. 10 9. Pool name or Wildcat Paddock (49210)		
4. Well Location Unit Letter <u>H</u> : <u>1980</u> Feet From The <u>North</u> Line and <u>660</u> Feet From The <u>East</u> Line					
Section 4 Township 22S Range 37E NMPM Lea County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3454 ! GR 3454 ! GR 1000000000000000000000000000000000000					
II. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
	CHANGE PLANS	COMMENCE DRILLING OPNS.			
PULL OR ALTER CASING					
OTHER:	[]	OTHER: Perforate and Treat			

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Please see attachment.

I hereby certify that the information above is true and complete to the best of my kno SKINATURE	mindge and ballef. <u> m.e. Production Supervisor</u>	
TYPE OR PRINT NAME Dianne Sumrall		тецерноме но. <u>(915)687-3</u> 435
(This space for State Use) Orig. Signed by Paul Kautz Geologist		
APPROVED BY	TITLE	DATE

ATTACHMENT TO FROM C-103 COLLINS & WARE, INC, CORRIGAN, H. #10

6/09/97 Run GR/JB to 6380'. Set CIBP at 6300' and dump 4 sx cement on top.

- 6/10/97 Tag PBTD at 6267'. Conventionally perf 5041' 5058' with 1 SPF. Set packer at 4920' and acidize perfs with 2000 gals 15% HCL utilizing 36 BS. Achieved ballout twice.
- 6/11/97 Run 2 3/8" tubing to 4919' and started swabbing.
- 6/25/97 POH with tubing and packer. Set RBP at 5320'. Perforate from 5180' 5200' and 5240' 5260' with 1 SPF. Set RBP at 5298' and packer at 5225'. Acidize perfs 5240' 5260' with 15% Ferchek SC. Pull up and set RBP at 5225' and packer at 5105'. Acidize perfs 5180' 5200' with 1000 gals 15% Ferchek SC. Balled out 3 times.
- 6/27/97 Frac well with 35,000 gals Delta Frac 25 carrying 1000 sx 20/40 Ottawa sand.