

Plugged back and acid treated as follows:

1. Pulled rods, pump and tubing. Set Baker Model C bridge plug on wire line at 8060'. Dumped 64 gallons Hydromite, hit bridge at 8027'. Cleaned out to 8046' with sand pump.
2. Ran 2-7/8" tubing with packer at 7959'. Treated formation from 7980-8046' with 1000 gallons 15% acid. Injection rate 71 gallons per minute. Swabbed dry. Treated formation from 7980-8046' with 4000 gallons 15% acid. Injection rate 6 bbls per minute. Swabbed dry.
3. Pulled tubing and packer. Dumped 52 gallons Hydromite and filled up to 8030'. Ran 2-7/8" tubing with 7" packer at 7980'. Swabbed. Ran rods and pump.
4. Pulled rods, pump, tubing and packer. Ran 2-7/8" tubing with cement retainer at 7973'. Pumped 200 sacks cement down tubing. WOC. Pumped 100 sacks cement with 25# flo-seal and squeezed formation with 3500#. Released from retainer and reversed out 20 sacks cement. Pulled tubing.
5. Perforated 7" casing from 7942-7972' with 4, 1/2" jet holes per foot. Ran 2-7/8" tubing with 7" packer at 7905'. Swabbed dry. Spotted 1000 gallons acid on perforations in 7" casing from 7942-7972' and squeezed in formation. Swabbed. Treated formation thru perforations in 7" casing from 7942-7972' with 3000 gallons 15% H² acid. Injection 4.5 bbls per minute. Swabbed dry. Well closed in for further study of remedial work.

- The first of these is the fact that the
 Government has been unable to secure
 the necessary funds to carry out its
 policy of non-interference. This is
 due to the fact that the Government
 has been unable to secure the necessary
 funds to carry out its policy of non-
 interference. This is due to the fact
 that the Government has been unable
 to secure the necessary funds to carry
 out its policy of non-interference.