

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals & Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P. O. Box 1980, Hobbs, NM 88240

DISTRICT II
P. O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P. O. Box 2088
Santa Fe, NM 87504-2088

WELL API NO. 30-025-10043
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1 Type of Well: OIL ☒ GAS ☐ WELL ☒ WELL ☐ OTHER	7. Lease Name or Unit Agreement Name Renewalt A
2. Name of Operator The Wiser Oil Company	8. Well No. 1
3. Address of Operator P.O. Box 2568 Hobbs, New Mexico 88241 (505) 392-9797	9. Pool name or Wildcat Drinkard
4. Well Location Unit Letter <u>D</u> : <u>560</u> Feet From The <u>South</u> Line and <u>660</u> Feet From The <u>East</u> Line Section <u>4</u> Township <u>22S</u> Range <u>37E</u> NMPM <u>Lea</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3453' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER: <u>Well is SI</u>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6/15/01 MIRU Tyler Well Service. POH w/2-3/8" tbg. LD pump. ND WH. RU BOP. POH w/2-3/8" tbg. LD BHA. RIH w/pkr. to 6296'. Set pkr. Load csg. annulus w/201 bbls. 2% KCL water. Pressured to 300#. RU swab.

6/19/01 Tagged @ 5200'. Fluid level @ 5500'. RD swab. Loaded tbg.w/20 bbls. 2% KCL water. Unset pkr. Tried to move down. Stacked out @ 6345'. POH w/2-3/8" tbg. LD 7" pkr.

6/20/01 RIH w/6-1/4" cone bit, 7" csg. scraper & 2-3/8" tbg. to 6475'. POH w/tbg. LD tools. RIH w/pkr. & 2-3/8" tbg. to 6443' & set pkr. RU swab. POH w/2-3/8" tbg. & pkr. to 3000'.

6/21/01 RIH w/7" RBP, pkr. & 2-3/8" tbg. Set RBP @ 6443'. Set pkr. @ 6298'. RU swab. Rec'd 23 bbls. fluid. Moved pkr. to 6350'. FFL 5700'. RD swab. POH w/2-3/8" tbg. LD tools.

6/22/01 RIH w/2-3/8" tbg. POH. LD 2-3/8" tbg. RD BOP. RIH w/rods. POH. LD rods. NU WH w/1 jt. 2-3/8" tbg. through flang vale & gauge on top. Left open to flowline. RDMO. Well is SI waiting on evaluation.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mary Jo Turner TITLE Production Tech II DATE September 5, 2001
TYPE OR PRINT NAME Mary Jo Turner TELEPHONE NO. 392-9797

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

ORIGINAL SIGNED BY
T. J. HENRIZ
PETROLEUM ENGINEER

