

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>Water Injection Well</b>	7. Unit Agreement Name <b>South Penrose Skelly Unit</b>
2. Name of Operator <b>Gulf Oil Corporation</b>	8. Farm or Lease Name
3. Address of Operator <b>Box 670, Hobbs, New Mexico 88240</b>	9. Well No. <b>106</b>
4. Location of Well UNIT LETTER <b>C</b> , <b>660</b> FEET FROM THE <b>North</b> LINE AND <b>1980</b> FEET FROM THE <b>West</b> LINE, SECTION <b>5</b> TOWNSHIP <b>22-S</b> RANGE <b>37-E</b> NMPM.	10. Field and Pool, or Wildcat <b>Penrose Skelly</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3455' GL</b>	12. County <b>Lea</b>

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐  
CHANGE PLANS ☐

OTHER **Squeeze cement bottom of liner**

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOB ☐

ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐

OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

**3755' TD**

Pull tubing and packer. Plug back to 3693' with pea gravel. Plug back to 3683' with hydramite. Run packer on tubing and set at 3650'. Establish injection rate. Release packer and set at 3250'. Squeeze with 50 sacks of Glass C neat. WOC 24 hours. Pull tubing and packer. Run 3-7/8" bit on 2-3/8" tubing and drill out to 3683'. Test with 500#. Clean out to TD at 3755'. Pull tubing and bit. Run Baker Model AD tension type packer and set at approximately 3345' with 10,000# tension. Resume water injection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

ORIGINAL SIGNED BY

SIGNED **C. D. BORLAND**

TITLE **Area Production Manager**

DATE **December 7, 1967**

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: