Submit 3 Copies		
to Appropriate Energy, District Office	State of New Mexico Minerals and Natural Resources Department	Form C-103 Revised 1-1-89
P.O. Bax 1980, Hobbs, NM 88240	Box 1980, Hobba, NM 88240 P.O. Box 2088	
DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088		5. Indicate Type of Lease STATE FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410		6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name
1. Type of Well: OIL GAS WELL X WELL		Simmons
WELL X WELL 2. Name of Operator	OTHER	8. Well No.
Zia Energy, Inc.		1
3. Address of Operator P.O. Box 2219, Hobbs,	NM 88241	9. Pool name or Wildcat Blinebáry, Tubbs, Drinkard
4. Well Location Unit LetterG: 1760 Feet Fi	rom The <u>North</u> Line and <u>17</u>	60 Feet From The East Line
سع		
Section 5 Towns	hip 22 South Range 37 East 10. Elevation (Show whether DF, RKB, RT, GR, etc.)	NMPM Lea County
	3424' GR	
II. Check Appropri	ate Box to Indicate Nature of Notice, F N TO: SUE	Report, or Other Data BSEQUENT REPORT OF:
PULL OR ALTER CASING	CASING TEST AND C	
DTHER:	ОТНЕВ:	entry of P & A Well
12. Describe Proposed or Completed Operations (Clearly work) SEE RULE 1103.	y state all pertinent details, and give pertinent dates, inclu	uding estimated date of starting any proposed
 1/30/91 commencea operation, dug out cell plug. 	erations to re-enter P & / llar, removed dry hole man	A Sohio Grizzell #1. Cleared rker and drilled 40' of top
to drill surface ceme	unit and reverse circular ent plug. Fell out of cmm	t. at 180'. Tagged 2nd
to drill surface ceme plug @ 906'. Drilled 3. 2/7/91 Circulate down	ent plug. Fell out of cm d through 2nd plug at 1112 n to 3rd plug at 2039'. I	t. at 180'. Tagged 2nd 2'. Drilled cmt. to 2275'.
to drill surface ceme plug @ 906'. Drilled 3. 2/7/91 Circulate down Circulated down to 28 the 8 5/8" csg wow	ent plug. Fell out of cm d through 2nd plug at 1112 n to 3rd plug at 2039'. I 852', the top of the 5 1/2 ald not hold pressure. Lo	t. at 180'. Tagged 2nd 2'. Drilled cmt. to 2275'. 2" casing. Pressured up on Docated a hole in the 8 5/8"
to drill surface cent plug @ 906'. Drilled 3. 2/7/91 Circulate down Circulated down to 28 the 8 5/8" csg wou csg. at 1135'. Squee hole - left 25 sx in	ent plug. Fell out of cm d through 2nd plug at 1112 n to 3rd plug at 2039'. I 852', the top of the 5 1/2 ald not hold pressure. Lo ezed hole using 100 sx cm csg. Drilled out cmt. us	t. at 180'. Tagged 2nd 2'. Drilled cmt. to 2275'. 2" casing. Pressured up on Decated a hole in the 8 5/8" t. Displaced 75 sx through sing 7 5/8" bit. Pressure
to drill surface cent plug @ 906'. Drilled 3. 2/7/91 Circulate down Circulated down to 28 the 8 5/8" csg wou csg. at 1135'. Squee hole - left 25 sx in tested to 500 psi - }	ent plug. Fell out of cm d through 2nd plug at 1112 n to 3rd plug at 2039'. I 852', the top of the 5 1/2 ald not hold pressure. Lo ezed hole using 100 sx cm csg. Drilled out cmt. us held w/0 loss of pressure.	t. at 180'. Tagged 2nd 2'. Drilled cmt. to 2275'. 2" casing. Pressured up on Decated a hole in the 8 5/8" t. Displaced 75 sx through sing 7 5/8" bit. Pressure
to drill surface cent plug @ 906'. Drilled 3. 2/7/91 Circulate down Circulated down to 28 the 8 5/8" csg wou csg. at 1135'. Squee hole - left 25 sx in tested to 500 psi - 4 4. 2/9/91 TIH w/ 4 3/4"	ent plug. Fell out of cm d through 2nd plug at 1112 n to 3rd plug at 2039'. I 852', the top of the 5 1/2 ald not hold pressure. Lo ezed hole using 100 sx cm csg. Drilled out cmt. us held w/0 loss of pressure. hole - circulated to 5491	t. at 180'. Tagged 2nd 2'. Drilled cmt. to 2275'. 2" casing. Pressured up on boated a hole in the 8 5/8" t. Displaced 75 sx through sing 7 5/8" bit. Pressure
to drill surface cent plug @ 906'. Drilled 3. 2/7/91 Circulate down Circulated down to 28 the 8 5/8" csg wou csg. at 1135'. Squee hole - left 25 sx in tested to 500 psi - 1 4. 2/9/91 TIH w/ 4 3/4" 5509'. Circulated to Thereby certify that the information above is true and complete	ent plug. Fell out of cm d through 2nd plug at 1112 n to 3rd plug at 2039'. I 852', the top of the 5 1/2 ald not hold pressure. Lo ezed hole using 100 sx cm csg. Drilled out cmt. us held w/0 loss of pressure. hole - circulated to 5491 <u>5952'. Drilled cmt. \$ (</u> to the best of my knowledge and belof.	t. at 180'. Tagged 2nd 2'. Drilled cmt. to 2275'. 2" casing. Pressured up on bocated a hole in the 8 5/8" t. Displaced 75 sx through sing 7 5/8" bit. Pressure 1'. Drilled cmt. & CIBP to CIBF to 5964' Continued
to drill surface cent plug @ 906'. Drilled 3. 2/7/91 Circulate down Circulated down to 28 the 8 5/8" csg wou csg. at 1135'. Squee hole - left 25 sx in tested to 500 psi - 1 4. 2/9/91 TIH w/ 4 3/4" 5509'. Circulated to Thereby certify that the information above is true and complete	ent plug. Fell out of cm d through 2nd plug at 1112 h to 3rd plug at 2039'. I 852', the top of the 5 1/2 ald not hold pressure. Lo ezed hole using 100 sx cm csg. Drilled out cmt. us held w/0 loss of pressure. hole - circulated to 5491 5 5952'. Drilled cmt. \$ (t. at 180'. Tagged 2nd 2'. Drilled cmt. to 2275'. 2" casing. Pressured up on bocated a hole in the 8 5/8" t. Displaced 75 sx through sing 7 5/8" bit. Pressure 1'. Drilled cmt. & CIBP to CIBF to 5964' Continued
to drill surface cent plug @ 906'. Drilled 3. 2/7/91 Circulate down Circulated down to 28 the 8 5/8" csg wou csg. at 1135'. Squee hole - left 25 sx in tested to 500 psi - 1 4. 2/9/91 TIH w/ 4 3/4" 5509'. Circulated to Ibereby certify that the information above is true and complete	ent plug. Fell out of cm d through 2nd plug at 1112 n to 3rd plug at 2039'. I 852', the top of the 5 1/2 ald not hold pressure. Lo ezed hole using 100 sx cm csg. Drilled out cmt. us held w/0 loss of pressure. hole - circulated to 5491 5952'. Drilled cmt. C to the best of my knowledge and belief. Market Market States and belief.	t. at 180'. Tagged 2nd 2'. Drilled cmt. to 2275'. 2" casing. Pressured up on bcated a hole in the 8 5/8" t. Displaced 75 sx through sing 7 5/8" bit. Pressure 1'. Drilled cmt. & CIBP to CIBF to 5964' Continued
to drill surface cent plug @ 906'. Drilled 3. 2/7/91 Circulate down Circulated down to 28 the 8 5/8" csg wou csg. at 1135'. Squee hole - left 25 sx in tested to 500 psi - 4 4. 2/9/91 TIH w/ 4 3/4" 5509'. Circulated to I hereby certify that the information above is true and complete skinature TYPE OR PRINT NAME TYPE OR PRINT TYPE OR PRINT NAME TYPE OR	ent plug. Fell out of cmt d through 2nd plug at 1112 n to 3rd plug at 2039'. I 852', the top of the 5 1/2 ald not hold pressure. Lo ezed hole using 100 sx cmt csg. Drilled out cmt. us held w/0 loss of pressure. hole - circulated to 5491 <u>5952'. Drilled cmt. </u> to the best of my knowledge and belief. <u>Soc.</u> <u>n 505/3</u>	t. at 180'. Tagged 2nd 2'. Drilled cmt. to 2275'. 2" casing. Pressured up on bcated a hole in the 8 5/8" t. Displaced 75 sx through sing 7 5/8" bit. Pressure 1'. Drilled cmt. & CIBP to CIBF to 5964' Continued er
to drill surface cent plug @ 906'. Drilled 3. 2/7/91 Circulate down Circulated down to 28 the 8 5/8" csg wou csg. at 1135'. Squee hole - left 25 sx in tested to 500 psi - 4 2. 2/9/91 TIH w/ 4 3/4" 5509'. Circulated to I hereby certify that the information above is true and complete skinature TYPE OR PRINT NAME Farris Nelson (This space for State Use) Drig. Signed	ent plug. Fell out of cmt d through 2nd plug at 1112 n to 3rd plug at 2039'. I 852', the top of the 5 1/2 ald not hold pressure. Lo ezed hole using 100 sx cmt csg. Drilled out cmt. us held w/0 loss of pressure. hole - circulated to 5491 <u>5952'. Drilled cmt. </u> to the best of my knowledge and belief. <u>Soc.</u> <u>n 505/3</u>	t. at 180'. Tagged 2nd 2'. Drilled cmt. to 2275'. 2" casing. Pressured up on bcated a hole in the 8 5/8" t. Displaced 75 sx through sing 7 5/8" bit. Pressure 1'. Drilled cmt. & CIBP to CIBF to 5964' Continued er <u>4/17/91</u>

CONTINUED

- 5. Circulated down to 6234'. Drilled cmt. & CIBP to 6300'. Circulate to 6549' - original TD.
- 6. Set a guide on top of 5 1/2" csg at 2852' with one joint of 5 1/2" csg, & a swage from 5 1/2" to 8 5/8".
- 7. Set a BP at 5990' & a pkr. at 5800'. Treated Blinebry perfs. from 5820' - 5845' using 5000 gallons of 15% HCL. Swab tested Blinebry 0 BOPD, 0 BWPD & gas. TSTM.
- 8. Moved BP to 6275' & pkr at 6000'. Treated Tubbs perfs from 6062' 6163' using 5000 gallons of 15% HCL. Swab tested. Tubbs to produce 1.5 BOPD, 6.0 BWPD & gas 10 MCF/D.
- 9. TOH to lay down BP. TIH w/ pkr. set pkr. at 6410'. 'Treated Drinkard perfs. from 6440' - 6478' & 6488' - 6549' open hole using 5000 gallons of 15% HCL. Swab tested Drinkard to produce 4.5 BOPD, 7.0 BWPD & gas 25.0 MCF/D.
- 10. TOH to lay down pkr. & 2 7/8" work string. TIH w/ 6501' 2 3/8" tbg. w/complete assembly to pump, including a tbg. anchor set at 5800'. Picked up 2" X l 1/2" X 16' rod pump, 3/4" and 7/8" rods. SD w/o pumping unit, electricity & paper work.

ŧ

ñ :

.

~

APR 2 3 1991