SIALE OF HEW MEXICO	← :	
ENERGY AND MINIERALS DEPARTMENT		
CILTANEUTION	OIL CONSERVATION DIVISION	
34473 07 1 1	P. O. BOX 201A	
V.S.G.S.	SANTA FE, NEW MEXICO 87501	Forn C-103 Revised 19-1-;
LAND OFFICE		Su, indicate Type of Louise
0/11/01		Sinie En X
SUNDRY NOTIO		S. State Oli & Gus Letune No.
100 NOT USE THIS FOOM THE OUTSALS TO P	ES AND REPORTS ON WELLS	
	Son Citoli For AUCH CHOPDALS.	
Jeame ut up civilar	••• •	7. Unit Asterment Heave
Amoco Production Company		d. Farm or Leave hume
		Grizzell Deen
P. 0. Box 68, Hobbs, New Mex	xico 88240	9. mil No.
Vait Letter <u>N</u> 660	South 1980	10. Field and Pool, or Amucat
· · · · · · · · · · · · · · · · · · ·	LINC AND	Und. Drinkard Blinebry
THE West LINE, SECTION 5	22-S 37-E	Aliiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiii
THE CONTRACTOR OF THE PARTY OF		
<u>1411141111111111111111111111111111111</u>	S. Elevation (Show whether DF. RT. CK. etc.) 3437' DF	12. County
Check Appropriat	ie Box To Indiana N	Lea
NOTICE OF INTENTION	te Box To Indicate Nature of Notice, Repo	rt or Other Data
AFORM BENEDIAL WORK	5085	EQUENT REPORT OF:
4 PORA 41LT ARABON	PLUE AND ABANDON AEMEDIAL WORE	
LL OR ALTEN CASING	CMANCE PLANS CASING TEST AND CEMENT JOB	PLUG AND ABANGONMENT
91+6.	OTHER	
Describe Processos or Commission		
WERAJ SEE RULE HOS.	ariy state all pertinent details, and give pertinent dates,	including estimated for al
and pulled up. Ran tree and with rods and pump. Pulled t ream to 3%89'. Ran tubing to Circulated bottom up. Wash	installed BOP. Worked tubing and c tubing, bit and drill collars. Tagg 5600, tag fill, wash and ream to 5	pump stuck. Backed off rods ame free. Pull out of hole ed drill at 3804 and washed 652'. Wash and ream to 5805'
Circulated and conditioned ho set at 3721'. Tested RRP to	) vis pill and 10#/bbl CACL corbonat ble. Ran retrievable bridge plug an	e. Wash and ream to 6536'. d set at 3754'. Ran packer and
Squeezed perfs at 3666'_3718	Population I and Cased pucker a	nu reset at 3590'. Tested
Spotted 250 gal 15% HCL to on	ueezed perfs at 1/4 BPM and 1500 ps d to tubing. Sting into cement not	i. Plugged down cement retainer
perts. Plugged down comont n	otainau	arrier drid could not numn into
relather and no good pan ba	ckon nielen in the out atta. Atte	ipled to clean out cement
Spear, grapple and tested case	t retainer free and trip out of hole ing at 6000 lbs above slips Tagged	Did not catch fish Pan
In noie. Kan 4" magnet and to	ubing D	ITISM at 3/42'. Left grannle
unied LUDING and recovered to		e. Dressed Tish to 3/44'
	000 uc 0000 .	an cement retainer and set at
nderthus no. In Petros Lewisson	en RM 21.150 1-F. J. Nash, HOU RM	4.206 1-SUSP
4410	and complete to the usat of my anowieuxy and belief.	······
· _ ulu Jema	Assist. Admin. Analy	<b>.</b>
ORIGINAL CICAIRE	Tite	st 11-9-83
ORIGINAL SIGNED BY JERRY S	SEXTON	
DITIONS OF APPROVAL, IF ANTI	t	<u>NOV 10 1983</u>
	,	

3558'. Squeezed perfs 3666'-3718' with 75 sacks class C and additives at 2000 psi. Reversed out 8 sacks cement and pulled tubing. Perforated 7" casing 1275' at 4 SPF. Displaced with 50 bbl 10 lb brine and reset packer at 978'. Load and pressure backside at 990 psi. Slight blow on bradenhead and no circulation. Pulled tubing, packer and ran cement retainer set at 1217'. Squeezed perfs 1275' with 500 sacks class C and 18% salt. Revered out 10 sack cement. Ran temperature survey and cement top apx. 1175' from surface. Perforated 1100' with 4 SPF. Ran packer and set at 789'. Pumped 50 bbl 10 lb. brine and circulated out 2" Bradenhead valve. Pumped 140 sacks class C cement. Displaced with 9 bbl 10 lb. brine and circulated 38 sacks cement. Tagged cement at 943'. Drilled cement from 1057'-1100'. Ran packer and set at 914'. Ran cement retainer and set at 886'. Squeezed perfs 1100'-01' with 150 sacks class C cement, 50 sacks class C with 10 lb/ sack of sand. Max squeeze pressure 900 psi. Reversed out 2 sacks. Tagged cement retainer at 881'. Break circulation and drilled 9 hours on retainer. Drilled and circulated clean. Changed bit and tagged cement at 881'. Drilled out 20" in 7 hours. Tagged retainer at 882'. Drilled out retainer 5 hours.Drilled out cement t 938! Circulated clean. Ran tubing & tagged cement at 938. Drilled out cement to 1008. Tagged cem at 1008' and drilled cement to 1040'. Pressure tested perfs 1100-1101' to 600 psi for 15 min and held. OK. Ran tubing and tagged cement retainer at 1217'. Drilled cement retainer and cement to 1280'. Ran packer, seating nipple, and tubing with packer set at 1187'. Reset packer at 1312'. Bled to 0 and flowed 1/4" stream out casing. Reset packer at 1250'. Unable to pump into perfs at 1275'-76' at 1100 psi. Shut in well at 600 psi. Release packer and pulled tubing and packer. Ran tubing, drill collars and seating nipple. Seating nipple landed at 3379'. Removed BOP and flanged well up. Tubing plugged and unable to cut parrafin. Layed down tubing and seating nipple set at 2942'. Moved out service unit 6-16-83. No further report until additional work performed.

