June 1990) DEPARTM	JNL) STATES MENT OF THE INTERIOR OF LAND MANAGEMENT	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals		5. Lease Designation and Serial No. NMLC 033706A 6. If Indian, Alottee or Tribe Name
		7. If Unit or CA, Agreement Designation
		8. Well Name and Number
WELL - WELL	LI _{OTHER}	FALBY, C. PA- FEDERAL
2. Name of Operator TEXACO EXPLC	RATION & PRODUCTION INC.	3
3. Address and Telephone No. 205 E. Bender, HOBBS, NM 88240 397-0405		9. API Well No.
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Unit Letter F 1980 Feet From The NORTH Line and 1981		30 025 10118 10. Field and Pool, Exploaratory Area DRINKARD
WEST Line Section 8	Township <u>22S</u> Range <u>37E</u>	11. County or Parish, State LEA , NEW MEXICO
2. Check Appropriat	e Box(s) To Indicate Nature of Notice, R	eport, or Other Data
TYPE OF SUBMISSION		YPE OF ACTION
	Abandonment	Change of Plans New Construction
Notice of Intent	Plugging Back	Non-Routine Fracturing
Subsequent Report	Casing Repair	Water Shut-Off
Final Abandonment Notice	Atlering Casing	RES / Dispose Water
		(Note: Report results of multiple completion on Weil Completion or Recompletion Report and Log Form.)
work. If well is directionally drilled, give substitution TEXACO INTENDS TO PULL PRODUCTION ANDRES AND ACIDIZE W/7900 GALS 15% H THE INTENDED PROCEDURE IS AS FOLLO 1. MIRU pulling unit. Install BOP & TOH w/pro 2. MIRU wireline. TIH w/CIBP, set @ 6300'. T 3. TIH w/GR-CBL-CNL. Log from PBTD to 38 4. If cmt is across San Andres interval, then pri Perf 5" csg fr 3930-4020'. Correlate to Lane 5. TIH w/packer. Set packer below San Andres 6. Release packer & pull up to 3910' & reset packer	xd. eqpt. FIH w/dump bailer. Place 35' cmt on top of CIBP for new F 00'. occeed w/perforating. TIH w/csg gun w/2 JSPF & 120 deg. Wells Radioactive log date 6-4-51. s perfs. Test Drinkard plug to 500# surface pressure. icker. Load backside, but do not pressure up. ICL & 1.3 ballsealers. Pump job w/max. pressure not to ex	II markers and zones pertinent to this work,)*. PERFORATE 79 NET FEET OF PAY IN THE SAN 'ed OR PUT BACK ON PRODUCTION. PBTD @ 6265'. spiral phasing.
	v	
14. I hereby certify thay the foregoing is read and correct SIGNATURE	Marke, TITLE Engineering Assistant	DATE 12/1/98
SIGNATURE . MEMISE	να/μεEngineering Assistant ise Leake	DATE 12/1/98

Ç.