

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIP
(Other instructions
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

| | | | |
|--|--|--|--|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> | | 7. UNIT AGREEMENT NAME | |
| 2. NAME OF OPERATOR Sun Oil Company | | 8. FARM OR LEASE NAME Elliott B-9 | |
| 3. ADDRESS OF OPERATOR P.O. Box 1861, Midland, Texas 79702 | | 9. WELL NO. X X 3 | |
| 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface Unit Letter <i>CD</i> 660' FNL & 2150 810' FWL | | 10. FIELD AND POOL, OR WILDCAT Drinkard | |
| 14. PERMIT NO. | | 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 9, T-22-S. R-37-E | |
| 15. ELEVATIONS (Show whether DF, RT, GR, etc.) N/A | | 12. COUNTY OR PARISH Lea | |
| | | 13. STATE New Mex. | |

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) Drill out two CIBP & Run Log ☒

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. MIRU workover unit. Load hole with field saltwater. Install BOP's.
2. POOH w/ tbg.
3. GIH w/ 2-7/8" tbg, 10-3-1/2" drill collars & 4-3/4" bit. Drill out CIBP's @ 6445 and 6585'. Clean out hole to 8029'. Circ hole clean.
Note: Be cautious of pressure beneath CIBP's.
4. POOH w/ tbg. and bit. Lay down drill collars.
5. Rig up Schlumberger wireline. Run a Compensated Neutron Log from 3850-8029'.
Note: Use workover unit to run log.
6. GIH w/ tbg and hange off open-ended.
7. RDMO workover unit. NU wellhead.
8. Further instructions will be issued if perforating is warranted.

RECEIVED
FEB 9 1982

OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSOWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Dee Ann Kemp

TITLE Acct. Asst. II

DATE 1-29-82

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED

DATE

MAR 9 1982

JAMES A. GILLHAM
DISTRICT SUPERVISOR

*See Instructions on Reverse Side

RECEIVED

MAR 10 1982

**O.C.D.
HOSES OFFICE**