District Office	Energy, Minerals and Natural Resources Department					orm C-103 evised 1-1-89	
DISTRICT	0	CONSERVAT	TON DIVISIO	N			
P.O. Box 1980, Hobbs, NM 88240	U.		·	VELL API NO.			
DISTRICT II		P.O. Box 2088			42-475-10163		
P.O. Box Drawer DD, Artesia, NM 88210 Santa Fe, New Mexic			ico 87504-2088	5. Indicate Type			
DISTRICT III					STATE	FEE 🔽	
1000 Rio Brazos Rd., Aztec, NM 87	410			6. State Oil / Ga	as Lease No.		
SUNDRY NOTICES AND REPORTS ON WELLS						1	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI					7. Lease Name or Unit Agreement Name		
(FORM C-101) FOR SUCH PROPOSALS.							
	GAS -						
1. Type of Well: WELL VIEL	WELL	OTHER					
2. Name of Operator				8. Well No.			
CHEVRON USA INC 1							
3. Address of Operator 15 SMITH ROAD, MIDLAND, TX 79705					Wildcat		
4. Well Location					ICE SAN ANDRES, SOU	тн	
	600						
Unit Letter A		Feet From The NO	RIH_Line and 660'	Feet From Th	ie EAST Line		
Section 10	Towns	ship22-S	Range <u>37-E</u>	NMPM	LEA_COUN	TY	
10. Elevation (Show whether DF, RKB, RT,GR, etc.) 3381'							
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data							
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:							
PERFORM REMEDIAL WORK	PLUG A	ND ABANDON	REMEDIAL WORK		ALTERING CASING		
	CHANG	E PLANS	COMMENCE DRILLING		PLUG AND ABANDONME		
PULL OR ALTER CASING							
			OTHER:				

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

CHEVRON U.S.A. INTENDS TO FRACTURE STIMULATE THE SAN ANDRES FORMATION IN THE SUBJECT WELL.

THE INTENDED PROCEDURE AND THE CURRENT WELLBORE DIAGRAM IS ATTACHED FOR APPROVAL.

2

I hereby certify that the information above is grue and co SIGNATURE		Regulatory Specialist	DATE - 2(27/05-00- Telephone No 915-687-7375
TYPE OR PRINT NAME	Denise Leake		Telephone No. 915-687-7375
(This space for State Use) APPROVED BUNDITIONS OF APPROVAL, IF ANY:	TITLE	NULLY FROMEER	APR 0 2 2002 DATEDATEDeSolo/Nichois 12:93 ver 1.0

## Eaves # 1 Eunice; San Andres, South Field T22S, R37E, Section 10 Job: <u>Frac Stimulate San Andres Formation</u>

## **Procedure:**

- MI & RU pulling unit. Bleed pressure from well, if any. Pump down csg with 2% KCl water containing 2 GPT BJ Inflo 150 fluorosurfactant, if necessary to kill well. POH with rods and pump. Remove WH. Install BOP's and test to 1000 psi. <u>Note</u>: All 2% KCl water used is to contain 2 GPT BJ Inflo 150 fluorosurfactant.
- POH with 2 3/8" tbg string. PU and GIH with 3 7/8" MT bit on 2 3/8" work string to TD at 4100'. Reverse circulate well clean from 4100' using 2% KCl water containing 2 GPT BJ Inflo 150 fluorosurfactant. POH with work string and 3 7/8" bit. LD bit.
- 3. Install frac valve and csg saver. Fill 4 <sup>1</sup>/<sub>2</sub>"x 5 <sup>1</sup>/<sub>2</sub>" annulus and pressure to 300 psi, if possible. Observe for communication during frac job.
- 4. MI & RU BJ Services. Frac well down 4 <sup>1</sup>/<sub>2</sub>" casing at **40 BPM** with 56,500 gals of SpectraFrac G4000, 6,000 lbs. 100 mesh White Sand, 91,500 lbs. 16/30 mesh White Sand, and 66,500 lbs resin-coated 16/30 mesh proppant. Observe a maximum surface treating pressure of **4500 psi**. Pump job as follows:

Pump 630 gals 2% KCl water containing 110 gals Baker Petrolite CW-358 scale inhibitor
Pump 6,000 gals SpectraFrac G4000 pad
Pump 6,000 gals SpectraFrac G4000 pad containing 1 PPG 100 mesh White Sand
Pump 3,500 gals SpectraFrac G4000 containing 1 PPG 16/30 mesh White Sand
Pump 5,500 gals SpectraFrac G4000 containing 2 PPG 16/30 mesh White Sand
Pump 6,000 gals SpectraFrac G4000 containing 3 PPG 16/30 mesh White Sand
Pump 6,000 gals SpectraFrac G4000 containing 4 PPG 16/30 mesh White Sand
Pump 7,000 gals SpectraFrac G4000 containing 5 PPG 16/30 mesh White Sand
Pump 7,000 gals SpectraFrac G4000 containing 6 PPG resin-coated 16/30 mesh proppart
Pump 3,500 gals SpectraFrac G4000 containing 7 PPG resin-coated 16/30 mesh proppart

Flush to 3750' with 2,450 gals SpectraFrac G4000. <u>Do not overflush</u>: Shut well in. Record ISIP, 5, 10, and 15 minute SI tbg pressures. Open well and flowback through choke manifold at **1 BPM maximum rate** until square root of time plot indicates that closure has been obtained. SWI. RD & Release BJ Services.

5. Open well and backflow until well cleans up with no frac sand in returns and a stabilized flow rate is obtained. Report recovered fluid volumes, choke sizes and flowing pressures. SWI.

- 6. MI & RU electric line unit. Install lubricator and test to 3000 psi. GIH with sinker bar and tag bottom to check for fill. POH. GIH with gauge ring and junk basket to 3725'. POH. GIH with 4 <sup>1</sup>/<sub>2</sub>" Baker Model "WL" wireline-set retrievable packer and L-10 On-Off Tool (with blanking plug installed) to 3725'. Set pkr at 3725'. POH. RD & release electric line unit.
- 7. PU and GIH w/ top half of on-off tool on 2 3/8" tbg, testing to 5000 psi. Displace annulus with inhibited packer fluid. Re-engage on-off tool. Remove BOP's and install flanged WH rated at 3000 psi WP. Pressure test tbg and WH to 3000 psi. Pressure test casing to 500 psi. GIH and swab fluid level in tubing down until differential across blanking plug is balanced. GIH and retrieve blanking plug from L-10 seal nipple. Swab well if necessary to initiate flow. RD & release pulling unit.
- If well does not flow, PU and GIH with 3 7/8" MT bit on 2 3/8" work string to TD at 4100'. Reverse circulate well clean from 4100' using 2% KCl water containing 2 GPT BJ Inflo 150 fluorosurfactant. POH with work string and 3 7/8" bit. LD bit.
- 9. PU and GIH w/ 4 <sup>1</sup>/<sub>2</sub>" Lok-Set pkr & On-Off tool w/ 1.78" "F" profile on 2 3/8" work string to 3725'. Set pkr at approximately 3725'.
- 10. Open well and backflow or swab as necessary until well cleans up with no frac sand in returns and a stabilized flow rate is obtained. Report recovered fluid volumes, pressures, and/or swabbing fluid levels.
- 11. If well flows, GIH and set tbg plug in "F" profile. Release on-off tool and POH with 2 3/8" work string and top half of on-off tool. Lay down work string. PU and GIH w/ top half of on-off tool on 2 3/8" tbg, testing to 5000 psi. Displace annulus with inhibited packer fluid. Re-engage on-off tool. Remove BOP's and install flanged WH rated at 3000 psi WP. Pressure test tbg and WH to 3000 psi. Pressure test casing to 500 psi. GIH and swab fluid level in tubing down until differential across tbg plug is balanced. GIH and retrieve tbg plug from "F" nipple. Swab well if necessary to initiate flow. RD & release pulling unit.
- 12. If well does not flow, release pkr and POH with 2 3/8" work string. Lay downal and PU and GIH with 3 7/8" MT bit on 2 3/8" work string to TD at 4100'. Reserve circulate well clean from 4100' using 2% KCl water containing 2 GPT BJ Inflo 150 fluorosurfactant. POH with work string and 3 7/8" bit. LD 2 3/8" work string and bit.
- 13. PU and GIH w/ BP mud anchor jt of 2 3/8" tbg, 2 3/8" x 4' perforated sub, SN, 10 jts 2 3/8" EUE 8R J-55 tbg, TAC, and 119 jts 2 3/8" EUE 8R J-55 tbg, testing to 5000 psi. Set TAC at 3700' with EOT at 4035' and SN at 4000'.
- 14. Remove BOP's and install WH. GIH with rods, weight bars, and pump per ALS recommended design. RD & release pulling unit.

15. Turn well over to production. Report producing rates, choke sizes, flowing pressures and/or fluid levels.

, 1

AMH 2/21/02

.



i

Res 'r: San Andres



eaves1.xls