

ALL WORK RECOMMENDATIONS
Proposals for Well Reconditioning and Subsurface Maintenance
Workovers, Expense DD's, PB's, and Conversions

Lease: BRUNSON - ARGO Well No. 17
Field: DRINKARD
County: LEA State: NEW MEXICO

RECOMMENDED PROCEDURE.

1. MOVE IN A PULLING UNIT, PULL THE PERFORATING EQUIPMENT,
AND CLEAN THE WELL OUT TO T.D. OF 6,575'.
2. RUN A GRIND PDM-NEUTRAL-COLLAP LOG FROM T.D. OF
6,575' THROUGH 2400' (PER L.D. RIDER, GEOLOGIST, 6-20-73).
3. SPOT 500 GALS OF 15% NON-EMULSION, HCL ACID IN
THE BOTTOM OF THE HOLE AND PERFORATE THE DRINKARD
FORMATION WITH 4 JET SHOT PER PLANE AS DIRECTED
BY THE GEOLOGIST (L.D. RIDER, MIDLAND, TEXAS, EXT. 338).
4. TREAT EACH ZONE IN THE DRINKARD FORMATION SEPARATELY
AND AS FOLLOWS:

ZONE I (NEW PERFORATIONS)-- ACIDIZE WITH 7,500 GALS OF
15% NON-EMULSION, HCL ACID, TREAT AT 5 TO
7 BRLS/MIN AND USE A SUFFICIENT QUANTITY
OF RUBBER-COVERED NYLON BALL SERIES TO
OBTAIN A COMPLETE BALL-OUT. APPROXIMATELY
24 BALL SERIES WILL BE REQUIRED.

ZONE II (6,400'-6,500'-6,500'-2400' HOLE) - ACIDIZE WITH 5,000 GALS OF
15% NON-EMULSION, HCL ACID, TREAT AT 5 TO 7

6-20-73 JW

Oper. Engr.
Form - 1/73

page. 1 of 2.