

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

2040 South Pacheco
Santa Fe, NM 87505

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.
30-025-10325

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
B-3480

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS)

7. Lease Name or Unit Agreement Name

Cole State

1. Type of Well:

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator

Zia Energy, Inc.

8. Well No.

5

3. Address of Operator

PO Box 2510, Hobbs, NM 88241

9. Pool name or Wildcat

Penrose Skelly

4. Well Location

Unit Letter H | 1980 Feet From The North Line and 660 Feet From The East Line

Section 16 Township 22s Rang. 37e NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3411

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

THE COMMISSION MUST BE NOTIFIED 24
HOURS PRIOR TO THE BEGINNING OF
PLUGGING OPERATIONS FOR THE C-103
TO BE APPROVED.

- 1) POH with production equipment.
- 2) RIH with CIBP and set at 3450'.
- 3) Load hole with 10 ppg brine w/ 25 lbs gel/bbl. Spot 25 sx class 'C' neat at 3450 to 3200'.
- 4) Perforate at 1190' (top of anhydrite), pump a 25 sack plug from 1190' to 1036' (154'). - TAG
- 5) Spot 25 sacks from 276' to 400' (across surface shoe) (124'). Tag cement.
- 6) Spot 10 sacks at surface.
- 7) Cut casing off 3' below surface and weld on dry hole marker.
- 8) Cut off anchors and clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Scott Nelson

TITLE

Engineer

DATE 5/16/00

TYPE OR PRINT NAME

Scott Nelson

393-2937

TELEPHONE NO.

(This space for State Use)

APPROVED BY

E. Gonzalez

TITLE

Ed Lopez

DATE

11-20-01

CONDITIONS OF APPROVAL, IF ANY: