

NO. OF COPIES RECEIVED	
DISTRIBUTION	
DATE	
BY	
S.G.S.	
FIELD OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR APPLICATION TO DRILL OR TO REOPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT TO DRILL OR REOPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.")

OIL WELL ☐ GAS WELL ☐ OTHER ☒ Gas/Gas Dual

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

Name of Operator
Marathon Oil Company

7. Unit Agreement Name

6. Form or Lease Name
J. L. Muncy

Address of Operator
P. O. Box 2409, Hobbs, New Mexico 88240

9. Well No.
1

4. Location of Well
UNIT LETTER P 660 FEET FROM THE East LINE AND 660 FEET FROM
THE South LINE, SECTION 24 TOWNSHIP 22-S RANGE 37-E N.M.P.M.

10. Field and Pool, or Wildcat
Drinkard/Tubb

15. Elevation (Show whether DF, RT, GR, etc.)
3333' KDB

12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☒ Repair gas flow on intermediate casing	CASING TEST AND CEMENT JOB ☐	OTHER ☐

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up pulling unit, kill well, and install BOP's.
2. Pull 2-3/8" production tubing.
3. Set DR Plug in Baker Model "D" packer
4. Run in hole with retrievable bridge plug, 2-7/8" work string and squeeze tool.
5. Set retrievable bridge plug at 5800' and test.
6. Pressure up on 5-1/2" casing to 1500 psi and check for casing leak.
7. If casing leak is found, make necessary repairs (replace or squeeze cement).
8. If no casing leak is found, perforate 5-1/2" casing at 2790', set squeeze tool, break circulation to surface and squeeze cement.
9. Wait on cement, then drill out.
10. Test squeeze and rerun bradenhead survey.

I, Thereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED William P. Holmes

TITLE Petroleum Engineer

DATE 10-7-76

APPROVED BY _____

TITLE _____

DATE OCT 8 1976

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

AUG 8 1976

OIL CONSERVATION COMM.
HOBBS, N. M.