

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Arriba Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	3002510485
5. Indicate Type of Lease	STATE ☐ FEE ☒
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name	J.V. Baker
8. Well No.	10
9. Pool name or Wildcat	Blinebry Oil & Gas

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
Texaco Producing Inc

3. Address of Operator
P.O. Box 730 Hobbs, New Mexico 88240

4. Well Location
Unit Letter A : 660 Feet From The North Line and 330 Feet From The East Line

Section 27 Township 22S Range 37E NMPM Lea County
10. Elevation (Show whether M.F., RKB, RT, GR, etc.)
3339' BF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
PLUG AND ABANDON ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	COMMENCE DRILLING OPNS. ☐
CHANGE PLANS ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	CASING TEST AND CEMENT JOB ☐
OTHER: ☐	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1101.

- | | |
|--|--|
| 1. MURU pulling unit. TOH w/rods and pump. Install BOP. TOH w/2-3/8" tbg. | 7. Load hole full of 9.5 ppg mud. TOH w/tbg. |
| 2. TIR w/svage on tbg. Svage out collapsed csg. TOH w/tbg and svage. | 8. Test for freepoint on 5-1/2" csg. Cut and pull 5-1/2" csg. (On 3/75, found bad csg @ 4924'-4926'. Squeezed w/450 sxs cmt and found top of cmt @ 2710' by temp. survey.) |
| 3. TIR w/tbg. Spot 100' cmt plug (approx. 12 sxs of Class 'H' cmt w/2% CaCl, 5.2 gal water/sack, 15.6 ppg, 1.18 cu.ft/sack) from 5550'-5450'. | 9. TIR w/tbg and spot 100' cmt plug across 8-5/8" shoe from 2750'-2650'. (If top of 5-1/2" csg is near 8-5/8" shoe, will want to spot 50' inside 5-1/2" csg and bring plug up to 2650'.) |
| 4. TOH w/tbg. | 10. Pull tbg uphole. Spot 100' cmt plug across top of salt @ 1165'-1265' (approx 30 sxs Class 'H' cmt w/2% CaCl, 5.2 gal water/sack, 15.6 ppg, 1.18 cu.ft/sack). |
| 5. TIR w/5-1/2" pkr on WS. Locate top of bad csg by setting pkr and pressuring backside. TOH w/tbg and pkr. | 11. Spot 10' cmt plug at surface. |
| 6. TIR w/tbg. Spot 200' cmt plug w/bottom of plug 50' below top of bad csg (approx 25 sxs Class 'H' cmt w/2% CaCl, 5.2 gal water/sack, 15.6 ppg, 1.18 cu.ft/sack). | 12. Cut off well head, install dry hole marker. Clean location. |

(over)

I hereby certify that the information above is true and accurate to the best of my knowledge and belief.

SIGNATURE L.W. Johnson TITLE Engr. Asst. DATE 10-1-90

TYPE OR PRINT NAME L.W. Johnson TELEPHONE NO. (505) 426

(This space for State Use)

APPROVED BY Paul J. Geologist TITLE Geologist DATE

CONTINUATION APPROVAL, IF ANY:

