

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-10519
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name State M
8. Well No. 9
9. Pool name or Wildcat Langlie Mattix
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3425 DF

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator GP II Energy, Inc.
3. Address of Operator P. O. Box 59682, Midland, Tx. 79710	4. Well Location Unit Letter M : 660 Feet From The South Line and 660 Feet From The West Line Section 30 Township 22 S Range 37 E NMPM Lea County
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Re-enter inside casing ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

03-26-96 - 04-12-96

MIRU. Remove pipe from casing. RU reverse unit. Drill out inside 4 1/2" plugging marker w/ 3 7/8" blade bit. Dig out cellar around 8 5/8" casing to 17'. Cut 8 5/8" & 5 1/2" to remove cemented plug marker. Replace 8 5/8" & 5 1/2". Install 8 5/8" well head. Set slips & pack off. Install 5 1/2" well head. Cover up cellar. Install BOP. RIH w/new 4 3/4" rock bit. Ream out 5 1/2" from surface to 115'. Drill out cement. Plug #1 fell out @ 450'. Circulate clean. Drill out CIBP @ 2978'. Chase to 3582'. Drill loose @ 3697'. Plug fell, ran bit to 3775'. Displace hole w/2% KCL. RIH w/bit & scraper. Run scraper to 3735'. RU loggers. Set RBP. Perf: 3502'-3511', 3514'-3521', 3523'-3533', 3535'-3542', 3544'-3546', 3547'-3554', 3559'-3561', 3568'-3580', 3583'-3601', 3605'-3611', 3619'-3646', 3651'-3661', 3688'-3699'. RIH w/5 1/2" PPI tool. Acidize perms w/8000 gals acid. RIH w/pkr & 118 jts. Set pkr. @ 3710'. Acidize open hole to 3936' w/4500 gals 7 1/2% NeFe. ND BOP & flange. Close well in w/sub & bull plug & pack off.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE George P. Mitchell, II TITLE President DATE 4-15-96
TYPE OR PRINT NAME George P. Mitchell, II TELEPHONE NO. 915 684-4748

(This space for State Use)

ORIGINAL SIGNED BY CHRIS WILLIAMS
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE AUG 16 1996

CONDITIONS OF APPROVAL, IF ANY: