Anadar o Productio	on Company	T. O. May
3. Address of Operator  BOX 306. Eunice. N	New Mexico 88231	9. Well No.
4. Location of Well		10. Field and Pool, or Wildcat
	34 22S 37E	ROM TIPM.
	15. Elevation (Show whether DF, RT, GR, etc.) 3329 'GR	12. County
16. Check	Appropriate Box To Indicate Nature of Notice, Report or	Other Data
		ENT REPORT OF:
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING	PLUG AND ABANDON REMEDIAL WORK  COMMENCE DRILLING OPNS.  CHANGE PLANS CASING TEST AND CEMENT JQB	ALTERING CASING PLUG AND ABANDONMENT X
OTHER	OTHER	
	OTHER  Operations (Clearly state all pertinent details, and give pertinent dates, included)	ling estimated date of starting any proposed
17. Describe Proposed or Completed C	corrections (Clearly state all pertinent details, and give pertinent dates, included and include	stalled BOP.  ss C cmt. Circulated  O# for 30. min.  s C w/2% Cacl.  cmt. plug.  aliper & Temp. Sur. Logs  Halliburton light w/10%  s Halliburton light.
17. Describe Proposed or Completed C	corrections (Clearly state all pertinent details, and give pertinent dates, included and include	stalled BOP.  ss C cmt. Circulated  O# for 30. min.  s C w/2% Cacl.  cmt. plug.  aliper & Temp. Sur. Logs  Halliburton light w/10%  s Halliburton light.

## Contd. T.O. May P&A

- 12. RDPU Wainting on csg. puller 12-11-74
- 13. 3-4-75 RUPU Pulled 7" csg. into @ 1702' left 311 7 in hole.
- 14. Ran tub ng to 1900' and pumped 350 s's Halliberton light w/18% salt. Pulled tubing.
- 15. Ran tubing & found cmt. @ 50' cut off surface csg. 5' below ground level. Loaded hole w/cmt. & installed dry hole mar er. RDPU.
- 16. Cut off dead man. Covered workover pits & leveled location.
- 17. Well Plugged and Abandoned on 3-6-75.