Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I

OIL CONSERVATION DIVISION

P.O. Box 1980, Hobbs, NM 88240	P.O. Box 2088		WELL API NO.
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico 87504-2088		5. Indicate Type of Lease STATE X FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410		6. State Oil & Gas Lease No. B-01167	
SUNDRY NOTICES AND REPORTS ON WELLS			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name
1. Type of Well:		Shell "B" State	
OIL GAS WELL X	OTHER		
2. Name of Operator			8. Well No.
Maralo, Inc.			1
3. Address of Operator	T 70700		9. Pool name or Wildcat
P.O. Box 832, Midland,	Texas /9/02		Jalmat(Gas)
Unit Letter K : 1980 F	eet From The South	Line and 1980	Feet From The <u>West</u> Line
Section 16 T	Cownship 23-S Ra	unge 36-E	NMPM Lea County
	10. Elevation (Show whether 3448		
11. Check Appr	opriate Box to Indicate	Nature of Notice. R	eport, or Other Data
			SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON X	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT	
PULL OR ALTER CASING CASING TEST AND CE		MENT JOB	
OTHER:		OTHER:	
 Describe Proposed or Completed Operations (C work) SEE RULE 1103. 	Clearly state all pertinent details, as	nd give pertinent dates, inclu	ding estimated date of starting any proposed
1. Notify NMOCC prior to	heginning plugging	procedure	
2. RUPU.			
3. TIH w/guage ring & junk basket on slick line to insure csg clear to perforations.			
4. TIH w/5 1/2" CIBP and set @ ± 3450'. Cap w/35' cement. 5. TIH w/tbg open-ended to PBTD. Circulate hole w/10#/gal mud-laden fluid.			
out perfs and leaving 15 sx inside csg. 7. Perf 4 squeeze holes in 5 $1/2$ " csg @ \pm 350'. Pump 40 sx down thg displacing 25 sx out			
7. Perf 4 squeeze holes in 5 1/2" csg @# 350'. Pump 40 sx down the displacing 25 sx out perfs and leaving 15 sx inside csg.			
3. Spot 10 sx plug @ surface.			
9. Remove wellhead, cut off csg and weld plate on csg.			
10. Clean up location.			
11. Place metal dry hole marker at location.			
I hereby certify that the information above is true and con	•		DATE 2-20-91
	it mor	LEREILC	DATE 2-20-91
TYPEOR PRINT NAME Brenda Coffma	an		TELEPHONE NO. 915 684-744

_ DATE _ ... TITLE -

CONDITIONS OF APPROVAL, IF ANY: