

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRI-DATE\*  
(Other instructions on re-  
verse side)Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-032104

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

NONE

7. UNIT AGREEMENT NAME

NONE

8. FARM OR LEASE NAME

A. H. Blinebry NCT-1

9. WELL NO.

10

10. FIELD AND POOL, OR WILDCAT

Blinebry

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 20, T-22-S, R-38-E

12. COUNTY OR PARISH

Lea

13. STATE

N. M.

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

1.

OIL ☒ GAS ☐ OTHER ☐  
WELL WELL

2. NAME OF OPERATOR

TEXACO Inc.

3. ADDRESS OF OPERATOR

P. O. Box 728 - Hobbs, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)

At surface

Well located 660' from the North Line, and 660' from the  
West Line of Section 20, T-22-S, R-38-E, Lea County, N. M.

14. PERMIT NO.

Regular

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3387' (D. F.)

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐

(Other) Re-Complete in Wildcat (San Andres) Pool

PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON\* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT\* ☐(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-  
nent to this work.)\*

We propose to abandon the Blinebry Pool &amp; Re-complete in the Wildcat (San Andres) Pool.

1. Set CIBP at 5420', and dump 10' of hydromite on top of plug. Perforate 5 1/2" casing with two jet shots at 4290', 4300', 4318', 4338', 4373', 4390', 4412', 4448', 4467', 4485', 4528', 4553', 4581', and 4615'.

2. Set retrievable bridge plug at 4640', and spot 250 gals 15% NE acid, acidize with 500 gals 15% NE acid in two stages with 14 ball sealers between stages. If necessary use additional acid.

3. If no show, additional perforations of two jet shots at 4091', 4110', 4142', 4157', 4170', 4200', 4230', &amp; 4260'.

4. Acidize with 500 gals 15% NE in two equal stages with eight ball sealers between stages. If necessary use additional acid.

5. Swab well, recover load, Test, and place well on production.

**CONDITION:** The setting of a bridge plug does not constitute permanent abandonment of the lower perforations. Should conditions warrant at the time of permanent abandonment the bridge plug must be drilled out and cement placed across all perforations.

18. I hereby certify that the foregoing is true and correct

SIGNED

Dan Gillett

TITLE

Assistant District

DATE

August 29, 1966

(This space for Federal or State office use)

Superintendent

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED  
As Amended  
AUG 30 1966  
R. B. Brown  
DISTRICT ENGINEER

\*See Instructions on Reverse Side