

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease  
State ☐ Fee ☒  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Gulf Oil Corporation	8. Farm or Lease Name Scarborough Estate
3. Address of Operator P. O. Box 670, Hobbs, NM 88240	9. Well No. 4
4. Location of Well UNIT LETTER <u>F</u> , <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>31</u> TOWNSHIP <u>22S</u> RANGE <u>38E</u> NMPM.	10. Field and Pool, or Wildcat Brunson Abo South
15. Elevation (Show whether DF, RT, GR, etc.) 3324' GL	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <u>P&amp;A Tubb</u> <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

POH with rods, pump and tubing. Set RBP at 6500', test tubing 3000#, test RBP 1000#. Drop 10' sand on RBP. Spot 300 gals 15% HCL 6204'-5940'. Set cement retainer at 5870'. Test tubing 3000#. Pump 250 sacks Class "C" with Halad 9 and squeeze to 700#. Dump 4 sacks cement on retainer. WOC. Drill out cement and retainer and test squeeze 500#. Circulate sand off RBP and POH. RIH with 2-7/8" tubing and packer to 6600'. Frac as necessary.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED James H. Howard TITLE Area Engineer DATE 6-20-83

ORIGINAL SIGNED BY JAMES H. HOWARD

APPROVED BY DISK TITLE DISK DATE DISK

CONDITIONS OF APPROVAL, IF ANY: