

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-101
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator Gulf Oil Corporation	8. Farm or Lease Name Scarborough Estate
3. Address of Operator P. O. Box 670, Hobbs, NM 88240	9. Well No. 4
4. Location of Well UNIT LETTER <u>F</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>31</u> TOWNSHIP <u>22S</u> RANGE <u>38E</u> NMPM.	10. Field and Pool, or Wildcat Tubb
15. Elevation (Show whether DF, RT, GR, etc.) 3324' GL	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
		OTHER <u>P&A Blinebry, Single in Tubb</u> <input checked="" type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

POH with rods and pump. Tubing stuck at 5320', hot water tubing with GKF. GIH with string shot and shoot at 5260'. Clean out scale to 5434'. Cut tubing at 5798', POH with tubing. Set RBP at 5600', test 500#. Pump into Blinebry perfs. Dump 2 sacks sand on RBP. Set cement retainer at 5312'. Pumped 166 sacks Class "C" with Halad 9. Drill out cement retainer and cement. Washed sand off RBP and POH. Circulate hole clean. GIH with tubing, perf sub, SN; set at 6207'. Ran rods and pump; spaced out and hung on. Complete after P&A Blinebry to pump Tubb as single completion 5-2-83. Pumped 69 MCFPD, no gauge on fluid.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R. D. Prite TITLE Area Engineer DATE 5-6-83

APPROVED BY ORIGINAL SIGNED BY JERRY SEXTON TITLE DISTRICT 1 SUPERVISOR DATE MAY 9 1983
CONDITIONS OF APPROVAL, IF ANY: